EXHIBIT H

Page 1

IN THE UNITED STATES DISTRICT COURT FOR THE NORTHERN DISTRICT OF TEXAS DALLAS DIVISION

CAMBRIDGE CONSULTING GROUP, S
INC., S
Plaintiff, S Civil Action No. S 3:11-CV-00306-O
S
-V- S
BANK OF AMERICA, N.A., S

Defendant.

VIDEOTAPE TRIAL DEPOSITION of NON-PARTY WITNESS RANDY KOHANA, taken by Defendant at the offices of Thompson & Knight LLP, 900 Third Avenue, New York, New York, on Monday, October 10, 2011, commencing at 9:35 a.m., before Kimberly Smith, a Shorthand (Stenotype) Reporter and Notary Public within and for the State of New York.

2 (Pages 2 to 5)

				2 (Pages 2 to 5)
	Page	2		Page 4
1	APPEARANCES:	1	1	MR. ANDERSON: Ted Anderson and
2	(Via telephone.)	- 1	2	Bob Goodman for the plaintiff,
3	KILGORE & KILGORE PLLC Attorneys for Plaintiff	- 1	3	Cambridge Consulting.
	3109 Carlisle, Suite 200	- 1	4	THE VIDEOGRAPHER: Our court
4	Dallas, TX 75204	- 1	5	reporter is Kimberly Smith also here
5	BY: THEODORE C. ANDERSON, III, Esq.	- 1	6	in association with Hundt Reporting
6	ROBERT E. GOODMAN, Esq.	- 1	7	will please swear in the witness.
7	FULBRIGHT & JAWORSKI L.L.P.		8	RANDY KOHANA, called as a witness, having
	Attorneys for Defendant	- 1	9	been first duly sworn by Kimberly Smith, a Notary
8	2200 Ross Avenue, Suite 2800 Dallas, TX 75201	1		Public within and for the State of New York, was
9	Dutter, 111,020,	Ë		examined and testified as follows:
1.	BY: THEODORE W. DANIEL, Esq.	Ė		THE VIDEOGRAPHER: Proceed.
10		h		EXAMINATION
1 1	THOMPSON & KNIGHT LLP	- 1		•
12	Attorneys for Witness	ļ		BY MR. DANIEL:
	900 Third Avenue, 20th Floor	þ		Q Good morning, Mr. Kohana.
13 14	New York, NY 10022 BY: GABRIELLE E. FARINA, Esq.	ŀ		A Good morning.
15	· · · · · · · · · · · · · · · · · ·	ŀ		Q Would you state your full name for the
16	ALCO DEFCENT.	1		record, please?
17 18	ALSO PRESENT: James Robert, Legal Videographer	þ		A Randy Kohana.
19	valino robor, 2-8a - robograpio	2		Q And where do you live, Mr. Kohana?
20			1	A I live in New York City.
21		- 1	2	Q Okay. Is that your permanent residence?
23		2		A Yes, it is.
24		- 1	4	Q And do you also office in New York City?
25		2	5	A Yes, I do.
	Page	3		Page 5
1	THE VIDEOGRAPHER: Good		1	Q And what is your residence address?
2	morning. We're going on the record.		2	A 134 West 10th Street.
3	My name is James Robert here in		3	Q And your office address?
4	association with Hundt Reporting, LLC		4	A 270 Lafayette Street.
5	in Dallas, Texas. Today's date is		5	Q Now, you understand that we're here in
6	October 10, 2011. The time is		6	connection with a lawsuit that Cambridge Consulting Group
7	approximately 9:35 a.m.		7	has filed against my client, Bank of America; it's
8	This deposition is being held		8	pending in federal court in Dallas, Texas?
9	in the office of Thompson & Knight		9	A Yes, I do.
10	located at 900 Third Avenue, New York	1	.0	Q And you you have an affiliation with
11	City, New York. The caption of the	1	.1	the landlord of the One Main Place office building in
12	case is Cambridge Consulting Group	1	2	downtown Dallas; is that correct?
13	Incorporated versus Bank of America,	1	.3	A Yes, I do.
14	N.A. in the U.S. District Court,	1	.4	Q What is that affiliation?
15	Northern District of Texas, Dallas	1	.5	A I'm the general partner of the
16	Division, Civil Action No.	1	.6	partnership that owns the property.
17	3:11-CV-00306-0. The name of the	1	.7	Q Okay. And what is the name of that
18	witness is Randy Kohana.	1	8	partnership?
19	At this time the attorneys will	1	. 9	A RAK Main Place Associates L.P.
20	please identify themselves and the	2	0	Q Okay. When did RAK Main Place become the
21	parties they represent.		1	landlord of that property?
22	MR. DANIEL: Ted Daniel for	2	2	A May of 1998.
23	Bank of America.	- 1	23	Q Okay. You bought the property from the
24	MS. FARINA: Gabrielle Farina	- 1	4	prior owner?
25	for Mr. Kohana.	- 1	25	A Correct.
1				

		1	3 (Pages 6 to 9)
	Page 6		Page 8
1	Q Okay. And so RAK Main Street considers	1	form.
2	itself to be the landlord?	2	Q And in connection with your discussions
3	A RAK Main Place Associates.	3	with the bank with respect to a buyout strike that.
4	Q Associates is the landlord with Bank of	4	You did have discussions with the bank
5	America with respect to the floors that Bank of America	5	with respect to a buyout of the lease?
6	leases at the One Main Place building?	6	A Very, very general.
7	A Correct.	7	Q Okay. Did the discussions ever get to a
8	Q Okay. And how many floors does Bank of	8	point where you went to your lender for approval?
9	America have under that lease at this time?	9	A No.
10	A I think 17.	10	MR. ANDERSON: Object to the
11	Q Okay. Are you the sole general partner	11	form.
12	of the landlord?	12	Q What was the first time you spoke with
13	A I'm the sole general partner of the	13	John or David Worrell with respect to the lease, the Bank
14	general partner of the partnership that owns the	14	of America lease?
15	building.	15	A I think it was approximately
16	Q Okay. So any any deals that might be	16	Christmas-time 2008.
17	made with the with the bank, Bank of America, with	17	Q 2008?
18	respect to the lease would have to be approved by you?	18	A I think so.
19	A Yes.	19	Q Okay. And how did you first come into
20	MR. ANDERSON: Object to the	20	contact with the Worrells?
21	form.	21	A They called my company and they were in
22	Q As the sole general partner of the	22	New York and they wanted to meet with us as representing
23	general partner of the landlord would you need approval	23	the bank.
24	from anyone else to consummate an agreement with the bank	24	Q Okay. Mr. Kohana, to speed things up I'm
25	with respect to the lease?	25	just going to ask you to identify a bunch of documents
		1	The state of the s
	Page 7		Page 9
1	A Yes.	1	real quick.
2	MR. ANDERSON: Object to the	2	A Sure.
3	form.	3	Q And then I'm going to ask you a few
4	Q Who would that be?	4	questions about just some of the documents.
5	A It would be the mortgagee of the	5	A Sure.
6	building.	6	(John Worrell's e-mail,
7	Q And the mortgagee is?	7	12/30/09, was marked as Exhibit 1 for
8	A It it was a CMBS transaction. I don't	8	identification, as of this date.)
9	I don't know the name.	9	BY MR. DANIEL:
10	Q Okay. Did you ever communicate with the	μo	Q Let me hand you Exhibit 1 (handing).
11	mortgagee and when you say let's back up. When you	11	MR. ANDERSON: And Ted, what
12	say mortgagee, what do you mean?	12	you're marking as Exhibit 1 is what
1.3	A The bank, the mortgage, the bank that	13	has been marked generally as
14	holds the mortgage.	14	Exhibit 1 or is this Exhibit 1 to the
15	Q So RAK Main Street (sic) Associates has a	15	deposition of Mr. Kohana?
16	loan against the building?	16	MR. DANIEL: It's Exhibit 1 to
17	A Correct.	17	the deposition of Mr. Kohana.
18	Q Okay. And they were written loan	18	MR. ANDERSON: Okay. Is there
19	documents?	19	a Bates number on the document?
20	A Correct.	20	MR. DANIEL: Yes. RAK 000027.
21	Q And your understanding is that under	21	MS. FARINA: Do you have a
22	those documents you would have to get approval with	22	copy?
23	respect to any agreement that you made with the bank?	23	MR. DANIEL: Yeah.
h 4	A 37	h 4	A COLUMN TO THE TAXABLE TO THE TAXAB
24 25	A Yes. MR. ANDERSON: Object to the	24 25	MS. FARINA: Thank you. MR. DANIEL: Ted, it's a

5 (Pages 14 to 17)

			5 (Pages 14 to 17)
-	Page 14		Page 16
1	Q Now, Mr. Kohana, is this your e-mail	1	Q And what's the date on this e-mail?
2	dated March 15, 2010, to John Worrell?	2	A March 19, 2010.
3	A (Perusing document.) You mean the two	3	(David Worrell's e-mail,
4	sentences at the top?	4	3/22/10, was marked as Exhibit 7 for
5	Q Yes.	5	identification, as of this date.)
6	A Yes.	6	BY MR, DANIEL:
7	Q Okay. And you sent this in connection	7	Q Okay. Let me hand you Exhibit 7, sir
8	with the One Main Place roof?	8	(handing). What is Exhibit 7?
9	A Yes.	9	A (Perusing document.) An e-mail from
10	Q Okay. And then you see down below	10	David Worrell to myself.
11	Mr. Worrell sent you an e-mail on March 15, 2010?	11	Q What's the date on this e-mail?
12	A Well, I see that in the page you gave me,	12	A March 22, 2010.
13	yes.	13	(John Worrell's e-mail,
14	Q Okay. Do you recall seeing this e-mail	14	3/22/10, was marked as Exhibit 8
15	from Mr. Worrell?	15	for identification, as of this
16	A Their e-mails all seem the same, I don't	16	date.)
17	remember this one in particular.	17	BY MR. DANIEL:
18	Q Okay.	18	Q Now, let me hand you Exhibit 8 (handing).
19	MR. ANDERSON: Object to the	19	What is Exhibit 8, sir?
20	responsiveness.	20	A (Perusing document.) E-mail from
21	(David Worrell's e-mail,	21	John Worrell to myself and Seth.
22	3/16/10, was marked as Exhibit 5 for	22	Q What's the date on this e-mail?
23	identification, as of this date.)	23	A March 22, 2010.
24	BY MR. DANIEL:	24 25	(John Worrell's e-mail, 3/24/10, was marked as Exhibit 9
25	Q Now, let me hand you Exhibit 5,	25	
	Page 15		Page 17
1	Mr. Kohana (handing).	1	for identification, as of this
2	MR. DANIEL: Ted, this is RAK	2	date.)
3	3.	3	BY MR. DANIEL:
4	Q Mr. Kohana, what is Exhibit 5?	4	Q Let me hand you Exhibit 9, sir (handing).
5	A (Perusing document.) It seems like an	5	What is Exhibit 9?
6	e-mail from Worrell to me threatening me.	6	A (Perusing document.) E-mail from
7	Q From which Worrell?	7	John Worrell to Seth CCing me.
8	MR. ANDERSON: Object to the	8	Q Okay.
9	response object to the	9	MR. ANDERSON: I'm sorry, I
10	responsiveness.	10	didn't catch the date.
11	Q Which Worrell?	11	Q And what's the date on that e-mail?
12	A David Worrell.	12	A March 24, 2010.
h			(Danda II abanda a mail
13	Q And what's the date on this e-mail?	13	(Randy Kohana's e-mail,
14	Q And what's the date on this e-mail?A March 16, 2010.	14	3/25/10, was marked as Exhibit 10
14 15	Q And what's the date on this e-mail?A March 16, 2010.Q Okay. Did you receive this e-mail on or	14 15	3/25/10, was marked as Exhibit 10 for identification, as of this
14 15 16	Q And what's the date on this e-mail? A March 16, 2010. Q Okay. Did you receive this e-mail on or about that date?	14 15 16	3/25/10, was marked as Exhibit 10 for identification, as of this date.)
14 15 16 17	Q And what's the date on this e-mail? A March 16, 2010. Q Okay. Did you receive this e-mail on or about that date? A I don't I don't remember.	14 15 16 17	3/25/10, was marked as Exhibit 10 for identification, as of this date.) BY MR. DANIEL:
14 15 16 17 18	Q And what's the date on this e-mail? A March 16, 2010. Q Okay. Did you receive this e-mail on or about that date? A I don't I don't remember. (John Worrell's e-mail,	14 15 16 17	3/25/10, was marked as Exhibit 10 for identification, as of this date.) BY MR. DANIEL: Q Now, let me hand you Exhibit 10, sir
14 15 16 17 18 19	Q And what's the date on this e-mail? A March 16, 2010. Q Okay. Did you receive this e-mail on or about that date? A I don't I don't remember. (John Worrell's e-mail, 3/19/10, was marked as Exhibit 6 for	14 15 16 17 18 19	3/25/10, was marked as Exhibit 10 for identification, as of this date.) BY MR. DANIEL: Q Now, let me hand you Exhibit 10, sir (handing). What is Exhibit 10?
14 15 16 17 18 19	Q And what's the date on this e-mail? A March 16, 2010. Q Okay. Did you receive this e-mail on or about that date? A I don't I don't remember. (John Worrell's e-mail, 3/19/10, was marked as Exhibit 6 for identification, as of this date.)	14 15 16 17 18 19 20	3/25/10, was marked as Exhibit 10 for identification, as of this date.) BY MR. DANIEL: Q Now, let me hand you Exhibit 10, sir (handing). What is Exhibit 10? A (Perusing document.) I don't know.
14 15 16 17 18 19 20 21	Q And what's the date on this e-mail? A March 16, 2010. Q Okay. Did you receive this e-mail on or about that date? A I don't I don't remember. (John Worrell's e-mail, 3/19/10, was marked as Exhibit 6 for identification, as of this date.) BY MR. DANIEL:	14 15 16 17 18 19 20	3/25/10, was marked as Exhibit 10 for identification, as of this date.) BY MR. DANIEL: Q Now, let me hand you Exhibit 10, sir (handing). What is Exhibit 10? A (Perusing document.) I don't know. Q Do you see the first page of Exhibit 10?
14 15 16 17 18 19 20 21 22	Q And what's the date on this e-mail? A March 16, 2010. Q Okay. Did you receive this e-mail on or about that date? A I don't I don't remember. (John Worrell's e-mail, 3/19/10, was marked as Exhibit 6 for identification, as of this date.) BY MR. DANIEL: Q Okay. Now, let me hand you Exhibit 6,	14 15 16 17 18 19 20 21 22	3/25/10, was marked as Exhibit 10 for identification, as of this date.) BY MR. DANIEL: Q Now, let me hand you Exhibit 10, sir (handing). What is Exhibit 10? A (Perusing document.) I don't know. Q Do you see the first page of Exhibit 10? A It says it's from me to Sudderth on
14 15 16 17 18 19 20 21 22 23	Q And what's the date on this e-mail? A March 16, 2010. Q Okay. Did you receive this e-mail on or about that date? A I don't I don't remember. (John Worrell's e-mail, 3/19/10, was marked as Exhibit 6 for identification, as of this date.) BY MR. DANIEL: Q Okay. Now, let me hand you Exhibit 6, Mr. Kohana (handing). What is Exhibit 6, sir?	14 15 16 17 18 19 20	3/25/10, was marked as Exhibit 10 for identification, as of this date.) BY MR. DANIEL: Q Now, let me hand you Exhibit 10, sir (handing). What is Exhibit 10? A (Perusing document.) I don't know. Q Do you see the first page of Exhibit 10? A It says it's from me to Sudderth on March 25, 2010.
14 15 16 17 18 19 20 21 22	Q And what's the date on this e-mail? A March 16, 2010. Q Okay. Did you receive this e-mail on or about that date? A I don't I don't remember. (John Worrell's e-mail, 3/19/10, was marked as Exhibit 6 for identification, as of this date.) BY MR. DANIEL: Q Okay. Now, let me hand you Exhibit 6, Mr. Kohana (handing). What is Exhibit 6, sir?	14 15 16 17 18 19 20 21 22 23	3/25/10, was marked as Exhibit 10 for identification, as of this date.) BY MR. DANIEL: Q Now, let me hand you Exhibit 10, sir (handing). What is Exhibit 10? A (Perusing document.) I don't know. Q Do you see the first page of Exhibit 10? A It says it's from me to Sudderth on March 25, 2010.

		,	6 (Pages 18 to 21)
	Page 18		Page 20
1	A I guess now looking at it it looks like	1	first page of Exhibit 11?
2	copies of things he asked for.	2	A Correct.
3	Q Okay. Let's let's go through	3	Q Okay. And and there's an attachment
4	Exhibit 10 real quick, Mr. Kohana.	4	to your e-mail of April 6, 2010?
5	A Okay.	5	A Yes.
6	Q On your the cover page to Exhibit 10	6	Q And what is the attachment, sir?
7	is your e-mail of March 25, 2010?	7	A It's a printout of information from
8	A Correct.	8	Cambridge's website.
9	Q Okay. And you've copied David Worrell?	9	O And what's the first what's the first
10	A Yes.	10	attachment there, sir?
11	Q Okay. And then it looks like there's	11	A Oh, a letter to Dave.
12	several attachments?	12	Q Okay. And this is your letter of
13	A Yes.	13	April 6, 2010, to Mr. Sudderth?
14	Q Okay. And let's look at the first	14	A Yes.
15	attachment, sir. The first attachment is what?	15	Q And is that your signature on the letter?
16	A It seems like a letter I sent Sudderth	16	A Yes, it is.
17	March 24, 2010.	17	Q All right. And then attached to your
18	Q Yes, sir. And did you prepare this	18	April 6th letter is a printout of Cambridge's website?
19	letter?	19	A Yes.
20	A I was involved with the preparation.	20	(David Sudderth's e-mail,
21	Q Okay. Is that your signature on the	21	5/20/10, was marked as Exhibit 12 for
22	March 24th lever March 24, 2010, letter?	22	identification, as of this date.)
23	A Yes, it is.	23	BY MR. DANIEL:
24	Q Okay. And did you copy Mr. David Worrell	24	
25	on your letter?	25	Q Okay. Now, let me hand you Exhibit 12 (handing). What is Exhibit 12?
= -		1	
	Page 19		Page 21
1	A Yes.	1	A (Perusing document.) A letter to
2	Q Okay. Did you put together all of these	2	Sudderth, May 20, 2010.
3	attachments and send these to Mr. Sudderth?	3	Q Is it a letter to Mr. Sudderth or from
4	A I don't remember who particularly did.	4	Mr. Sudderth?
5	Q Okay. But do you agree that you	5	A To him I'm sorry, to me from him.
6	ultimately sent the e-mail with the attachments to	6	Q Yes, sir. And it's dated May 20, 2010?
7	Mr. Sudderth?	7	A Yes.
8	A I don't recollect, but it seems to be.	8	Q And did you receive this letter on or
9	Q Okay.	9	about that date?
μo	MR, ANDERSON: Object to the	μo	A Yes.
11	responsiveness.	11	(Randy Kohana's e-mail,
12	Q Do you have any reason to doubt that you	12	6/10/10, was marked as Exhibit 13 for
13	did that?	13	identification, as of this date.)
ի4	A No.	14	BY MR. DANIEL:
15	Q Okay.	15	Q Okay. Now, let me hand you Exhibit 13
16	(Randy Kohana's	16	(handing). Is Exhibit 13 your June 10, 2010, e-mail to
17	correspondence, 4/6/10, was	17	Mr. Sudderth?
18	marked as Exhibit 11 for	18	A (Perusing document.) Seems to be.
19	identification, as of this date.)	19	Q Okay. Do you have any reason to believe
20	BY MR. DANIEL:	20	it is not?
21	Q Now, let me hand you Exhibit 11,	21	A No.
22	Mr. Kohana (handing). And what is Exhibit 11, sir?	22	(Mr. Worrell's e-mail, 6/10/10,
23	A (Perusing document.) A letter from it	23	was marked as Exhibit 14 for
24 25	seems to be from me to Sudderth, April 6, 2010. Q Okay. And you're looking now at the	24 25	identification, as of this date.) BY MR. DANIEL:

			7 (Fages 30 to 33)
	Page 30		Page 32
1	Q Did I read that correctly?	1	form.
2	A That's correct.	2	A There were many that over time became
3	Q Now, what what did you understand the	3	less and less from their point of view.
4	purpose of this e-mail to be?	4	Q Do you recall in March of 2006 (sic)
5	MR. ANDERSON: Object to the	5	MR. ANDERSON: Object to the
6	form.	6	responsiveness.
7	A A threat that either we work something	7	Q Do you recall in March 2010 what
8	out like giving back the floors or taking a buyout or	8	environmental issues the Worrells were focused on?
9	that it would get out of control in some way.	9	A No, I do not.
10	O And from from December of 2009 when	ho	Q Okay.
11		11	MR, ANDERSON: Object to the
12	you met with the Worrells up through the date of this	12	•
	e-mail tell me what what the Worrells had been telling	1	form.
13	you just in general.	13	Q And at at some point in time did the
14	A That there were environmental negative	14	Worrells focus on a particular environmental issue?
15	environmental conditions in the building that needed to	15	A Yes.
16	be dealt with.	16	Q What was that?
17	Q Had they mentioned a buyout to you at	17	A Potential asbestos issues within the HVAC
18	that point?	18	units.
19	A I don't remember at what point they did.	19	Q And did you investigate that issue?
20	Q Okay. And what was your reaction when	20	A Yes.
21	they told you that there were negative environmental	21	Q And what did you determine?
22	issues in the building?	22	A That there was non-friable mastic in the
23	A We we investigated it.	23	units.
24	Q Okay. And when you say we, who who is	24	Q And did you engage Sigma Consulting to
25	that?	25	help you investigate the asbestos issue raised by the
	Page 31		Page 33
1	A The sort of the management team at my	1	Worrells?
2	company with outside people.	2	A Yes.
3	Q Okay. And who were the outside people?	3	Q Did you tell the Worrells the
4	A Mostly Sigma Consultant.	4	determination that you made with respect to the asbestos
5	Q Okay. And who is Sigma?	5	issues they raised?
6	A They're an environmental consultant.	6	MR, ANDERSON: Object to the
7	Q Where are they located?	7	form.
8	A In Dallas.	8	A Anything we said was in writing.
9	Q And had you worked with Sigma before?	9	Q Now, when you say non-friable mastic,
10	A Yes.	10	what do you mean by that?
11	Q For how long?	11	A I'm not an asbestos expert, my
12	A I don't remember,	12	understanding is that it's like a glue that glues
13	Q Okay. As of March of 2010 had had you	13	something to something.
14	had any problems with Sigma?	14	Q Did you after the Worrells started
15	A No.	15	raising these environmental issues with you, did you
16		16	travel from New York to Dallas to inspect the building?
1.6 1.7	Q Okay. And what what did you what what did you and your team conclude with respect to	17	A Yes, I did.
		1.8	
18	the negative environmental issues that the Worrells had	1.8	Q On how many occasions? A I don't remember.
19	been raising?	t t	
20	A We believed there never was an issue or	20	Q Was it more than one?
21	is an issue.	21	A There was one specifically that I
22	Q What specifically were the Worrells	22	remember.
23	focused on in their conversations with you with respect	23	Q Okay. And who and what did you do
24	to negative environmental issues?	24	when you traveled to the building?
25	MR. ANDERSON: Object to the	25	A I reviewed the things that were mostly in

10 (Pages 34 to 37)

		,	10 (Pages 34 to 37)
	Page 34		Page 36
1	their report and pictures that they had given us and to	1	was your reaction to it?
2	see for myself what the what the situation was.	2	A It would have been in a written response.
3	Q And what from what you saw what did	3	Q Well, did you did you respond to it?
4	you determine?	4	I have not I have not seen a response. Do you recall
5	A Well, the only thing that I could point	5	responding to it?
6	to in my mind was there was mold conditions on ceiling	6	A Maybe there was one phone conversation
7	tiles that we believed came from the bank themselves.	7	with David Worrell.
8	Q And why did you believe that mold issues	8	Q What what did you talk about in that
9	came from the bank?	9	phone conversation?
10		10	A He was talking about a buyout of the
11	· · · · · · · · · · · · · · · · · · ·	11	lease.
12		12	Q What did you tell him?
13		13	A We're not interested in a buyout of the
14		14	lease.
15		15	Q Did that ever change, sir, in your
16		16	discussions with the Worrells?
1			
17	March 22, 2010, e-mail to you; do you see that, sir?	17	* * * * * * * * * * * * * * * * * * * *
18	A Yes.	18	Q And why weren't you interested in a
19	Q And the subject on this e-mail is	19	buyout of the lease?
20	resolution offer; do you see that?	20	A Because, one, we believed we never did
21	•	21	anything wrong in the building; and two, they had a
22	Q And were you surprised when you got this	22	lease, we wanted to hold them to it.
23	e-mail from Mr. David Worrell?	23	Q Did you did you tell that to the
24	A Never surprised when I got an e-mail from	24	Worrells?
25	any of the Worrells.	25	A Yes, I did.
	Page 35		Page 37
1	Q And why do you say that, sir?	1	Q And what did what was what was
2	A The abusive nature of their bullying of	2	their response when you said that to them?
3	us on this issue.	3	A I don't remember.
4	Q And prior prior to March 22, 2010,	4	Q Now, do you see from the resolution offer
5	when Mr. Worrell sent you his resolution offer, describe	5	that you got from Mr. Worrell that he's only talking
6	the bullying efforts.	6	about six of the 17 floors?
7	A They're all in the e-mails.	7	A Yes.
8	Q Can you just generally describe them for	8	MR. ANDERSON: Object to the
9	me, sir?	9	form.
10	A One of threats.	10	Q Did did David Worrell ever tell you
11	MR. ANDERSON: Object to the	11	why the offer was limited to six floors?
12	form of the question. Object to the	12	A Yes.
13	responsiveness.	13	Q What was what did he tell you in that
14	Q And what kind of threats were they making	14	regard?
15	to you as of March 22, 2010?	15	A These were six floors the bank no longer
16	A I I don't remember specific dates to	16	occupied nor needed to continue their operations of their
17	as of their threats.	17	space.
18	Q Do you remember the substance of the	18	Q Do you recall how much rent remained as
19	threats?	19	to those six floors when you got the resolution offer on
20	A Basically two levels, one was that it	20	March 22, 2010?
21	would be out of their hands and the bank would take over	21	A No, I don't remember.
22	and do whatever or two, to go to regulatory Texas	22	Q Okay. Okay. Now, take take a look at
23	regulatory commissions and make complaints.	23	Exhibit 10, Mr. Kohana, and I want to I want to focus
1	Q Okay. When you got this resolution offer	23 24	you on your the letter, your March 24, 2010, letter;
24	from David Worrell that we've marked as Exhibit 7, what	25	do you see that?
25			

11 (Pages 38 to 41)

			11 (Pages 38 to 41)
	Page 38		Page 40
ı	A Yes.	1	speak, to some governmental authority.
2	Q Now, in your let me get you to look	2	Q All right. And what was your reaction to
3	down at your fourth paragraph starting with "Since CRC	3	that?
4	was commissioned by the bank." Do you see that?	4	A We didn't do anything wrong.
5	A Yes, I do.	5	Q Okay. Did the Worrells ever report you
6	Q And you say in this letter, "we have	6	to the governmental authorities?
7	endured outrageous claims and comments to our building,	7	A Not to my understanding.
8	reputation, procedures, operations and past service to	8	Q Did the government authorities ever come
9	the bank."	9	to you and ask to inspect your building?
1.0	A Correct.	10	A No.
11	Q Did you believe that was a true	11	Q And that's true as of today, is it not?
12	statement?	12	A That is true.
13	A Yes.	13	Q And are you are you aware of anybody
14	Q And what outrageous claims and comments	14	at the building getting sick from asbestos?
15	-	15	A Not that I'm aware of.
16		16	Q And did the Worrells ever provide you
17	· · · · · · · · · · · · · · · · · · ·	17	with any evidence that anybody on one of the bank's
18	_	18	floors at One Main Place had gotten sick as a result of
19	•	19	asbestos
20		20	A No.
21		21	Q or mold?
22	•	22	A No.
23	· · · · · · · · · · · · · · · · · · ·	23	Q Now, at the end of your that fourth
24	A It I don't remember exactly but it was	24	paragraph in your March 24, 2010, letter you say, "We do
25	· · · · · · · · · · · · · · · · · · ·	25	not want to entertain a buyout of the lease."
	Page 39		Page 41
1	Q Okay. And then you say in that fourth	1	A Yes:
2	paragraph of your March 24, 2010, letter that "It is	2	Q And was that the landlord's position as
3	obvious through telephone calls and e-mails see	3	of March 24, 2010?
4	attached that the modus operandi of CRC was to create	4	A Yes, it was.
5	an atmosphere of fear, litigation, government	5	Q And did that position ever change?
6	intervention and a threat of early lease termination in	6	A No, it did not.
7	2014 as a way to force a buyout of your six-floor	7	Q And then in your March 24th letter you
8	obligation and then provide us with a clean estoppel."	8	you go through various issues and address those issues,
9	Do you see that?	9	do you not?
10		10	A Yes.
11	•	11	Q And the first thing you address is
12	· · · · · · · · · · · · · · · · · · ·	12	asbestos?
13		13	A Yes.
14	•	14	Q And do you see at the bottom of Page 1 of
15		15	your March 24, 2000 (sic) letter where you refer to the
16	·	16	allegations of non-compliance with OSHA requirements
17	· · · · · · · · · · · · · · · · · · ·	17	regarding asbestos as among other fallacious comments?
18		18	MR. ANDERSON: I'm sorry, Ted,
19	•	19	you're talking about the bottom of
20		20	the letter dated March 24, 2010?
21	- · · · · · · · · · · · · · · · · · · ·	21	MR. DANIEL: Yes.
22		22	MR. ANDERSON: Okay.
23		23	A Please repeat the question.
24		24	Q You see where you refer to the
		25	accusations with respect to non-compliance with OSHA
25			weensurious man respect to non-compliance with Coli/\

12 (Pages 42 to 45)

			12 (Pages 42 to 45)
	Page 42		Page 44
1	requirements, it says "among other fallacious comments"?	1	from you at the One Main Place building?
2	A Yes.	2	A No.
3	Q Did you believe that to be true?	3	Q Now, let me direct your attention to the
4	A Yes, I did.	4	second paragraph of your April 6, 2010, letter. You say,
5	Q As of March 24, 2010?	5	"David Worrell called me a few weeks ago with a proposal
6	A Yes, I did.	6	to buy out your unused office space. As we were
7	Q Okay. And then you also address HVAC	7	discussing the situation, among other comments, he said
8	maintenance issues raised?	8	all my brother wants to do is make a lot of money on
9	A Yes.	9	this." Do you see that?
10	Q And roof leak issues raised?	10	A Yes.
11	A Yes.	11	Q Did he say that?
12	Q Leaks in general raised?	12	A Yes, he did.
13	A Yes.	13	Q And what did you understand he was
14	Q Work orders raised?	14	referring or who did you understand he was referring
15	A Yes.	15	to when he said my brother?
16	Q And lighting and safety issues?	16	A John Worrell.
17	A Yes.	1.7	Q Now, go over to the next page, will you
18	Q And those were all issues that the	18	please, sir.
19	Worrells had raised with you?	19	A Okay.
20	A Yes.	20	Q The second paragraph
21	Q You conclude your March 24th letter by	21	A Yes.
22	saying that "Mr. Schochet and I are more than willing to	22	Q you see where you say, "Additionally,
23	come to Dallas to meet with you to go over any open or	23	John Worrell in conversations with my employees has
24	to-be-discussed issues."	24	spoken about me in a most disparaging fashion as well as
25	A Correct.	25	to my general manager"?
	Page 43	 	Page 45
	-		
1	Q Did you did you ever do that, sir?] 1	A Yes.
2	A No.	2	Q Is that the same issue we we discussed
3	Q Did Mr. Sudderth ever ask you to come to	3	earlier today?
4	Dallas and go over the issues?	4	A Correct.
5	A No.	5	Q Okay. Now, did you believe that the
6	Q Now, you copied David Worrell on your	6	Worrells were acting in a professional manner with you
7	March 24, 2010 e,-mail; do you see that?	7	MR. ANDERSON: Object to the
8	A Yes.	8	form.
9	Q Did you ever get get a response to Mr.	9	Q as of April 6, 2010?
10	I'm sorry, from Mr. Worrell to this letter?	10	A No.
11	A I don't recollect that.	11	MR. ANDERSON: Object to the
12	Q Okay. And why did you copy David Worrell	12	form.
13	on your letter?	13	Q And why is that?
14	A So he was aware of the response I had	14	A Speaking negatively about me to a
15	made to the bank.	15	employee of mine for one.
16	Q Okay. Did John Worrell ever call you up	16	Q Okay. Can you think of any anything
17	and respond to your March 24, 2010, letter?	17	else?
18	A No.	18	A No. The harassment of the letters.
19	Q Now, let's look at Exhibit 11, sir. You	19	Q Okay. The letters that we have
20	can put Exhibit that one away. Now, Exhibit 11 is	20	A The e-mails, letters.
21	your April 6, 2010, letter to Mr. Sudderth; is that	21	Q Okay. All right. Now, in your next
22	correct?	22	paragraph, the third paragraph, on Page 2 of your
23	A Yes.	23	April 6, 2010, letter you say, "Dave, we have had a good
24	Q Did did the Worrells ever suggest a buyout on all of the floors that the bank was leasing	24 25	and professional landlord-tenant relationship for 12 years without any of the issues that have arisen
25			

13 (Pages 46 to 49)

			13 (Pages 46 to 49)
	Page 46		Page 48
1	recently." Was that true?	1	Q Is there can you think of any
2	A That is true.	2	circumstance under which you would have agreed to a
3	Q And then you say, "At this point as	3	buyout?
4	landlord we will not have any more contact with the	4	MR. ANDERSON: Object to the
5	Worrells."	5	form.
6	A Yes.	6	A The only discussion we had was if the
7	Q And that was your direction to	7	bank paid us 99 percent of the money that they owed us
8	Mr. Sudderth?	8	under the lease term and only then under that
9	A Yes.	9	circumstance would we consider doing it and if then, we'd
10	Q And did you have any contact with the	10	have to go to the loan the person who has the mortgage
11	Worrells after your April 6, 2010, letter?	11	on the building to ask them what they would like to do.
12	A No.	12	Q Now, you conclude your April 6, 2010,
13	Q Now, do you recall that they continued to	1.3	letter by saying, "In summary, we're going to look to the
14	· · · · · · · · · · · · · · · · · · ·	14	lease between us and follow it completely no more, no
15		15	less."
16	Q Okay. But you do not believe you had any	16	A Correct.
17	direct communications to the Worrells after April 6,	17	Q Do you see that?
18	2010?	18	A Correct.
19	A No.	19	Q Was that always your position, sir?
20	Q Is that correct?	20	A Always.
21	`	21	Q When the Worrells contacted your lender,
22		22	what was your reaction to that?
23	,	23	A Anger.
24	,,	24	Q And why were you angry?
25		25	A They had no right to do that.
	Page 47		Page 49
,		١,	•
1	A Yes.	1 2	Q Are you familiar with the termination option under the lease?
2	Q And then you then you conclude by	3	A Somewhat.
3	saying, "We will be happy to communicate directly with Bank of America employees." Is that correct?	4	
4 -	A That's correct.	5	Q And does it does it a what do you understand about the termination option?
5		6	A I know they have one
6	Q Now, why why did you direct	7	MR. ANDERSON: Object to the
7	Mr. Sudderth that the Worrells were not to contact any of	8	•
8	your people via e-mail, regular mail and/or telephone as	9	form.
9	of April 6, 2010? A We wanted no further contact with these	1	A I think for a couple of floors at some
10		10	point in time.
11	people.	11	Q Okay. Now, at some point in time did
12	Q And why is that, sir?	12	did the landlord through you agree to an abatement plan
13		13 14	with respect with respect to the One Main Place floors
14	with us over these few months.	15	that the bank occupied or leased?
15 16	Q Okay. Now now, I showed you	16	A Yes.
1	Mr. Worrell's resolution offer of March 22, 2010. A Yes.	l .	Q And when did when did that agreement
17		17	come about?
18	Q We just looked at that. Did you have any	18	A I don't remember.
19	further negotiations with David or John Worrell with	19	Q Could you give approximate it for me,
20	respect to a buyout after you got his resolution offer?	20	sir?
21	A We spoke in general on the telephone.	21	A I think sometime in the springtime of
22	Q Okay. Did you ever agree to a buyout?	22	2010.
23	A No.	23	Q Okay. Do you recall when the abatement
24 25	Q Did you ever even consider a buyout, sir?	24	work actually started?
	A No.	25	A Sometime I think in June of this year, of

14 (Pages 50 to 53)

				14 (Pages 50 to 53)
		Page 50		Page 52
1,	2010.	•	1	
1 2	2010. Q	June of 2010?	2	
3	A	No, I'm sorry. I'm sorry. This year it	3	
4		I think June 2011.	4	•
5	Q Q	2011?	5	
6	Q A	Yes.	6	
7	Q	Okay. Has the abatement work been	7	
8		ed at this time?	8	
9	A	It has now, yes.	9	•
10	Q	It has now?	10	
11	A	Yes.	11	- · · · · · · · · · · · · · · · · · · ·
12	Q	Okay. And who paid for the abatement	12	
13	work?	Okay. And who paid for the abatement	13	
14	WOIK?	The landlord.	14	
15	Q	Your your entity?	15	
16	A	Yes.	16	
17		RAK Main Street Associates?	17	
18	Q A	Main Place Associates, yes.	18	
19		Main Place Associates, yes. Main Place Associates, I'm sorry.	19	•
20	Q	· · · · · · · · · · · · · · · · · · ·	20	<u>-</u>
21	ahatama	And how much did you pay for the out work?	21	•
22	abateme A		22	
23	Q	Could you give me your best judgment on	23	-
24	the amo		24	
25	the amo	MR. ANDERSON: Object to the	25	——————————————————————————————————————
	·		 	
		Page 51		Page 53
1		form.	1	
2	Α	Approximately \$650,000.	2	A None that I know of.
3	Q	Does that \$650,000 include the monies	3	·
4	that you	paid to your consultants?	4	
5	Α	Yes, it does.	5	
6		MR. ANDERSON: Object to the	6	time and time to pay their,
7		form.	7	sir?
8	Q	Okay. Well, tell me what comprises the	8	• • • • • • • • • • • • • • • • • • • •
9		red approximate \$650,000 amount.	9	\
1.0	Α	The abatement and the consultant.	10	,
11	Q	Okay. And who was your consultant?	11	5
12	A	Sigma contract Sigma.	12	
13	Q	And was Sigma involved in coming up with	13	
14	_	e of work for the abatement?	14	
15	A	Yes.	15	
16	Q	Did you defer to Sigma on the scope of	16	
17		the abatement?	17	
18	A	Yes.	18	
19		MR. ANDERSON: Object to the	19	· · · · · · · · · · · · · · · · · · ·
20	^	form.	20	
21	Q	And who who did Sigma work with in	21	• •
22		on with the scope of work on the bank's on the	22	negotiate the scope of work for the abatement?
22			100	A I doubt up call
23	bank's si	de?	23	
			23 24 25	Q Okay. Would you agree that it took

15 (Pages 54 to 57)

			15 (Pages 54 to 57)
	Page 54		Page 56
1	MR. ANDERSON: Object to the	1	Q Mr. Kohana, my name is Ted Anderson. I
2	form.	2	represent the plaintiff in the case, Cambridge
3	A I don't recall.	3	Consulting. I've got some questions that I'd like to ask
4	Q You don't recall, okay.	4	to you, sir. Do you realize that you're still under
5	Now, you testified earlier that you	5	oath, sir?
6	didn't think there were any issues with respect to the	6	A Correct.
7	environmental condition of the One Main Place building?	7	Q Mr. Kohana, did you have an opportunity
8	A Correct.	8	to meet with the attorneys for the bank prior to giving
9	Q And you still believe that today?	9	your deposition today?
10	A Yes, I do.	10	A No.
11	Q Can you can you explain to us, then,	11	Q Okay. Have you ever given your
12	why you ultimately agreed to abate under the under the	12	deposition before, sir?
13	scope of work that was agreed upon?	13	A Yes.
14	A I think that after the continued	14	Q On how many occasions?
15	harassment by the Worrells and the bank we just wanted to	15	A I don't remember. Very few.
16	end the so-called fight. And while we didn't believe	16	Q Have you been did it have anything to
17	that anything within those units were causing an issue,	17	
		ŀ	do with litigation over a landlord-tenant dispute?
18	we decided okay, let's just as part of cleaning the	1.8	A No.
19	units let's get it out of there,	19	Q Okay. I want to pick up on some of the
20	MR. DANIEL: I'll pass the	20	questions that Mr. Daniel asked you and I guess I'm going
21	witness. Thank you, Mr. Kohana.	21	to kind of go in reverse order. It's my understanding,
22	THE WITNESS: I'm going to take	22	sir, that the bank agreed to pay for I'm sorry, strike
23	a break.	23	that,
24	MR. ANDERSON: Okay.	24	The landlord, you, agreed to pay for an
25	THE VIDEOGRAPHER: Off the	25	abatement that you did not think needed to be done; is
	Page 55		Page 57
1	record. 10	1	that correct?
2	MR. ANDERSON: Let's go off the	2	A The landlord yes, in regard to the
3	record and then I want to talk to you	3	landlord; yes.
4	guys about the exhibits that	4	Q Okay. And it is your position that
5	hopefully are there by now.	5	nothing should have been done anyway?
6	THE VIDEOGRAPHER: Off the	6	 A My understanding is nothing needed to be
7	record. 10:43 a.m. This is the end	7	done.
8	of disc one in the deposition of	8	 Q Okay. And was that always your position,
9	Randy Kohana,	9	sir?
10	(Unidentified document was	10	A Yes, it was.
11	marked as Exhibit 20 for	11	Q And is it true, sir, that you would not
12	identification, as of this date.)	12	have incurred that cost at all except for the alleged
13	(Whereupon, at 10:43 o'clock	13	harassment from the Worrells?
14	a.m., a recess was taken to 11:06	14	A I think you need to be more specific than
15	a.m.)	15	that.
16	(The deposition resumed with	16	Q Okay. Well, I I thought that it was
17	all parties present.)	17	your testimony, sir, that because of the harass the
18	THE VIDEOGRAPHER: Going back on	18	alleged harassment from Cambridge Consulting and from the
19	the record at 11:06 a.m. This is the	19	bank the landlord agreed to incur the \$650,000 in costs
20	beginning of disc disc two in the	20	to to abate the premises; is that correct?
21	deposition of Randy Kohana. Okay.	21	A Yes; but the units also needed
22	RANDY KOHANA, resumed and testified further	22	maintenance.
23	as follows:	23	Q So that so you agree that the units
24	EXAMINATION	24	that the units did need maintenance?
25	BY MR. ANDERSON:	25	A I think they needed their normal
<i>U.</i> 2			A MILLION CLUB INDUMENTAL MINISTER CONTRACTOR CONTRA

19 (Pages 70 to 73)

			19 (Pages 70 to 73)
	Page 70		Page 72
1	Q And what is it that made you decide that	1	of Bank of America on or about April 9, 2010?
2	you didn't need an estoppel letter?	2	A I believe so.
3	A Nothing in particular.	3	Q Here it says, "Randy, once again, thank
4	Q Before, Mr. Daniel asked some questions	4	you for your letter. I still expect you to give CRC your
5	about your demand that you no longer have anything any	5	full cooperation as you promised." Is that true?
6	communications with the Worrells; do you recall that,	6	A That was before the letter I sent saying
7	sir?	7	we wouldn't deal with them anymore.
8	A Yes.	8	Q Okay. Let's take a look here. All
9	Q Do you recall whether or not the bank	9	right. Do you have Exhibit 11 there, sir?
10	stated that you you need to continue to work with them	10	A I'll get it. Yes, I do.
11	notwithstanding your demand?	11	Q All right. And if you look this is
12	A There was something said, I don't	12	the April this is dated what date, sir?
13	remember what it was.	13	A April 6th.
14	Q But you do recall that the bank wanted	14	Q Okay. So this is April 6th and do you
15		15	recall Mr. Daniel asked you some questions about the
16	no wanted nothing further to do with them?	16	second-to-last paragraph of the April 6, 2010, letter
17	A I remember something to that effect but	17	from you to David Sudderth?
18	we we never had anything to do with them afterwards.	18	A Yes, I do remember that.
19	Q Okay. So the bank did say that you	19	Q And it says in this April 6, 2010, letter
20	wanted they wanted you to continue to deal with them?	20	that in the second-to-last paragraph, "At this point
21	A The bank said they'd continue to be their	21	as landlord we will not have any more contact with the
22	consultants.	22	Worrells. They are not to contact us or any of our
23	Q Okay. Did they say that they wanted you	23	employees including without limitation via e-mail,
24	to continue to to work with them?	24	regular mail and/or telephone. We will be happy to
25	A I don't remember. It didn't matter, we	25	communicate directly with the Bank of America employees."
	Page 71		Page 73
1_		,	_
1	weren't going to.	1	Do you see that, sir?
2	MR. ANDERSON: Object to the	2	A Yes, I do.
3	responsiveness.	3	Q All right. So does that change your
4	MS. FARINA: No, I believe he	4	testimony as to whether or not you made that request
5	answered your question.	5	prior to or after you received this e-mail from David Sudderth which is Exhibit 21 dated April 9, 2010?
6	MR. ANDERSON: Who's talking?	6	•
7	MS. FARINA: Gabrielle Farina,	7	A Let me be clear, at some point previous
8	his counsel.	9	to April 6th, I don't remember whether it was a letter or
9	(David Sudderth's e-mail,	10	a phone call, I told Dave that I would cooperate with CRC. I never did after the fact so he was I'm sure
10	4/9/10, was previously marked as	11	4
11	Exhibit 21 for identification, as of this date.)	12	what he was alluding to was something that I had discussed pre the April 6th letter.
12	BY MR. ANDERSON:	13	
13		14	Q Right. And then you in your April 6th letter stated in writing that you would have nothing to
14	Q Look at Exhibit what's been marked as	15	do with CRC, right?
15 16	Exhibit 21, sir (handing). A (Perusing document.) Okay.	16	A That's correct.
	· · · · · · · · · · · · · · · · · · ·	17	;
17	MR. DANIEL: What is that? THE WITNESS: 21.	18	Q And then on April the 9th in Exhibit 21 Bank of America stated to you "once again, thank you for
18 19	MR. ANDERSON: It is an e-mail	19	your letter. I still expect you to give CRC your full
20	from David Sudderth to Randy Kohana	20	cooperation as you promised," right?
20 21	dated April the 9th of 2010.	21	A Yes. I see that.
	uateu April the 7th 01 2010.		
	MR DANTEL Obou	22	O And then in the third paragraph of
22	MR. DANIEL: Okay.	22	Q And then in the third paragraph of Exhibit 21 it says "I do not believe we have anything to
22 23	A I see it.	23	Exhibit 21 it says, "I do not believe we have anything to
22	· · · · · · · · · · · · · · · · · · ·	1	

1	CERTIFICATE
2	STATE OF NEW YORK)
3) ss.
4	COUNTY OF NEW YORK)
5	I, KIMBERLY SMITH, a
6	Shorthand (Stenotype) Reporter and
7	Notary Public of the State of New
8	York, do hereby certify that the
9	foregoing Deposition, of the
10	witness, RANDY KOHANA, taken at the
11	time and place aforesaid, is a true
12	and correct transcription of my
13	shorthand notes.
14	I further certify that I am
15	neither counsel for nor related to
16	any party to said action, nor in any
17	wise interested in the result or
18	outcome thereof.
19	IN WITNESS WHEREOF, I have
20	hereunto set my hand this day of
21	October, 2011.
22	the back of the
23	KIMBERIA EMITH
24	KIMBERAL BITTIL

25

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page <u>16</u>

From: Randy Kohana [rkohana@rakgroup.com]
Sent: Thursday, March 25, 2010 1:14 AM

To: david.l.sudderth@bankofamerica.com

Cc: dworrell@att.net

Subject: Bank of America - One Main Place

Attachments: Letter to Bank of America.3.24.10.pdf; OMP - Emails.pdf; OMP Status Letter.pdf; HVAC

Limited Testing report.pdf; OMP- Sigma Certificate of Completion.pdf; BofA Work Orders

10/10/11/65

2009.pdf; Fan Coil Unit Maintenance Procedures.pdf

Dave:

As promised.

Randy

Randy Kohana
Chief Executive Officer
RAK Group LLC
270 Lafayette Street
New York, NY 10012
(212) 245-1601 (Tel)
(212) 245-7001 (Fax)
RKohana@rakgroup.com
www.rakgroup.com

^{*}PLEASE NOTE OUR NEW ADDRESS ABOVE.



VIA E-MAIL AND FEDEX

March 24, 2010

Mr. David L. Sudderth Transaction Director Bank of America Bank of America Corporate Workplace 35 North Greenvine Circle The Woodlands, Texas 77382

Re:

Lease Between RAK Main Place Associates L.P., as successor to RREEF USA Fund-II, as "Landlord" and Bank of America, N.A., as successor to NationsBank of Texas, as "Tenant," dated May 1, 1995, as amended (the "Lease"), for premises located at One Main Place, 1201 Main Street, Dallas, TX (the "Building")

Dear Dave:

We have been the Bank of America ("Bank") Landlord for 12 years now. We have been through two lease extensions (one just over 2 years ago) and have always gone out of our way to keep the Bank happy.

You and I have always had a cordial and professional relationship and I know of no circumstance where we did not come to a professional resolution. As an aside, I will respond to your e-mail of today, tomorrow.

In March 2009, we became aware of the Bank's interest in subleasing three floors and now the Bank is looking to sublet six floors of unneeded space and as such brought in Corporate Risk Consultants ("CRC").

Since CRC was commissioned by the Bank, we have endured outrageous claims and comments to our building reputation, procedures, operations and past service to the Bank. It is obvious through telephone calls and e-mails (see attached) that the modus operandi of CRC was to create an atmosphere of fear, litigation, government intervention, and a threat of early lease termination in 2014 as a way to force a buyout of your six floor obligation and then provide us with a "clean estoppel" while "quickly and quietly" forgetting all the other alleged claims among other comments. We feel this is a form of harassment. We do not want to entertain a buyout of the lease and do not at this time need an estoppel from the Bank. In the event we do, we will request one in accordance with the terms of the Lease.

That all being said we will address all issues raised with a methodical response to all.

Asbestos

We have been accused of not following our O & M procedures and being in non-compliance with OSHA requirements among other fallacious comments (see email dated March 19, 2010). In addition, the IAQ Testing prepared by Maxim Technologies Inc., dated April 18, 2001 which CRC said was not available was and is available for Todd to review (found subsequent to Todd Ratliff's conversation with Seth Schochet but prior to Todd's actual review of any of the environmental reports) and was with the rest of the reports Todd reviewed.

Mr. David L. Sudderth March 24, 2010 Page 2



We have enclosed a letter from Sigma Environmental Solutions, Inc. ("Sigma") which documents all procedures followed pertaining to the Banks ACM abatement procedures per the 11th amendment to lease. We obviously have complied with all federal and state requirements.

In reference to the window HVAC units, which have been commented on quite a bit (See e-mail dated March 19, 2010 "what is going on inside those HVAC units"), there is a friable foam insulation in the enclosed unit. The insulation has been tested by EFI Global (Tenant's contractor) and just recently been retested by Sigma. The results were NEGATIVE for asbestos. There is also mastic and some pipe wrap associated with the HVAC units that are extremely non-friable, poses no health risk and does not need to be removed (see Sigma report). Additionally, the Bank accepted possession of all renovated floors per the asbestos removal done on all now occupied floors (see actual certificates of completion enclosed). I assure you there was not an issue since EFI Global and CBRE did not mention it.

In terms of the "As-Is" language in the 11th amendment regarding the HVAC perimeter units, that was meant to mean that the perimeter units were not to be replaced. If they were to be replaced, the mastic and pipe wrap would have been abated, if necessary, along with putting in the new units. We have always been ready, willing and able to implement all ACM abatement on all non-abated floors per Exhibit B to the 11th amendment to lease. One of the 6 floors the Bank is looking to sublet (31st floor) has already been demolished and the ACM abatement was completed which demonstrates the success of our program.

HVAC Maintenance

It is obvious and agreed that all perimeter HVAC units need to be in good working order and be free of any leaks or mold accumulation. We have a commercially reasonable list of procedures to apply on every unit as serviced (List is attached). If you or your consultants have any questions, comments or additions to that list we would be more than happy to work out a protocol that works for all parties.

We have recently performed maintenance on the perimeter HVAC units on floors 12 & 28 and are currently performing maintenance on the units on the 31st floor with all other floors to follow. The maintenance takes about a week and a half to two weeks per floor to complete. Mike Horstman will coordinate the schedule with the appropriate Bank or CBRE representative. We stopped maintenance on the six unoccupied floors due to imminent demolition pursuant to building plans received by Landlord but we will now include such floors into our routine maintenance.

Roof Leaks

Sometimes upon massive rains there are roof leaks, as with all buildings, sometimes other unforeseen events happen. Each time we respond immediately and fix the problem.

We have inspected the roof and it is in good condition. Recently a water pump broke and there was excess water from a Trane annual inspection of the chiller units. This can happen in any building. We will do our best to minimize these types of occurrences.

Additionally, as a reminder, the Bank commissioned a full MEP and building condition report prior to signing the 11th Amendment to Lease (which we paid for) which was pursuant to section 20 of the 11th amendment to Lease. There were a number of issues discussed and ultimately agreed on that were to be performed and paid for by the Landlord. This included sprinkler work, electrical panel work and ACM abatement. All have been done correctly per the Lease. There was NO mention of roof problems, HVAC maintenance issues or work order non compliance.

Mr. David L. Sudderth March 24, 2010 Page 3



Leaks in General

As you know leaks can happen anytime in any building. We have been accused of causing leaks and having those leaks turn into a mold condition.

While a couple may have been from the outside window line, the majority have been from floors above which coincidentally are the Bank's recently renovated floors. We have now replaced all ceiling tiles on all of the unoccupied floors and have had our environmental consultant, Sigma (see report) inspect for mold. There was NONE found. Additionally, NO leaks have been discovered once the damaged tiles were replaced with the exception of below.

The empty floors had not been walked by Bank personnel for many months and up to a year on some. This is also what has led to some of the problems. In fact, if Mike Horstman hadn't walked the 28th floor yesterday or an engineer on the 7th floor on March 16, 2010, 2 of the floors you are looking to sublet, (see e-mails) a mold condition could have begun because of leaks coming directly from the Bank's spaces. You can speak with Larry Williams of CBRE for confirmation.

Work Orders

Pursuant to the most recent CRC E-mail (March 22, 2010) we have received over 2 calls a day to our management office. While we would like there to be zero this is within the normal range for the size of your tenancy.

Along with the latest threatening "we will terminate the lease in 2014" language we received a spreadsheet along with the e-mail and have responded to each and every line item as we have a record of each complaint and its resolution. In 2009, there was approximately 1 work order per day of which approximately 56% were ordinary day to day issues but a good amount are complaints regarding various other issues such as construction related and after hour calls. We have attached comments specific to each and every complaint. 2008 will follow shortly. I think you will realize that all work orders are acted on and resolved quickly. We are happy to work together to make this normal occurrence the minimum it can be.

Lighting and Safety Issues

The safety of everyone that walks into One Main Place is of paramount importance to us let alone the Bank's employees. To allude to something less is fallacious.

Sometimes ballasts do blow, rarely do they smoke. Either way, they are in compliance with applicable laws in their current condition under the law and do not need to be replaced unless broken. If so we replace with an electronic ballast. Our electrical consultants Schmidt and Stacy have sent us a letter (see attached) to that effect and to the safety of the current lighting fixtures.

In summary, this letter, e-mail writing and voicemails have gotten out of hand so we wanted to answer everything globally with specific backup for each misguided comment made to date. We want to do as we have always done to keep the Bank happy and to do everything possible within the confines of the lease to allow for the enjoyment of your continued occupancy.

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 21 of 122 PageID 607

Mr. David L. Sudderth March 24, 2010 Page 4



I am more than willing to discuss any further issues you might have or need additional backup for. We are committed as always to provide the Bank with the excellent service we have always furnished. Additionally, Seth Schochet and I are more than willing to come to Dallas to meet with you to go over any open or to be discussed issues.

Very truly yours,
RAK MAIN PLACE ASSOCIATES, LP,
a Delaware limited partnership
By: RAK Main Ventures L.P., a Texas
limited partnership, its general partner
By: RAK Ventures Corp., a Texas
corporation, its general partner

Randy Kohana President

cc: David Worrell

Randy Kohana

From: John Worrell [johnw.crc@gmail.com]
Sent: Friday, March 19, 2010 5:59 PM
To: Seth Schochet; Randy Kohana

Subject: OMP Status

Randy/Seth:

BAC's patience is at an end waiting for you to make some effort at addressing these serious and growing problems. To date you've only offered denial in the face of overwhelming evidence as documented by Texas certified inspectors.

I know you are talking with David but I can't stop doing my job. I can't wait to see how your talks go with David and from what I understand they are going nowhere anyway.

My number one issue right now is our concern over the threat of asbestos. Until I get this issue addressed FIRST nothing else can move forward for me.

We still have not received and demand access to all Environmental Reports. The IAQ Testing prepared by Maxim Technologies, Inc. was listed in the lease but Todd didn't receive that report. I assume this is an internal air quality report and thus quite important even though it is quite dated. Also, there is an Asbestos Activity Log, OSHA 29CFR1926.1101(n), as identified in section 6.4.2 of the TERRA-MAR Asbestos Operations & Maintenance Procedures dated 05/30/1997 that we need to review. We also need to see and review the 'Asbestos File' referenced in section 6.4.3 of the same O&M (this is a permanent, active file of detailed documentation concerning asbestos activity). We need immediate access to these documents as our concern was raised because each of the Environmental Reports were qualified by the disclaimer that they were only permitted to conduct 'limited visual surveys' and specifically did not inspect less accessible areas of the building. They also noted in some cases they were not allowed to collect samples of known and suspect ACMs and had to rely on past testing that was also noted as gathered during a 'limited visual survey' so they couldn't validate their findings. In the Phase I Environmental Site Assessment prepared by Eckland Consultants Inc. and dated 02/27/1998, Eckland specifically warned RAK that "OSHA requires untested material to be presumed asbestos containing if the building was constructed before 1981". Finally, in 1997 TERRA-MAR specifically advised RAK that: "TMI recommends a comprehensive building area survey prior to any renovation and or demolition activity to accurately determine the type and extent of ACM."

When we add all this together – our own inspections discovered a great deal of ACM, your 'limited visual surveys' plus specific instruction noted in the reports that your inspectors were not permitted to gather and test known and suspected ACM plus notice from your inspectors that OMP must treat all untested material as presumed ACM given the age of OMP (advice that RAK did not follow) plus the direct recommendation from your inspectors that a comprehensive building area survey be conducted prior to renovation is conducted (again, advice that RAK didn't follow) – I remain unable to sign off on my 'safe to sublease' mandate.

I spoke to Dave Stoddard at the OSHA Texas headquarters in Austin. I did not yet mention company names or the property. He introduced me to Richard Hensley who is the Team Manager Dallas Area for these inspections.

I am in the process of packaging all of our inspection results which will take a few days before I can forward this to OSHA and the inspection can begin. You need to call Richard at 409-899-5589 extension 700 first to set up a time for a comprehensive building area survey. You've maintained from the start OMP is already in total compliance so there is no reason not to do this.

I am currently going through a massive spreadsheet listing every maintenance request on all BAC floors that I am sure you will find revealing as it clearly documents a long and consistent pattern of HVAC, lighting, as well as rain-event related water intrusion issues. I will send you specifics over the weekend.

Randy, to date you've done a lot of talking but not taken any measurable actions I can show BAC as progress. Since you won't help me get these issues resolved my recommendations to BAC are as follows:

- > BAC will exercise the termination option to leave the entire building at the end of 2014.
- > Through 2014, BAC will persistently demand that RAK perform to the highest standards under the lease. If RAK doesn't BAC will do it themselves in a first class manner as per the lease and then deduct the cost from rent also as per the lease. We've already got Brandt scheduled for a follow up behind your current repair and maintenance efforts on the HVAC because there is reasonable concern RAK is going to handle this maintenance in the same shoddy and health hazardous manner as you have in the past and not to a first class level as required by the lease. The necessity to audit all RAK R&M actions going forward through 2014 will become the new normal.
- ➤ BAC is bringing in its full team of inspectors as coordinated by BAC's Environmental Service division to work with OSHA for a full building inspection. We expect your cooperation in gaining access to all floors. As you already know, CBRE is scheduling a roof inspection and we will need an up-to-date internal air quality inspection done right away as the last one (the missing IAQ report) was done in 1997 and the standards have since changed.
- ➤ BAC is legally bound to update a full disclosure in the Estoppel that notes BAC's intent to exercise the full Premises termination option and exit at the end of 2014 due to environmental hazard and health concerns as compounded by the history of RAK negligent maintenance as documented by Texas certified third party inspectors.

David told me you were still in strong disagreement with Todd Ratliff's letters. Let me assure you that Todd writes nothing unless and until it has passed legal's eyes and approval. Any letter RAK has received from Ratliff was blessed by BAC's legal department as defendable. Let me be clear, Todd is not a loose cannon if that's what you are thinking. He has the full backing of BAC legal – both corporate and local. I know because I was a party to those conferences.

We understand your main arguments rest on AS-IS acceptance of the Premises and a presumed intention that BAC would build out these remaining floors to some undefined level. 'Premises' is defined in the lease as net rentable square footage and what is going on inside those HVAC window units is certainly not that, neither in the lease's definition nor according to ANSI-BOMA standards, so while BAC accepted the Premises AS-IS, they did not accept those HVAC units and what is inside them AS-IS. BAC has completed its initial build out efforts on these floors and can contemplate no further work unless and until the asbestos issues are resolved as per TERRA-MAR's advice.

The opportunity to quickly and quietly diffuse this situation in a way that works for everyone before it blows into a broader dispute over OMP as suffering from 'sick building syndrome' is about to evaporate. We're running out of time here.

We expect you to schedule an immediate, building-wide OSHA inspection. If you can't or won't do this then we will.

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 25 of 122 PageID 611

I will call you early next week to schedule access for OSHA and BAC Environmental Services along with our other inspectors to conduct these necessary additional surveys.

Regards,

John

Randy Kohana

From: Sent: David Worrell [dworrell@att.net] Tuesday, March 16, 2010 4:22 PM

To: Subject: Randy Kohana Bank of America

It is imperative we speak as soon as possible. I have till Friday to either work something out with you or BAC's environmental group and attorneys take it over themselves. That outcome is obvious – and it is not 5 years out. It is 5 weeks out.

Cambridge Consulting Group Inc. David Worrell 678-488-2504 678-456-8118 dworrell@att.net

Seth Schochet

From:

John Worrell [johnw.crc@gmail.com]

Sent:

Wednesday, December 30, 2009 1:16 PM

To:

Seth Schochet

Subject:

OMP/BAC

Attachments: 4_100_0677.jpg

Seth,

I appreciate your time this week and your help keeping BAC a happy tenant at OMP - the main goal for both of us.

Here's the gist of what I'm dealing with and the reason for my sense of urgency:

On floors 4, 6, 7, 12, and 28 many of the lighting fixtures are in fact fire hazards because as we did our inspection we would turn on lights and they would sizzle and pop and smoke would pour out. Obviously this scared the heck out of us. At one point I even went down to the security desk to warn them and they were surprisingly indifferent telling me not to worry about it. I can tell you honestly that I do worry about it because any cleaning or security person could accidently start a fire just by turning on a light.

Two places I can pinpoint for you include the 12th floor pantry room and the 28th floor space just outside the back door to the pantry room. The 12th floor blown ballast and smoke is pictured in the book I left with you (pix also attached). On the 28th floor there were at least two fixtures that blew when I turned them on. On every floor we inspected we learned to be careful turning on lights - waiting and listening carefully in case we needed to turn off power fast. We had to turn off power fast on every floor at least once so our concern is that this issue is systemic.

What we need to do is first agree who is responsible for repair and maintenance of the lighting fixtures. I hear you that RAK's expectation (intent was the word you used) was for BAC to build out these floors but we had legal go over the lease, exhibits and amendments and it is clear to us that a) BAC has no obligation or mandate under the lease to build out those floors and b) RAK retains as Landlord the obligation for R&M of the HVAC and lighting, etc. whether or not BAC builds out the spaces. Someone has to be responsible for ongoing R&M and as best we can see it is RAK.

Also - in the original lease section 3b, page 9 states that "All replacement lighting tubes required through normal office usage in Building standard fixtures in the Premises will be furnished and installed by or at the Landlord's expense." Nowhere in any subsequent amendment is this paragraph nullified or replaced so we have to assume it remains in effect. Obviously we wouldn't want you to replace all of the missing and dead bulbs (and there are a ton of them) before the lighting fixtures were properly maintained as they would most likely just blow the good bulbs and throw away a lot of your money. But once the fixtures are addressed we will need all of the bulbs that are down replaced ASAP so we can begin to show the space for sublease (after we address the remaining issues on my list).

When you are ready I can show you the chapter/verse of the original lease (which remains in effect regarding HVAC and Lighting R&M) and the 11th amendment explaining how we read it and hopefully you can show us how you see it and we can reach an understanding because I am sure you will agree that nobody wants to risk a fire through delay. That's the good thing about a

lease - we can always go back to it and see exactly what was agreed to so we should be able to figure this out quickly.

Thanks again for chatting with me on your vacation - I really do appreciate it. I'm available until 5 pm ET tomorrow and then from Saturday on whenever you are ready to review.

If we don't speak before have a Happy New Year!

John Worrell 404-840-6475

PS - If you send this to Mike and his people find something to address please let me know first before they do anything so I can coordinate with CBRE - I don't want to be accused of doing an end run on them and will need to get a formal request submitted through them before RAK does anything. Thanks.

Randy Kohana

From: Sent:

John Worrell [johnw.crc@gmail.com]

To:

Tuesday, March 09, 2010 4:16 PM Randy Kohana

Subject:

Re: please call me

Randy,

As mentioned I am booked out today and cannot get away this time. If you can please mail the asbestos report you told me about (preferably for the 6th floor but for a remodelled floor if not). Address below.

FYI - my brother is returning from meetings in Charlotte this afternoon and he should be contacting you today.

John

12020 Leeward Walk Circle Alpharetta, GA 30005

On Tue, Mar 9, 2010 at 12:38 PM, Randy Kohana < rkohana@rakgroup.com > wrote:

Randy Kohana

Chief Executive Officer

RAK Group LLC

270 Lafayette Street

New York, NY 10012

(212) 245-1601 (Tel)

(212) 245-7001 (Fax)

RKohana@rakgroup.com

www.rakgroup.com

*PLEASE NOTE OUR NEW ADDRESS ABOVE.

Seth Schochet

From:

John Worrell []ohnw.crc@gmail.com]

Sent:

Monday, February 01, 2010 4:34 PM

To:

Seth Schochet

Subject:

OMP

Attachments: BrandtElectricalReport.doc

Seth,

I overnighted you a CD with photos and reports from the HVAC inspection. I'm attaching their electrical/lighting inspection for 2 floors that I forgot to include.

I'm in bank meetings all day today but we need to talk ASAP. Crowded day tomorrow too but I need to review with you before I have to review with the bank.

The HVAC inspection turned up some things that are going to make my job very hard if we don't spin this right.

I sent you all the photos and inspection sheets on a DVD_ROM. Brandt Mechanical tested the entire 6th floor (fully occupied so we would have valid data and not just idle units) plus some sampling on other floors to cross validate. Please scan through all of them as soon as you can.

I am very concerned this is going to arm those within the bank that are pushing for early relocation against our advice. We have to figure out a solution or this is going to be taken from me. Please also review the lease and admendments. We can't afford anymore time arguing over who is and is not responsible for what. We have to agree on that this week. I've got my notes ready and will send them before we meet regarding the relevant sections of the lease as we see them. I need you to educate me where I am seeing things wrong if that is the case. At the very least we have to know where we agree to disagree. I can't report back with vagueness any longer.

Tomorrow is going to be real hard to find the time. Maybe Wed morning is better. I am open before noon Wed but will have to come up with a reason to punt my status report to the bank tomorrow.

Let me know if Wed morning is open please.

John 404-840-6475



January 26, 2010

Todd Ratliff Bank of America 1201 Main Street 18th Floor Dallas, TX, 75202

SUBJECT: IDENTIFICATION OF ELECTRICAL FUNCTIONALITY AND SAFETY AT 1201 MAIN ST, DALLAS, TX.

The following is a list of electrical issues found during our survey of the 12^{th} and 28^{th} floors at 1201 Main St in Dallas, TX. Though we did not formally review the 4^{th} , 6^{th} , or 7^{th} floors, we feel that similar issues may likely exist there, as well.

Our recommended service will be listed to the side coded as follows:

RL = Replace Lamps

RB = Replace Ballasts

FIN = Further Investigation Needed

RC = Replace Lens/Cover

RF = Replace Fixture

RS = Replace Sockets

RR = Replace Receptacle

A sequence of events may take place to fix the situation. If the first step in the sequence fixes the problem, then subsequent steps may not be required. Notated as such Step1-Step2-Step3-etc

12th Floor

- Exit sign by men's restroom blinks (RF)
- 2 X 2 light in men's restroom is out (RL-RB-FIN)
- Men's Restroom--
- 2 lamps 4' T8 needs ballast Other ones have T12 lamps (RL-RB-FIN)
- Receptacle under the sink has no cover plate, not GFCI. (RR w/ GFCI)
- 65 watt 130V flood light needs bulb over 1st sink (RL-FIN)
- Broken glass lens over urinals (RC)
- Women's Restroom-
- 5 lights no lens covers (2 lamps 1'X4' lights) (RC)
- 3 fluorescent sockets broken (2 lamps 1'X4' lights) (RS)
- 3 lights out (2 lamps 1'X4' lights) (RL-RB-FIN)
- 2 lights half on (2 lamps 1'X4' lights) (RL-RB-FIN)

AUSTIN at Commerce Dr., Suite 575 Austin, TX 78741 512.491.9100 TACLA 27629C TECL 20109 DALLAS 11245 Indian Trail Dallas, TX 75229 972-241-9411 TACLA 000468C YECL 20109 FORT WORTH 2502 Gravel Drive Fort Worth, TX 76118 817.626.0033 TACLA 20707E TECL 20109

SAN ANTONIO 6023 Corridor Plowy., Suite 100 Schertz, TX 78154 210,599,6129 TACLA 000745C TECL 20109 WACO 1100 Jewel Drive Waco, TX 76712 254.772.1693 TACLA 000430C TECL 20109



- 1 recessed light needs 65W 130V flood lamp (RL-FIN) Receptacle under sink not GFCI (RR w/ GFCI) Open Areas-No power to floor plugs (whole floor) (FIN) Wall plugs are good 66 lights have power but not working (RL-RB-FIN) 232 lights only 2 out of 4 lamps working (RL-RB-FIN) NW comer - 12 lights without power (FIN) North end West side - 5 lights have no power (FIN) SE corner – 4 lights have no power (FIN) 12 lights have broken or missing lenses (RC) Server/Raised Floor Room-Needs 2 - 3X4' T8 lamps (RL-RB-FIN) PDU is missing cover by main breakers. (RC) Janitor's Closet---1-4' T12 lamp is out (RL-RB-FIN) IT Room-6 - 2' T12 lamps needed (RL-RB-FIN)
- 28th Floor
 - Main Areas-19 lights out (with power on) (RL-RB-FIN) 324 lights 1/2 out (2 lamps working) (RL-RB-FIN) NE corner 20 lights have no power to them (FIN) 1 exit sign is out (FIN-RF) Women's Restroom⊶ 11 globe incandescent lamps are out (RL-FIN) Janitor's Closet-Need 1 - T12X4' Lamp (RL-RB-FIN) Copy/Fax Room-Light open, wire hanging, switch does not shut power off (FIN)

Thank you for the opportunity to work with you. We look forward to any future requests you may have.

Sincerely, Tommy Kilman **Account Development Brandt Engineering**

Office: 972.395.6098 Mobile: 214.769.0057

AUSTIN at Commerce Dr., Suite 575 Aussin, TX 78741 512491.9100 TACLA 27629C TECL 20109

DALLAS 11245 Indian Tol Dalles, TX 75229 972.241.9411 TACLA 000468C TECL 20109

FORT WORTH 2502 Gravet Drive Fort Worth, 7X 76118 817.626.0033 **TACLA 20707E** TECL 20109

1 - 2X2 Lens required (RC)

SAN ANTONIO 6023 Corridor Plovy., Suite 100 Schertz, TX 78154 210.599.6120 TACLA 000745C TECL 20109

WACO 1100 Jewell Drive Waco, TX 76712 254.772.1693 TACLA 000430C TECL 20109



January 25, 2010

Bank of America One Main Place 1201 Main Street Dallas, Texas

Attention: John Worell

Proposal for repairs for chilled water fan coil units

We are pleased to offer this proposal to clean the coils and make necessary repairs on the 102 room fan coll units Brandt inspected. Following is our price per unit inspected and any additional accessible units at 1201 Main Street in Dallas, Texas.

Price per unit:

- 1. Blower assembly replacement per unit: \$766.45
- 2. Clean in place and re-insulate condensate pan per unit: \$1,301.16
- 3. Replace heat strip per unit: \$874.79
- 4. Replace T-Stat per unit: \$658.10

Exclusions:

- 1. All work to be done during normal work hours.
- 2. Repairs are contingent on water isolation valves operating.
- 3. This proposal does not include any repairs to water connections, valves and piping.
- 4. No work will be performed on any asbestos containing material.
- 5. The parts replacement is contingent on factory supplied parts being readily available.
- 6. Tax is not included in this proposal.

AUSTIN 1340 Akport Conveneroe Dr., Suite 575 Austin, TX 78741 512.491.9100 DALLAS 11245 Indian Traff Dallas, TX 75228 972241.9411 FORT WORTH 2502 Gravel Drive Fort Worth, TX 76118 817.626,0033 SAN ANTONIO 6023 Corridor Phwy., Suite 100 Schertz, TX 78154 210.599.6120 WACO 1100 Jewel Drive Waco, TX 76712 254.772.1693

Seth Schochet

From: John Worrell [johnw.crc@gmail.com]
Sent: Thursday, February 11, 2010 5:49 PM

To: Seth Schochet Subject: OMP Letter

Seth,

Last we spoke you and Randy were working up a letter for the bank stating the steps you were committed to taking regarding the lighting and HVAC unit maintenance. I told BAC this was in on the way over a week ago. I got cornered at a meeting today about it.

Can you please get with Randy and get us that letter ASAP so I can show Ratliff that we have at least some progress happening here?

Thanks in advance,

John 404-840-6475

Seth Schochet

From: John Worrell [johnw.crc@gmail.com]

Sent: Thursday, February 18, 2010 7:23 PM

To: Seth Schochet; mh@rakgroup.com

Subject: Environmental Reports

Please be advised that Todd Ratliff from Bank of America is planning on stopping by the RAK office at OMP tomorrow afternoon to review the Environmental Reports referenced in the 11th Amendment to the Lease. Please make sure all of the reports are available. Please let me know ASAP if this will not be the case.

Seth - I sure would feel better if I could review these reports myself first without running the risk of my client asking a lot of questions about things I can't anticipate and that I would not otherwise need to include in my report but unless you can help me with that we'll just have to go this route and hope for the best.

Seth Schochet

From: John Worrell [johnw.cre@gmail.com]

Sent: Monday, February 15, 2010 1:34 PM

To: Seth Schochet

Cc: todd.ratliff@bankofamerica.com

Subject: Re: One Main Place - Bank of America

Todd,

I needed to clarify a misstatement by RAK in their recent letter.

In the third paragraph they state, "Upon such inspection with Mr. Worrell, it was determined that no leaks existed and there is no problem with the HVAC system or structure of the Building causing any water intrusion."

This could easily be misread to assume I had endorsed their conclusion and that is not the case. In short, I did not agree that the HVAC units or structural issues with the building were not a problem and I am disappointed to have been painted in that way.

I needed to make certain you were not confused by RAK's statement regarding my conclusions which will be submitted in the formal report due by the end of this month.

John

On Fri, Feb 12, 2010 at 2:36 PM, Seth Schochet <sschochet@rakgroup.com> wrote: | Todd-

Please see the attached letter.

Seth Schochet RAK Group LLC 270 Lafayette Street New York, NY 10012 (212) 245-1601 (Tel) (212) 245-7001 (Fax) Schochet@rakgroup.com www.rakgroup.com

*PLEASE NOTE OUR NEW ADDRESS ABOVE.

Seth Schochet

From: John Worrell [johnw.crc@gmail.com]

Sent: Monday, March 08, 2010 5:16 PM

To: Seth Schochet

Subject: OMP

Seth,

Todd got back to me with his notes on the Environmental Reports and we need to chat first thing in the morning. When are you and Randy available? I've got to wrap up my report this week - I'm already late - and asbestos has become a major issue.

I'm booked for the day starting at noon so hopefully before that.

"andy Kohana

From: Sent: To: John Worrell [johnw.crc@gmail.com] Monday, March 15, 2010 6:16 PM Seth Schochet; Randy Kohana

Cc: Subject: dworrell@att.net OMP Roof

Guys,

See below email. I'm trying to get a grip on this but it is getting out of hand. The Dallas big wigs who want to move West are using this and everything else as a 'why bother anymore' response to our efforts to make the bank happy and stay put. Every call I'm getting challenged more directly. If we don't figure this out soon we won't be able to convince Charlotte that reasonable OMP rent dollars are worth all the headaches and risk. The natives have started beating their drums.

Terry Howell was asked how many times RAK has been notified about this leak and Terry said probably 3 times in the last 5 months (he's new and started in October) but that he doesn't know how many times in the past before he got here. As a result I was just sent the last three years maintenance request logs (a monster spreadsheet) by CBRE and BAC asked me to go through it line by line and start documenting request patterns. It goes without saying that I really don't have time for this but I'm the gopher and that's my job.

I see from below that Sitemark has been tasked to set up a roof inspection with Mike Horstman. I was in a call today that raised the issue of the 33rd floor. The worry is that the roof is failing and if this much water is making it down to the 32rd floor the 33rd floor is probably growing tadpoles - and Randy, 32rd floor leaks can't be due to BAC verticle cuts. The concern is that with the 33rd floor being the building's central HVAC floor this rain could create quite the moldy environment and since we've already tested and found Stachybotrys on the 28th floor (a very not healthy species) that makes BAC very concerned about air quality and safety. I'd be surprised if this doesn't spread into a full scale mold and asbestos inspection on the 33rd floor because running water is very bad for even non-fryable asbestos.

Randy - you never sent me the asbestos report you promised - 6th floor if possible, if not then a remodelled floor. Please send overnight to 12020 Leeward Walk, Alpharetta, GA 30005 so I can get a handle on this.

My boss at BAC is out of the country through this week so I've got some breathing space but come Monday I'm going to have to be prepared to answer some tough questions and I'm obviously not getting anywhere working with you guys on this.

You've got to help me help RAK and BAC fix this or I'm going to have no choice but to join the swelling ranks and let BAC know my recommendations are to plan on packing. I can't fight this battle much further without having something to show for it.

John Worrell 404-840-64375

From: Williams, Lawrence @ Dallas

Sent: Wednesday, March 10, 2010 1:43 PM **To:** 'Michael Horstman'; 'Shenikqua Davis'

Cc: Flynn, Bob @ Ft. Worth

"ubject: 32nd Floor OMP

There continue to be roof related water issues that need to be addressed:

- Water is dripping (as I write this) into space along north side. Dwights crew needs to clean this area and remove the cart that has been left behind by someone. (Shealeque, please handle)
- Ceiling tiles need to be replaced. This is in addition to the 4X4 tiles you mentioned were on order.
- Sheetrock repairs and painting is needed due to roof leaks.
- Ceiling tile stock needs to be removed from space that is stacked on top of one of the cubicles.
- Roof repairs need to made to resolve this issue which has been chronic. David Cook with Sitemark will be contacting you to set up a time to inspect roof.

Seth Schochet

From: Randy Kohana

Sent: Wednesday, March 17, 2010 9:52 AM

To: Seth Schochet

Subject: FW: Bank of America

Randy Kohana
Chief Executive Officer
RAK Group LLC
270 Lafayette Street
New York, NY 10012
(212) 245-1601 (Tel)
(212) 245-7001 (Fax)
RKohana@rakgroup.com
www.rakgroup.com

*PLEASE NOTE OUR NEW ADDRESS ABOVE.

From: David Worrell [mailto:dworrell@att.net]
Sent: Tuesday, March 16, 2010 4:22 PM

To: Randy Kohana **Subject:** Bank of America

It is imperative we speak as soon as possible. I have till Friday to either work something out with you or BAC's environmental group and attorneys take it over themselves. That outcome is obvious — and it is not 5 years out. It is 5 weeks out.

Cambridge Consulting Group Inc.
David Worrell
678-488-2504
678-456-8118
dworrell@att.net

Randy Kohana

From: Sent: David Worrell [dworrell@att.net]
Monday March 22, 2010 5:06 AN

To: Cc: Monday, March 22, 2010 5:06 AM Randy Kohana

Subject: Attachments: 'John Worrell' Resolution Offer OMP Basis.xls

Importance:

High

Randy:

As promised, this is the offer from Bank of America to resolve both parties' issues with One Main Place, Dallas, TX. To begin, there has been a ground-swell of desire and demand from the Bank employees located in One Main Place (OMP) to relocate to other Bank facilities in the Dallas Metro-plex.

Up until this weekend my understanding for this was a desire to be in better facilities. As of now I know more specific reasons which you will receive later tomorrow based on the amount of complaints and requests for more reasonable working conditions. My group was brought in to determine the expenses of either moving these employees or managing the repairs to end their issues.

Rather than getting into a continuing dispute as to the validity of these issues and the costs of ending them —! will simply offer a method and amount which will do just that without greater risk to your company. As I explained to you, Charlotte wants to remain in the majority of the space they presently occupy due to the favorable costs of the lease. Unfortunately, Charlotte cannot ignore the complaints of their employees working at OMP.

Again, as I explained to you – the problem can be isolated to 6 of the 17 floors the Bank presently occupies. Due to the present conditions, these 6 floors are now being vacated and the employees located on those floors are being re-located to other places in the building or elsewhere.

Having these floors vacant is why the Bank wanted to sublease these floors — but not without first verifying that these floors were totally safe to put another company into their space. This proved to be a problem. This is not due to Bank leasing "too much space" but the safety and working conditions on these floors. The Bank can no longer subject their employees, or take on the liability for another company - to these conditions and must make immediate changes to mitigate the losses they have incurred and are continuing to incur.

Based on the continued complaints within the building – the Bank hired certified engineers to determine the validity of these issues. Their answers were conclusive and verified the complaints. As of now, the estimate for complete repair and remediation of these floors is approximately \$13.42 per square foot per floor – 6 floors or 17 floors depending on your agreement to this offer.

The floors which the Bank has or is presently exiting are:

- 4 All but 1,512 square feet located in the building core where data equipment resides (unless terminated in 2014).
- 6 Will not be vacated until the end of 2011.
- 7 Effective immediately.
- 12 Effective immediately.
- 28 Effective immediately.
- 31 Effective immediately.

Based on the first attached spreadsheet, you can verify the Bank's obligation until their expected termination date of December 31, 2014. Based on the second spreadsheet, you can verify the remaining obligation of the Bank on these vacated floors.

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 43 of 122 PageID 629

The Offer: The basis of this offer stands on the fact that at this point the Bank intends to terminate the lease at the end of 2014.

Although this offer has not been authorized by BAC's Dallas Management, the following offer is extended until Wednesday of this week when a decision will be made as to how the Bank will proceed with this issue.

- 1. The Bank will agree to extend the termination date for the entire lease minus the 6 floors by 12 months.
- 2. The Bank will give RAK a fee of \$1,019,958.34 (the repair and remediation costs for these 6 floors) as a termination fee.
- 3. The Bank will sign a clean Estoppel for their entire lease.

Randy, there are many more reasons as to the amount of this offer. I will be happy to speak with you IN PERSON about them. If you want to negotiate further, please set up a time for us to meet. Remember, Charlotte wants this to work; but cannot afford to let these issues pass any longer. And as they say in real estate-eze: "time is of the essence".

Thank you for your kind consideration. I hope to hear from you soon.

PS: This offer is final and is void if not accepted as of 6 P.M. Wednesday, March 23rd, 2010.

Corporate Risk Consultants Inc.

David R. Worrell

Managing Director

678.488.2504 or 678-456-8118

dworrell@att.net <<...>>

CAM
$\overline{\omega}$
Z
₽
G
Ш
0248
N

7	SQ FT	MONTHLY	PSF	2010	2011	2012	2013	2014	Buyout Fee	NCOME .
Floor				From 4-1						
32	29,660	22,245	9.00	200,205	266,940	266,940	266,940	266,940		1,379,190
31	29,660	22,245	9.00	. 200,205	266,940	266,940	266,940	266,940		-54,379,490
29	29,660	22,245	9.00	200,205	266,940	265,940	266,940	266,940		1,379,19
28	28,678	21,509	9.00	193,577	258,102	258,102	258,102	258,102		~21,333,52
26	29,660	22,245	9.00	200,205	266,940	266,940	266,940	266,940		1,379,19
25	29,082	21,812	9.00	196,304	261,738	261,738	261,738	261,738		4,852,31
21	28,108	21,081	9.00	189,729	252,972	252,972	252,972	252,972		1,307,02
18	29,082	21,812	9.00	196,304	261,738	261,738	261,738	261,738		1,352,31
12	27,440	20,580	9.00	185,220	246,960	246,960	246,960	246,950		1,275,96
11	27,440	20,580	9.00	185,220	246,960	246,960	246,960	246,960		1,275,96
10	27,440	20,580	9.00	185,220	246,960	246,960	245,960	246,960		1,275,96
9	26,484	19,863	9.00	178,767	238,356	238,356	238,356	238,356		1,231,50
8	28,387	21,290	9.00	191,612	255,483	.255,483	255,483	255,483		· · 1,319,99
7	27,440	20,580	9.00	185,220	246,960	246,960	246,960	246,960		1,275,96
6	27,440	20,580	9.00	185,220	246,960	246,960	246,960	246,960		1,275,96
4	27,286	20,465	9.00	184,181	245,574	245,574	. 245,574	245,574		1,268,79
3	27,257	20,443	9.00	183,985	245,313		245,313	245,313		1,257,45
Vault	10,340	7,755	9.00	69,795	93,060	93,060	93,060	93,060		480,81
	 									l
TOTALS:	490,544	367,908	9.00	3314,172	4,414,896	4,414,896	4,414,896	4/414/896	1,839,540	2,22,610 21

RAM Bookable Revenue Basis Through End of 2014

RAK Bookable Revenue Basis Through End of 2019 Minus Confraction

	SQ FIRE	MONTHLY	PSF	2010	2011	2012	2013	2014	2015	Buyout Fee	INCOME
Floor	l			From 4-1							
32	29,660	22,245	9.00	200,205	266,940	266,940	266,940	266,940	281,770	24.4500000000000000000000000000000000000	1,667,139
31	29,660	22,245	9.00	0	0	0	0	0	0	0	0
29	29,660	22,245	9.00	200,205	266,940	266,940	266,940	266,940	281,770	् गान्याच्या	1,667,139
28	29,660	22,245	9.00	0	. 0	0	0	0	0	0	Q
26	28,678	21,509	9.00	193,577	258,102	258,102	258,102	258,102	272,441	1000000	1,611,943
25	29,660	22,245	9.00	200,205	266,940	266,940	266,940	266,940	281,770	2017年1月1日日本	1,667,139
21	29,082	21,812	9.00	196,304	261,738	261,738	261,738	261,738	276,279	是一点。 电铁铁	1,534,651
18	28,108	21,081	9.00	189,729	252,972	252,972	252,972	252,972	267,026	الرفي إنائية سنبت	1,579,904
12	29,082	21,812	9.00	0	0	0	0	C	0	0	0
11	27,440	20,580	9.00	185,220	246,960	246,960	246,960	246,960	260,680	in the graph	1,542,357
10	27,440	20,580	9.00	185,220	246,960	246,960	246,960	246,960	260,680	19.00	1,542,357
9	27,440	20,580	9.00	185,220	246,960	246,960	246,960	246,960	260,680	1.54.14	1,542,357
8	26,484	19,863	9.00	178,767	238,356	238,356	238,356	238,356	251,598		1,488,622
7	28,387	21,290	9.00	0	0	0	. 0	C	0	0	0
6	27,440	20,580	9.00	185,220	246,960	0	0		0	0	432,180
4	1,512	1,134	9.00	10,206	13,608	13,608	13,608	13,608	14,364	$ x \leq \frac{1}{2} \sqrt{\frac{1}{2}} \sqrt{\frac{1}{2}}$	84,987
3	27,257	20,443	9.00	183,985	245,313	245,313	245,313	245,313	258,942	(1) THE SE	1,532,071
Vault	10,340	7,755	9.00	69,795	93,060	93,060	93,060	93,060	98,230		581,194
TOTALS:											
	466,990	350,243	9.00	2,363,857	3,151,809	2,904,849	2,904,849	2,904;849	3,065,230	1,277,596	的可能的影響的

Randy Kohana

From: Sent:

To:

John Worrell [johnw.crc@gmail.com] Monday, March 22, 2010 5:46 PM Randy Kohana; Seth Schochet

Subject: Attachments: OMP Sick Building Syndrome 03212010_Work Order Report.xls

Randy/Seth,

I found the source of the BAC ground swell to leave OMP — it's everyone from hourly staffers to SVPs. Going through 2,000+ line items of work orders over a two year period was mind numbing enough but nothing like this clear and documented pattern of RAK neglect. I'd be surprised if there were a single BAC employee left at OMP who hasn't filed some kind of complaint about their working conditions. In all honesty, I've never seen anything like this and I've audited more buildings than I can remember. I've never seen something so systemic and with such clear patterns that RAK should have grasped and taken pro-active and preventative measures against. Seriously, did you think that this wouldn't eventually catch up with you? You can siphon cash out of a building for only so long.

We're talking an average of 2+ requests per day – more than half for HVAC issues: dirt and dust making people feel sick (specific complaints about 'respiratory issues', coughing and sneezing), banging and clanking of unmaintained equipment, HVAC leaks, even the smell of smoke and burning all compounded by an increasingly frustrated BAC staff at having their requests essentially ignored. There is no way RAK couldn't have seen that the HVAC units and ballasts were falling apart due to neglect and were, in fact, a safety and health hazard.

Some examples as reported to RAK:

04/04/2008: 6th fir south end of the building there is an *electrical burning smell* please investigate 05/27/2008: On the 21st floor - Lights in the office are not working - *seems to be a bad ballast - has a burning smell*

06/04/2008: Caller There is a burning smell (maybe wires) down the hall way on the 10th floor

07/17/2008: The a/c vents in Cindy Neinast's office are making a lot of noise that is disruptive to her work

07/25/2008: Some areas of the floor continue to be too cold - we're getting daily complaints from associates.

10/29/2008: 18th floor - East end - Many people are complaining that it is extremely cold.

11/05/2008: 11th floor north side. Caller says sparks came out of a ceiling light, now the lights are not working.

11/21/2008: Half of the NE side of the building is blowing cold air. **Also the previous attempt to adjust** the cold air **was a failure**

12/03/2008: 29th floor - hvac vent needs to be shut in cube 69 for Rachel Kufunoki as it is to much air *making* her sneeze

01/07/2009: 25th main street side, please repair ac unit its leaking water on the carpet .

01/30/2009: Caller says the a/c vents are very loud. Caller says they have a SVP on site and its very loud in the office.

04/07/2009: 26th floor Construction Lending Dept. *Caller says a/c vent is leaking near a window* 05/14/2009: Caller states the HVAC venting along the back windows is producing a *burning smell* and there is a *banging noise*

05/18/2009: please provide temperature readings from each reader.....numerous complaints that the floor in all areas are too cold.

06/08/2009: AC Vent blowing on location 9-145 is causing the associate to continually cough.

06/12/2009: need carpet replaced or cleaned since air conditioner leaked on the floor. Carpet is beginning to smell

09/15/2009: 32nd - Piece of the ceiling tile fell off onto the floor, soaking wet, been raining for five days 10/07/2009: 6th flr Need to clean all hvac vents. per caller several associates have reported "respiratory" issues.

10/28/2009: 21st flr Coporate Security Dept there is a *ceiling leak in the corner leaking down wall from HVAC* 11/05/2009: *air conditioner is leaking water* by Pat Herndons desk on the 26th floor

·11/20/2009: No hot water in restroom sinks - since we moved back after the renovation almost a year ago - complaints have gone unheeded.

I've highlighted the more egregious examples in vellow in the attached XLS. I cannot over-state the impact this will have. Boy I wish I had received this sooner. Come Thursday you can expect this to turbo-charge BAC's efforts to evacuate at-risk staff and confront this head on. BAC will not accept liability for RAK's negligence. People are reporting getting sick in your building. Rain water intrusion everywhere, mold, clogged, leaking and burning HVAC units, sparks and burning ballasts, ACMs. This is bad — very bad. My advice to BAC will be to double down on inspections and auditing to demonstrate my client's commitment to public health and safety. We're bringing OSHA, the EPA and TDSHS out there on an accelerated schedule - just as soon as I can bundle this last report with the other inspections.

I recall when we first met in your office that all three of you acted stunned and befuddled because "this is the first we're hearing about these kinds of problems". If that were true then Mike has kept you seriously in the dark about this flood (pun regrettably intended) of constant and repeat requests. The pattern of repeated requests for the same unresolved issues — some of them safety related — inarguably demonstrates RAK's blatant disregard.

And keep in mind that these logs cover 2008 and 2009 when RAK was receiving a 44% higher base rent than 2010 (\$13/PSF). It raises the legitimate concern that given how RAK was so clearly milking the property then, how much lower will the service levels drop at \$9/PSF? This is going to seriously undermine the perceived value of \$9/PSF.

I've culled and attached about 775 individual work orders to make the point. Note that about 100 of these were handled internally by CBRE and BAC contractors and I left them in on purpose. These are a big problem because CBRE was spending BAC money to fix issues that RAK was responsible for. I can assure you that will change going forward. Your building; your problem.

I'd been told that CBRE started doing RAK's job because it was just easier and faster than constantly asking RAK and waiting and only having the most minimal solution applied resulting in an almost immediate recurrence of the issues. CBRE simply got tired of the "don't shoot the messenger" syndrome as BAC staff were losing their patience with them for RAK's failures.

I'm truly afraid that when I report this to BAC at my conference meeting this Thursday they're going to make me move to Dallas and work out of OMP to personally handle this auditing and accountability on a daily basis in 2010.

Go ahead and scan through this shortened list. If you sort by category you can see how chronic these patterns are. If you sort by date you can see the constant and never ending nature of these issues.

180+ complaints about lighting issues 430+ complaints about the HVAC systems 115+ Plumbing and leak issues

Yes, all buildings have issues, but this is clearly self-inflicted and on a scale I have never before imagined.

Randy, this is a smoking gun. When BAC ties this proof of pattern back to the inspection reports, your claims that there are no problems or that they are BAC's fault or that they aren't problems so much as minor 'issues' that you'll be happy to fix won't fly anymore - and this in addition to the ACM issue. The Dallas execs who want to move are going to have a field day with this on Thursday.

I promised you a first look at what I found and here it is. I'll call shortly because I don't want to walk into my meeting without having some kind of answer to this. RAK needs to come up with some kind of solution that will help me keep BAC from going ballistic. And I'm not talking the same tired promises from the past. That dog won't hunt.

John Worrell Corporate Risk Consultants 404-840-6475

Randy Kohana

From: Sent: Michael Horstman [mh@rakgroup.com] Monday, March 22, 2010 5:18 PM Randy Kohana; Seth Schochet

To: Subject:

BofA 28th Floor Leak

Today while I was walking the vacant floors, I came across water leaking in a large meeting room in the interior of the 28th floor. I got a ladder and removed one of the wet ceiling tiles to see where it was coming from. The water was coming from around a drain hub on the 29th floor. I called Larry Williams, with CBRE and asked him to meet me on the 29th floor. I located the wet area under the raised floor in Bank of America's computer lab. The water was coming out from behind one of their leibert units. I knew it was coming from their lab because the leak was in the same general area as the one they had several weeks ago under one of their other leibert unit in the lab.

Michael Horstman, RPA,FMA,SMA

Property Manager

One Main Place

1201 Main Street, Suite 100

Dallas, Texas 75202

Office: 214-744-9815

Cell: 214-532-7800

Fax: 214-744-9810

mh@rakgroup.com

Randy Kohana

From: Sent: Michael Horstman [mh@rakgroup.com] Tuesday, March 23, 2010 2:53 PM

To: Subject: Randy Kohana; Seth Schochet Leaks Found on Vacant BofA Floors

Last Tuesday, March 16, one of my engineers was walking the vacant BofA floors and found a leak on the 7th floor. He investigated and found the source was BofA's water heater serving their break room on the west side. The water to the water heater was valved off. We also found that the pressure regulating valve for their southeast break room on 7 is also leaking.

Michael Horstman, RPA,FMA,SMA

Property Manager

One Main Place

1201 Main Street, Suite 100

Dallas, Texas 75202

Office: 214-744-9815

Cell: 214-532-7800

Fax: 214-744-9810

mh@rakgroup.com



SIGMA Environmental Solutions, Inc.

March 24, 2010

Mr. Seth Schochet RAK Group LLC 270 Lafayette Street New York, NY 10012

RE: Status Report

One Main Place Office Building 1201 Main Street Dallas, Texas

Mr. Schochet:

Sigma Environmental Solutions, Inc. (Sigma) has been providing asbestos and mold consulting services in the One Main Place office building in Dallas, Texas, since October of 2007. During this time Sigma has prepared specifications for the abatement of asbestos-containing-building-materials (ACBM) and monitored the abatement that was conducted on floors 3, 8, 9, 10, 11, 18, 21, 24, 25, 26, 29, 31, 32 and in the building core piping chase. The abatement occurred over the past few years.

All applicable rules and regulations were adhered to during the abatement and all air samples obtained were within regulatory and project specification requirements. The abatement was completed by North Star Abatement Corporation. All North Star employees who were involved in removal of asbestos containing materials (ACM) were accredited and licensed according to state and federal regulations.

Sigma was provided survey reports prepared by EFI Global, Inc. to review prior to preparing the specifications. Sigma reviewed the survey for each floor to be renovated and performed an inspection to determine if all suspect ACBM had been addressed, and then collected additional samples if needed. ACBM identified to be disturbed by the renovations, or was damaged and in need of removal, was included in the specifications for removal.

Non-friable materials that would not be affected by the renovations were left in place including without limitations the perimeter HVAC units and are not required by OSHA, EPA NESHAP, or Texas Department of State Health Services (TDSHS) to be removed.

Sigma collected additional samples of insulation and mastic associated with the condensate pan of the unit. The results of the sampling were negative.

Sigma has also performed surveys on other lease spaces within the building prior to renovation. Identified ACBM to be affected by the renovations was removed in accordance with all required OSHA, EPA NESHAP, and TDSHS regulations in these areas as well.

One Main Place Status Report Page 2

One Main Place has an Asbestos Management Plan in place to maintain ACBM and prevent any exposure to building occupants or servicemen. The Asbestos Management Plan contains O&M procedures to be used when encountering asbestos materials. The policy in the manual requires all disturbance of ACBM be performed by personnel licensed or certified by TDSHS. Additionally, prior to any disturbance of suspect ACBM, the existing survey is to be checked to determine if the material has been identified as ACBM, or if it needs to be tested prior to disturbance.

Thank you for the opportunity to provide RAK Group LLC with our environmental consulting services. Should you have any questions or concerns, please contact the undersigned at (972) 572-1400.

Respectfully

Rick D. Orr


Vice President/Director of IAQ Services

Environmental Services

TDSHS Licensed Individual Asbestos Consultant

License No. 10-5103





SIGMA Environmental Solutions, Inc.

March 24, 2010

Mr. Michael L. Horstman Property Manager RAK Group, LLC 1201 Main Street, Suite 100 Dallas, Texas 75202

RE: Limited Asbestos Testing
One Main Place
HVAC Window Units
1201 Main St.
Dallas, Texas 75202
Sigma Project No. 2100043

Dear Mr. Horstman:

Sigma Environmental Solutions, Inc. (Sigma) has completed limited testing for asbestos-containing building materials (ACBM) in the HVAC Window Units located around the perimeter of the floors in the One Main Place Building, Dallas, Texas. The testing was limited to the insulation on the exterior of the condensate pan. and foam insulation between the coil and the case. The test areas included the fifteenth floor and the fourth floor. The survey included visual observations, material sampling and laboratory analysis of suspect ACBM on the site. Mr. Rick D. Orr of Sigma performed the inspection on March 11, 2010. Mr. Orr is a DSHS licensed Individual Asbestos Consultant (DSHS License No. 10-5103).

A total of six (6) bulk samples of suspect ACBM were collected from two (2) suspect homogeneous materials in the HVAC Units. Bulk samples were collected from the following materials: condensate pan insulation and mastic, and white foam insulation.

Sampled materials were delivered under proper chain of custody to Steve Moody Micro Services Inc., of Carrollton, Texas, an accredited NVLAP (Lab No. 10-2056) and DSHS (License No. 30-0084) licensed laboratory for analysis by Polarized Light Microscopy (PLM) with dispersion staining techniques per EPA Method 40 CFR, Ch. 1, Part 763, Subpart F, Appendix A. The percentage of asbestos, where applicable, was determined by visual estimation. Based on the laboratory analysis, asbestos was determined to be present in the following materials:

No asbestos containing materials were found

SIGMA understands there are other Asbestos Containing Materials identified in the HVAC units. Prior to scheduled renovations or demolition that could impact the materials identified as ACBM in a prior report, State of Texas and Federal regulations require ACBM to be removed prior to performing the renovation or demolition activities that would affect those materials. It is also important to note that state and federal regulations require a ten (10) working day notification prior to any demolition activities in a building that affords public occupancy, regardless of whether asbestos is present or not.

HVAC Window Unit Testing Report Page 2

Materials in those areas not addressed by this survey should be tested to determine whether they contain asbestos prior to any additional renovation or demolition activities.

The identified renovation area was inspected and homogeneous materials were identified. Samples were collected on a homogeneous material basis. Any asbestos containing materials, if found, are listed in Attachment A. Each homogeneous material is described and functional spaces are identified in Attachment B. A minimum of three bulk samples were collected from each homogeneous material. The reports of laboratory analysis of all samples collected are included in Attachment C. Specific company and personnel documentation are located in Attachment D.

Sigma was also requested to inspect the twelfth, seventh, and fourth floors for evidence of mold growth on ceiling tiles. Rick D. Orr of Sigma is a DSHS licensed Mold Assessment Consultant (DSHS License No. MAC0363). During the walkthrough inspection of the floors various locations of water stained ceiling tiles were observed. The water stains did not appear to be the result of a continuing condition, the water leaks had been corrected and the tiles were dry to the touch. Sigma also visually inspected some of the Window HVAC Units on these floors.

No mold growth was observed.

On March 24, 2010, Rick D. Orr of Sigma re-inspected the affected areas, as well as the twenty-eighth floor and all water stained tiles in these areas have been replaced. During this re-inspection several areas above the ceiling were visually inspected for mold growth and again none was observed. Any future leakage should be repaired immediately, wet tiles should be removed and disposed of, and new tiles installed after the leak has been corrected. Tiles with existing stains should also be replaced.

We appreciate the opportunity to provide asbestos-related services to RAK Group, LLC and look forward to working with you on future projects. If you should have any questions regarding this report, please contact the undersigned at (972) 572-1400.

Respectfully,

∑ SIGMA Environmental Solutions, Inc.

Rick D. Orr

Vice President/Director of IAQ Services

Environmental Services

ATTACHMENT A INVENTORY AND ASSESSMENT OF ACM ATTACHMENT B INVENTORY OF HOMOGENOUS MATERIALS ATTACHMENT C PHOTOLOG

ATTACHMENT D REPORT OF LABORATORY ANALYSIS

ATTACHMENT E COMPANY AND PERSONNEL DOCUMENTATION

ATTACHMENT A

INVENTORY AND ASSESSMENT OF ACM

BUILDING / AREA: HVAC Window Units 15 th Floor and 4 th Floor	DATE INSPECTED: 3/11/10
SIGMA ENVIRONMENTAL SOLUTIONS, INC. PROJECT NO.: 2100043	INSPECTED BY: Rick D. Orr, TX License #10-5103

INVENTORY AND ASSESSMENT OF ASBESTOS-CONTAINING MATERIALS

AREA MATERIAL LOCATION SA	WALE TYPE FRIABLE MATER	AL CONDITION ASBESTOS CONTENT
	QUANT	FY : None Detected)
No asbeste	os containing materials were foun	d

ATTACHMENT B

INVENTORY OF HOMOGENOUS MATERIALS

AMB
RIDG
) (2)
4840

BUILDING / AREA: HVAC Window Units 15 th Floor and 4 th Floor		DATE INSPECTED: 3/11/10
SIGMA ENVIRONMENTAL SOLUTIONS, INC. PROJECT NO.: 2100043	INSPECTED BY: Rick D. Orr, T	K License #10-5103

INVENTORY OF HOMOGENEOUS MATERIALS

ZB-45-document in the star	HOMOGENEOUS MATERIALS DESCRIPTION	FUNCTIONAL SPACES				
M01	Black Insulation and Mastic on HVAC Condensate Pan	HVAC Units at Perimeter Windows throughout building	1,2,3	N/A	NEG	ND - Insulation ND - Mastic
M02	White Foam Insulation at Coil Fins to Case Joint	HVAC Units at Perimeter Windows	4,5,6	N/A	NEG	ND - Insulation

ATTACHMENT C

PHOTOLOG -


Site Location: One Main Place

Dallas, Texas

Date:

March 11, 2010

Photographer: Rick Orr



. Black Insulation and Mastic on HVAC Condensate Pan


Site Location: One Main Place

Dallas, Texas

Date:

March 11, 2010

Photographer: Rick Orr



2. Black Insulation and Mastic on HVAC Condensate Pan

RAK Main Place Associates L.P. 1201 Main Street, Dallas, Texas SITE PHOTOGRAPHS

SOLUTIONS, INC.

Site Location: One Main Place

Dallas, Texas

Date:

March 11, 2010

Photographer: Rick Orr



3. White Foam Insulation at Coil Fins to Case Joint

Site Location: One Main Place

Dalias, Texas

Date:

March 11, 2010


Photographer: Rick Orr



4. Water stained ceiling tiles on fourth floor.

RAK Main Place Associates L.P. 1201 Main Street, Dallas, Texas SITE PHOTOGRAPHS

∑ SIGMA ENVIRONMENTAL SOLUTIONS, INC.



ATTACHMENT D

REPORT OF LABORATORY ANALYSIS

PLM Summary Report

Steve Moody Micro Services, LLC

2051 Valley View Lane

NVLAP Lab No. 102056 TDSHS License No. 30-0084

Farmers Branch, TX 75234 Phone: (972) 241-8460

Client: Project: SIGMA Environmental Solutions

OMP HVAC Units under Windows

Lab Job No.: 10B-02273 Report Date: 03/11/2010

Project #:

210 00

Sample Date: 03/11/2010

Identification:

Asbestos, Bulk Sample Analysis

Test Method:

Polarized Light Microscopy / Dispersion Staining (PLM/DS)

EPA Method 600 / R-93 / 116

Page 1 of 1

On 3/11/2010, six (6) bulk material samples were submitted by Rick Orr of SIGMA Environmental Solutions for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
OMP01	Foam Insulation of Condensate Pan, 15th Floor Suite 1515 Northwest Office Unit	None Detected - Insulation None Detected - Black Mastic
OMP02	Foam Insulation of Condensate Pan, 15th Floor Suite 1515 Northwest Office Unit	None Detected - Insulation None Detected - Black Mastic
ОМР03	Foam Insulation of Condensate Pan, 15th Floor Suite 1515 Northwest Office Unit	None Detected - Insulation None Detected - Black Mastic
ОМР04	Foam Insulation (White) at Coils, 4th Floor South Side Units	None Detected - Insulation
OMP05	Foam Insulation (White) at Coils, 4th Floor South Side Units	None Detected - Insulation
ОМР06	Foam Insulation (White) at Coils, 4th Floor South Side Units	None Detected - Insulation
-		

These samples were analyzed by layers. Quantification, unless otherwise noted, is performed by calibrated visual estimate. Results may not be reproduced except in full. This test report relates only to the samples tested. These test results do not imply endorsement by NVLAP or any agency of the U.S. Government. Accredited by the National Voluntary Laboratory Accreditation Program for Bulk Asbestos Fiber Analysis under Lab Code 102056.

risual hese NVIAP
2056.

Benne Voll

Analyst(s): Kirsten Tye

Lab Manager: Bruce Crabb

Lab Director: Steve Moody

Approved Signatory:

Approved Signatory:

Thank you for choosing Steve Moody Micro Services

Steve Moody Micro Services, LLC

2051 Valley View Lane

PLM Detail Report Supplement to PLM Summary Report NVLAP Lab No. 102056 TDSHS License No. 30-0084

Farmers Branch, TX 75234 Phone: (972) 241-8460

Client:

SIGMA Environmental Solutions

Project: OMP HVAC Units under Windows

Project #: 210 00

Lab Job No.: 10B-02273

Report Date: 03/11/2010

						Pag	ge 1 of 1
Sample Number	Layer		% Of Sample	Components	% of Layer		Analyst
OMP01	Insulation (Black)		95%	Glass Foam	100%	03/11	KT
	Black Mastic (Black)		5%	Binders / Fillers	100%	1	
OMP02	Insulation (Black)		95%	Glass Foam	100%	03/11	KT
	Black Mastic (Black)		5%	Binders / Fillers	100%)	
OMP03 -	Insulation (Black)		95%	Glass Foam	100%	03/11	KT
	Black Mastic (Black)		5%	Binders / Fillers	100%	•	
OMP04	Insulation (White)		100%	Synthetic Foam	100%	03/11	KT
OMP05	Insulation (White)		100%	Synthetic Foam	100%	03/11	KT
OMP06	Insulation (White)		100%	Synthetic Foam	100%	03/11	KT
		elikeli j					
				:			

ATTACHMENT D

COMPANY AND PERSONNEL DOCUMENTATION



TEXAS DEPARTMENT OF STATE HEALTH SERVICES

STEVE MOODY MICRO SERVICES, LLC

is certified to perform as a

Asbestos Laboratory PCM, PLM, TEM

in the State of Texas within the purview of Texas Occupations Code, chapter 1954, so long as this license is not suspended or revoked and is renewed according to the rules adopted by the Texas Board of Health.

DAVID LAKEY, M.D. COMMISSIONER OF HEALTH

License Number: 300084

Expiration Date: <u>5/31/2010</u>

Control Number: 95509

(Void After Expiration Date)

VOID IF ALTERED

NON-TRANSFERABLE





TEXAS DEPARTMENT OF STATE HEALTH SERVICES

SIGMA ENVIRONMENTAL SOLUTIONS, INC

is certified to perform as a

Asbestos Consultant Agency

in the State of Texas within the purview of Texas Occupations Code, chapter 1954, so long as this license is not suspended or revoked and is renewed according to the rules adopted by the Texas Board of Health.

DAVID LAKEY, M.D. COMMISSIONER OF HEALTH

License Number: 100410

Expiration Date: <u>5/29/2010</u>

Control Number: 96129

(Void After Expiration Date)

VOID IF ALTERED

NON-TRANSFERABLE

∑ SIGMA Environmental Solutions, Inc.

Rick D. Orr

Ricardo D. Orr Scientific Investigation **Texas Department of** & Instruction Institute Air Moultoring Technician **State Health Services** er" - Proposition Press Proposition (1995) Paris (1975) Position (1995) PACES Annual Opdate 11/9/2009 Expires: 11/9/2010 Asbestos Individual Consultant Cent. No.: -100.001.169.034 RICARDO D ORR License No. 105103 Control No. 95582 Expiration Date: 03/11/2010 ⁵ax 51±538 9192 :J | 612 328 5379 Individual Asbestos Consultant Air Monitoring Technician Expires: 11/9/10 Tx DSHS #10-5103 Expires: 3/11/10 Refresher Course Ricardo D. Orr Scientific Investigation Scientific investigation Ricardo D. Orc & Instruction Institute & Instruction Institute Design of ACBM Abstement Inspecting Buildings for ACBAI et " Response bless Comment (Sections) \$15 Annia (Section \$972) of Resident Part Construction, Some All A. Carlings INTO Projects Annual Update Annual Update 11/11/2009 11/10/2009 Expires: 11/11/2010 Cert. No.: 100.001.169.031 Expires: 11/10/2010 Cert. No.: 100,001,169,033 fax 512,338 9192 cil. 612 333 5379 fax 512,538 9192 pt. 512 338 5379 **Project Design** Expires: 11/10/10 **Building Inspector** Expires: 11/11/10 Refresher Course **Refresher Course** Scientific Investigation Ricardo D. Ort & Instruction Institute Managing ACBM is Buildings er i Romanners Peut Einer an inno Scott 120 Augus 14-122 18729 Annual Update 11/11/2009 Expires: 11/11/2010 Cert. No.: 100.001,169.032

fax 512,538 9192 pl | 513 338 5379

Expires: 11/11/10

Management Planner Refresher Course

Σ SIGMA	ENVIRO	NMENTAL	SOLUT	IONS.	INC.

CERTIFICATE OF COMPLETION
TO:. RAK One Main Place Associates, L.P. OWNER/Manager
PROJECT NAME: One Main Place 17 Floor Renovation
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202
LOCATION WITHIN BUILDING: Third (3 rd) Floor
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration, the National Institute for Occupational Safety and Health, and state, county, and local agencies.* The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
SIGNED: Sigma Authorized Representative
DATE: March 10, 2009

^{*} With the exception of floor tile and mastic under the safes in Room 124 and under the transformer in the electrical room in the west elevator foyer.

Σ SIGMA ENVIRONMENTAL SOLUTIONS, INC.
`
\cdot
CERTIFICATE OF COMPLETION
· · · · · · · · · · · · · · · · · · ·
TO: RAK One Main Place Associates, L.P. OWNER/Manager
Ownermanage:
PROJECT NAME: One Main Place 17 Floor Renovation
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202
LOCATION WITHIN BUILDING: Eighth (8 th) Floor
en de la companya de La companya de la co
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration, the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
SIGNED:
Sigma Authorized Representative
DATE: 5-/2-08

Σ SIGMA ENVIRONMENTAL SOLUTIONS, INC.
CERTIFICATE OF COMPLETION
TO: RAK One Main Place Associates, L.P.
OWNER/Manager
PROJECT NAME: One Main Place 17 Floor Renovation
PROJECT ADDRESS: 1201 Main Street, Dalles, Texas 75202
LOCATION WITHIN BUILDING: Ninth (9") Floor
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration, the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
SIGNED: Sigma Authorized Representative

11-13-08

DATE:

Σ SIGMA ENVIRONMENTAL SOLUTIONS, INC.
CERTIFICATE OF COMPLETION
TO: FAK One Main Place Associates, L.P. OWNER/Managel
PROJECT NAME: One Main Place 17 Floor Renovation
THOSE OF TANKE.
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202
LOCATION WITHIN BUILDING: Tenth (10 ^{tt}) Floor
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration, the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
SIGNED: Sigma Authorized Representative
DATE:

Σ SIGMA ENVIRONMENTAL SOLUTIONS, INC.
•
CERTIFICATE OF COMPLETION
TO: RAK One Main Place Associates, L.P. OWNER/Manager
PROJECT NAME: One Main Place 17 Floor Renovation
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202
LOCATION WITHIN BUILDING: Eleventh (11 th) Floor
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
SIGNED: Sigma Authorized Representative
DATE: 12-19-08

Σ SIGMA ENVIRONMENTAL SOLUTIONS, INC.	
,	
CERTIFICATE OF COMPL	ETION
	•
TO: RAK One Main Place Associates, L.P.	•
OWNER/Manager	
TYPO HOT RESERVE.	
PROJECT NAME: One Main Place 17 Floor Renovation	
DDO IDOT ADDDEGO, About Maria Office Dull To Athony	≟ `
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202	
LOCATION	
WITHIN BUILDING: Eighteenth (18 th) Floor	
The work for the above referenced project has been completed in according the United States Environmental Protection Agency, the Occupation	ordance with applicable requirements
the National Institute for Occupational Safety and Health, and state, on has also been performed in accordance with the Project Manual as pre-	ounty, and local agencies. The work
SIGNED:	•
Sigma Authorized Representative	
DATE: MARCH 03 2008	

DATE:

Σ SIGMA ENVIRONMENTAL SOLUTIONS, INC.
CERTIFICATE OF COMPLETION
TO: RAK One Main Place Associates, L.P.
OWNER/Manager
PROJECT NAME: One Main Place 17 Floor Renovation
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202
LOCATION
WITHIN BUILDING: Twenty-First (21st) Floor
The work for the above referenced project has been completed in accordance with applicable requirements
of the United States Environmental Protection Agency, the Occupational Safety and Health Administration
the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
/ K / / / / / / / / / / / / / / / / / /
SIGNED: Sigma Authorized Representative
DATE:

Σ SIGMA ENVIRONMENTAL SOLUTIONS, INC.
•
CERTIFICATE OF COMPLETION
TO: RAK One Main Place Associates, L.P.
OWNER/Manager
PROJECT NAME: One Main Place 17 Floor Renovation
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202
LOCATION
WITHIN BUILDING: Twenty-fifth (25th) Floor
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration, the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
SIGNED: Sigma Authorized Representative
DATE: <u>5-12-08</u>

Σ SIGMA, ENVIRONMENTAL SOLUTIONS, INC.
CERTIFICATE OF COMPLETION
TO: RAK One Main Place Associates, L.P.
OWNER/Manager
PROJECT NAME: One Main Place 17 Floor Renovation
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202
LOCATION WITHIN BUILDING: Twenty-sixth (26 th) Floor
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration, the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
SIGNED: Sigma Authorized Representative
DATE: 2-30.08

Σ ŚIGMA ENVIRONMENTAL SOLUTIONS, INC.	
_	
CERTIFICATE OF COMPLETION	
TO: RAK One Main Place Associates, L.P. OWNER/Manager	
Salien Statistical Co.	
PROJECT NAME: One Main Place 17 Floor Renovation	
nat .	
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202	
LOCATION WITHIN BUILDING: Twenty-ninth (29 th) Floor	
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration, the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.	
SIGNED: Sigma Authorized Representative	
DATE: 4-07-08	

S SIGMA ENVIRONMENTAL SOLUTIONS, INC.
CERTIFICATE OF COMPLETION
TO: RAK One Main Place Associates, LP. OWNER/Manager
Ownyernwanager .
PROJECT NAME: One Main Place 17 Floor Renovation.
PROJECT ADDRESS: 1201 Main Street, Dallas, Texas 75202
LOCATION WITHIN BUILDING: Thirty-first (31st 1) Floor
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration, the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
SIGNED: Signia Authorized Representative
DATE: MARCH 27, 2008

Σ SIGMA ENVIRONMENTAL SOLUTIONS, INC.
CERTIFICATE OF COMPLETION
TO: RAK One Main Place Associates, L.P.
OWNER/Manager
PROJECT NAME: One Main Place 17 Floor Renovation.
PROJECT ADDRESS: 1201 Main Street, Dailas, Texas 75202
LOCATION WITHIN BUILDING: Thirty-second (32") Floor
The work for the above referenced project has been completed in accordance with applicable requirements of the United States Environmental Protection Agency, the Occupational Safety and Health Administration, the National Institute for Occupational Safety and Health, and state, county, and local agencies. The work has also been performed in accordance with the Project Manual as prepared by the CONSULTANT.
Signa Authorized Representative
DATE: March 19, 2008

Fan Coil Unit Maintenance Procedures

- Check for water leaks, repair or replace if necessary.
- Check for air leaks, repair or replace if necessary
- Check power, repair or replace if necessary
- Check thermostat replace if necessary
- Check motor replace if necessary
- Check fan and housing repair or replace if necessary
- Check heat element replace if necessary
- Check chill water valve repair or replace if necessary
- Check pressure switch repair or replace if necessary
- Clean coils
- Clean motor
- Clean condensate pan
- Check insulation on condensate pan repair or replace if necessary
- Replace filters
- Clean grills

NOTE: DO NOT DISTURB ANY MASTIC OR PIPE WRAP. IF REPAIRS ARE NECESSARY AND IT INVOLVES ANY MASTIC OR PIPE WRAP, PLEASE GO TO THE PROPERTY MANAGER AND HAVE THEM CONTACT THE ENVIRONMENTAL CONSULTANT.

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 89 of 122 PageID 675

BANK OF AMERICA WORK ORDERS

2003

D-4-	Time of	Name of			1110.4		Tme	Service		Time	Landlords
Date	Call	Caller	Floor	Issue	WO#	Category	Dispatched	Tech	What Was Done	Completed	Comments
1/5/09	8:04 AM	C.Eaker	6	no power	B5008536-1	Lights	8:34 AM	(E8)/(E4)	replaced bulbs/ reports issue to (E4)	9:03 AM	Normal Maintenance
											Normal
1/5/09	11:13 AM	C. Eaker	6	no power	B5008536-1	Electricity	11:44 AM	(E4)	reports the breaker was off, now on	11:44 AM	Maintenance
1/5/09	10:21 AM	L. Rhodes	21_	to cold	B5008889-1	HVAC	10:22 AM	(E1)	reports temp to E1, reports temp was at 70, made adjustments on comp. to 72.	10:48 AM	Normal Maintenance
1/5/09	11:28 AM	A.Orozco	8	to cold	B5009209-3	HVAC	11:30 AM	(E7)	reports temp was 68, made adjustments to 70	11:59 AM	Normal Maintenance
											Normal
1/6/09	11:34 AM	D.Salazar	7	lights out	B5010842-2	Lights	11:34 AM	(E8)	reports replacing two lights in hallway	2:00 PM	Maintenance
1/6/09	1:11 PM	B.McElyea	25	to cold	B5010965-5	HVAC	1:15 PM	(E4)	reports temp on unit was at 70, made adjust. To 72 and reports issue to (E1) to check in comp.	1:33 PM	Normal Maintenance
1/7/09	11:08 AM	G. Smith	26	coffee maker not working	B5012294-3	Plumbinig	11:40 AM	(E4)	reports water was turned off and disattached to coffe maker due to item needing to be replaced.	2:38 PM	Tenant issue
											Normal
1/7/09	11:17 AM	S.Nguyen	4	lights out	B5012376-2	Lights	11:20 AM		reports replacing several flourescent lights	2:12 PM	Maintenance
1/7/09	12:12 PM	B.McElyea	25	hot	B5012518-1	HVAC	12:20 PM		reports temp was at 75, made adjustments to 73.	1:12 PM	Normal Maintenance
_1 <i>[7]</i> 09	12:16 PM	B.McEiyea	25	window unit leaking	B5012518-2	Leaks	12:36 PM	(E4)	window unit was leaking a little water, turned unit off to repair.now in use and ok	2:28 PM	Normal Maintenance
1/8/09	8:49 AM	S. Heller	6	lights out	B5013787-1	Lights	8:50 AM	(E8)	reports replacing several lights threw out the floor	9:30 AM	Normal Maintenance
1/8/09	1:25 PM	B.McElyea	25	to cold	B5014337-1	HVAC	1:30 PM		reports making a call to Divcon for the 25th floor. A call was also placed on the 1/7/09 to Divcon.	2:11 PM	Construction related
1/12/09	10:22 AM	R. Doss	6	lights out	B5017304-2	Lights	10:45 AM		reports lights in training room have been replaced	11:30 AM	Normal Maintenance
1/13/09	7:45 AM	T. Crain	21	to cold	B5018526-1	HVAC	7:45 AM		reports temp in area is 71 degrees, reports unit to (E1) to make adjustments	8:09 AM	Normal Maintenance
1/13/09	2:35 PM	R. Weeks	32	ceiling tile	B5019471-2	Leaks	2:38 PM	(E7)	reports replacing 1 stained ceiling tile	3:00 PM	Normal Maintenance
1/14/09	7:55 AM				B5019919-1	HVAC	8:15 AM		(E4) reports tracking down water leak that's coming from 9th fl. To 8th.and take care of the issue.	9:00 AM	Tenant issue
1/14/09	7:58 AM	D. Pyeatt	21	hot	B5019979-2	HVAC	8:17 AM		report the heat was on/ turned heat off and turned on the ac unit	8:33 AM	Normal Maintenance

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 90 of 122 PageID 676

1/14/09	8:08 AM	M. Hampton	OF.	loints alonged	B5020041-1	Plumbinig	9:00 AM	(E4)	reports unclogging kitchen sink, now water	0:24 414	7
1/14/09	8:08 AIVI	w. rampton	25	sink clogged	B5020041-1	Plumbing	9:00 AM	(24)	runs down drain no problem	9:34 AM	Tenant issue
1/14/09	1:00 PM	S. Brown	21	light cover	B5020651-1	Lights	1:05 PM	(J3)	reports replacing 1 light cover that was hanging	2:00 PM	Normal Maintenance
1/15/09	2:59 PM	P.Benford	26	food spill	B5022467-1	Janitorial	3:02 PM	(J2)	reports taking a broom/ dustpan for a food cleanup that spilled on carpet.	3:15 PM	Tenant issue
1/20/09	9:09 AM	D. Pyeatt	21	hot	B5019979-2	HVAC	9:10 AM	(E7) /(E1)	reports checked floor temp again still a little warm, (E7) reports unit to (E1) to make adjust. In comp.	9:21 AM	Normal Maintenance
1/20/09	9:05 AM	R.Weeks	32	no power	B5025203-2	Electricity	9:10 AM	(E5)	reports breaker was off, now back on	9:34 AM	Normal Maintenance
1/22/09	11:00 AM	R.Raasch	26	hot	B5028675-3	HVAC	11:01 AM	(E7)	reports making adjust. To the comp to turn off heat and turn on ac.	11:25 AM	Normal Maintenance
1/22/09	12:18 PM	B.McElyea	25	to cold	B5029054-3	HVAC	12:18 PM	(E7) /(E1)	reports eadt side of the fl. Needs to be adjust. By comp.,)E1) made adjust.	12:30 PM	Normal Maintenance
1/22/09	1:58 PM	B.McElyea	25	to cold	B5029501-1	HVAC	2:00 PM	(E7)	reports making adjust. To the comp	2:22 PM	Normal Maintenance
1/23/09	10:39 AM	K.Hogan	21	to cold	B5030104-1	HVAC	10:45 AM	(E1)	reports northwest side to (E1) as he made adjustments to the comp. to the whole west side was to hot	11:00 AM	Normal Maintenance
1/23/09	12:05 PM	B.McEiyea	25	to cold	B5030565-1	HVAC	12:10 PM	(E5)	reports adjusting vent above tenants dsk.	12:22 PM	Normal Maintenance
1/26/09	9:18 AM	L.Thompsom	21	lights blinking	B5031680-2	Lights	9:20 AM	(E8)	reports replacing blinkling lights on SW corner of fl.	11:15 AM	Normal Maintenance
1/26/09	9:38 AM	L.Thompsom	21	lights out	B5031680-2	Lights	9:40 AM	(E8)	operator reports call was sent out twice, call has already been taking care off	9:44 AM	Duplicate call
1/26/09	9:20 AM	J.Wafer	6	lights out	B5031813-4	Lights	9:22 AM	(E8)	reports lights have bern replaced	10:00 AM	Normal Maintenance
1/26/09	10:49 AM	G.McNealis	6	toilet clogged	B5032196-2	Plumbing	11:23 AM	(E4)	reports tissus was clogging up the toilet, now unclogged	11:54 AM	Normal Maintenance
— 1/26/09	12:49 PM	B.McElyea	25	hot	B5032247-2	HVAC	1:00 PM	(E1)	reports talking with Brenda on 1/23/09 about the HVAC problem, (E1) informed her that the building is building standard temp, there nothing more we can do at this point.again on 1/26/09	1:00 PM	No Problem
1/27/09	8:58 AM	T. LaMere	21	to cold	B5033417-1	HVAC	9:00 AM	(E4)/(E1)	(E4) reports a few units are off and not working from 21st fl. To 25th fl(E1) contacts Divcon and inform them of whats goin on with ac units.	9:28 AM	Construction related

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 91 of 122 PageID 677

1/29/09	9:00 AM	B.McElyea	25	to cold	B5037365-1	HVAC	9:10 AM	(E5)	reports temp. 70 on SE, 1/28/09 Divcon was reports working on units, units are still not working. (E5) reports closing a few vents til ac unit is adjusted.	9:40 AM	Construction related
1/30/09	9:39 AM	R.Weeks	32	ac unit is noise	B5038772-2	HVAC	10:39 AM	(E6)	unit had loose bolts coming from unit, bolts has been tightened and now no rattling noise	11:00 AM	Normal Maintenance
2/2/09	1:35 PM	R.Doss	6	MR Door handle	B5040425-2	Doors & Locks	2:00 PM	(E7)	replaced plunger on door	2:21 PM	Normal Maintenance
2/3/09	8:51 AM	T.Houchins	21	hot	B5041681-1	HVAC	· 8:51 AM	(E5)	reports ac unit on nortwest side was adjusted	9:10 AM	Normal Maintenance
2/3/09	10:31 AM	B.McElyea	25	hot	B5042049-1	HVAC	10:31 AM	(E1)	reports making adjust. To the comp.	10:35 AM	Normal Maintenance
2/6/09	7:45 AM	S.Payne	8	hot	85046224-1	HVAC	8:27 AM	(E5)	reports temp was at 75, set thermo. To 73	9:00 AM	Normal Maintenance
2/9/09	8:41 AM	S.Heller	6	lights out	B5047391-2	Lights	8:45 AM	(E8)	reports replacing 3 lights out on south side	9:08 AM	Normal Maintenance
2/9/09	12:00 PM	R.Weeks	32	cold	85048509-2	HVAC	12:02 PM	(E5)	reports unit temp is at 72, set temp to 75	12:15 PM	Normal Maintenance
2/10/09	3:48 PM	C.Leeth	32	hot	B5049797-1	HVAC	3:50 PM	(E7)	reports making adjust. To the comp.	4:12 PM	Normal Maintenance
2/11/09	12:16 PM	N.Szymczyk	6_	hot	B5051688-1	HVAC	1:00 PM	(E4)	reports setting thermo. To 73, temp was at 71	1:12 PM	Normal Maintenance
2/12/09	1:08 PM	A.Orozco	8	coid	B5053448-2	HVAC	1:10 PM	(E5)	reports window unit was off/ turned heat on	1:33 PM	Normal Maintenance
2/13/09	9:21 AM	N.Szymczyk	6	hot	B5054470-1	HVAC	10:00 AM	(E7)	reports set temp is at 77.8,dropped to 73	10:51 AM	Normal Maintenance
2/13/09	12:51 PM	S.Parlin	6	hot	B5054902-1	HVAC	12:55 PM	(E4)	reports unit was off, turned unit on	2:06 PM	Normal Maintenance
2/17/09	9:02 AM	B.McElyea	25	keys	B5056005-2	Keys	9:02 AM	(E7)	reports key is still on construction cord.	9:51 AM	Construction related
2/17/09	9:23 AM	R.Hakul	21	hot	B5056050-1	HVAC	9:35 AM	(E4)	reports temp tp (E1), he made adjust. Tp comp.	10:03 AM	Normal Maintenance
2/19/09	4:46 PM	R.Doss	6	lights out	B5058744-2	Lights	4:50 PM	(E8)	reports taking care of those light at 9:40.WO just came thru at 17:46	4:50 PM	Normal Maintenance
2/19/09	8;49 AM	R.Weeks	32	dust	85059111-1	Janitoria!	8:50 AM	(J1) .	reports area in ass. Hub has been cleaned	9:06 AM	Normal Maintenance
2/19/09	1:59 PM	B.McElyea	25	cold	B5059822-1	HVAC	2:00 PM	(E7)	reports making adjust. To the comp.	2:12 PM	Normal Maintenance
2/20/09	8:08 AM	S.Payne	8	hot	B5060376-1	HVAC	8:10 AM	(E7)	temp 74,made adjust to 72 in comp.	8:15 AM	No Problem
2/23/09	10:19 AM	B.McElyea	25	hot	B5062591-1	HVAC	10:26 AM	(E4)	reports unit to (E1), made adjust. To comp	10:26 AM	Normal Maintenance

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 92 of 122 PageID 678

BANK OF AMERICA WORK ORDERS

200ま

			7			·	,				
2/24/09	4:04 PM	B.McElyea	25	cold	B5064958-1	HVAC	4:04 PM	(E5)	reports temp to (E1) ,make adjust. To comp.	4:16 PM	Normal Maintenance
2/26/09	8:35 AM	R.Weeks	32	hot	B5066804-1	HVAC	8:38 AM	(E5) (E7)	(E5) reports unit to (E7) to make adjust to comp	9:00 AM	Normal Maintenance
2/26/09	3:22 PM	A.Haddox	21	vent blowing to hard	B5067862-1	HVAC	3:33 PM	(E7)	reports closing vents slightly so air will not blowo hard.	3:50 PM	Normal Maintenance
3/2/09	11:10 AM	B.McElyea	25	hot	B5070465-2	HVAC	12:10 PM	(E5)	reports temp to (E1) ,make adjust. To comp.	12:15 PM	Normal Maintenance
3/3/09	10:42 AM	S.Payne	8_	LR running toilet	B5071852-2	Plumbing	10:42 AM	(E4)	reports toilet was stopped up, toilet stop running	11:00 AM	Normal Maintenance
3/3/09	12:31 PM	C.Morones	26	vent blowing to hard	B5072148-2	HVAC	12:35 PM	(E7)	reports adjusting the vents over 26.153	1:00 PM	Normal Maintenance
3/5/09	2:36 PM	R,Murray	18	noise	85075733-1	Security	2:50 PM	(S2)	reports security went to invest, Found nothing	3:00 PM	No Problem
3/6/09	8:55 AM	R.Murray	25	clean up	B5076375-1	Janitorial	8:55 AM	(J2)	reports spill on floor was cleaned up	9:10 AM	Tenant issue
3/10/09	8:36 AM	T.Houchins	21	tissue	B5079685-1	Janitorial	9:00 AM	(J2)	reports tissue has been restocked	9:18 AM	Normal Maintenance
3/10/09	8:40 AM	K.Harsha	32	hot	B5079763-1	HVAC	8:50 AM	(E4)	reports large conference room has been adjust.	9:00 AM	Normal Maintenance
3/10/09	3:55 PM	J.Walling	6	LR/soap despenser	B5080825-1	Janitorial	3:55 PM	(J2)/(E7)	(E7)replaced the despencer,cleanup is done.	4:12 PM	Normal Maintenance
3/11/09	4:30 PM	B.McElyea	25	cold	B5081829-2	HVAC	4:32 PM	(E6)	reports temp to (E1) ,make adjust. To comp.	4:45 PM	Normal Maintenance
3/11/09	12:56 PM	J.Altmann	29	cold	B5082027-1	HVAC	1:27 PM	(E6)	reports closing vents slightly	4:00 PM	Normal Maintenance
3/13/09		J.Crawley	8	cold	B5084864-1	HVAC	11:55 AM	(E70	reports adjusting temp in comp.	12:13 PM	Normal Maintenance
3/13/09	2:54 PM	S.Heller	6	trash	B5085074-1	Janitorial	2:54 PM	(J2)	reports picking up trash	3:05 PM	Tenant issue
3/18/09	8:04 AM	A.Walling	6	MR Door donot lock	B5089286-2	Doors & Locks	8:06 AM	, ,	reports door has reader locks/waiting for Bud	8:46 AM	Tenant issue
3/18/09	8:49 AM	S.Richards	6	hot	B5089647-2	HVAC	8:49 AM	(E1)/ (E5)	(E1) made adjust. In comp.(E5) adjust, Thermo.	9:16 AM	Normal Maintenance
3/19/09	11:43 AM	I.Ramirez	6	lights out	B5091478-2	Lights	11:45 AM	(E7)	reports no power, breaker was flipped	12:00 PM	Normal Maintenance
3/23/09	4:49 PM	J.Altmann	29	cold	B5082027-3	HVAC	4:49 PM	(E6)	reports making adjust to thermo.(E1)make adjust to the comp.	4:59 PM	Normal Maintenance
3/23/09	9:01 AM	J.Blair	6	clean up	B5094619-1	Janitorial	9:01 AM	(J4)	reports water on floor was wipped up.	9:23 AM	Tenant issue
3/23/09	11:41 AM	A.Orozco	8	lights out	B5094709-2	Lights	11:41 AM		replaced what he could, order the rest, inform bud due to lights needed trewout dept.	2:26 PM	Normal Maintenance
3/24/09	12:46 PM	C.Morones	6	spill	B5096964-1	Janitorial	12:51 PM	(J4)	reports someone waste water on the carpet	1:00 PM	Tenant issue

App. 267

7.1

3/24/09	12:38 PM	C.Morones	26	tissue	B5096964-2	Janitorial	12:38 PM	(J4)	reports restrooms are fully stocked with tissue	12:51 PM	Normal Maintenance
3/26/09	9:52 AM	C.Morones	26	waterin carpet	B5099720-1	Janitorial	9:52 AM	(J4) / (E4)	,(J4) wet vacuum while (E4) take care of condensation.	10:15 AM	Normal Maintenance
3/27/09	3:26 PM	C.Morones	26	stain	B5099720-1	Janitorial	3:33 PM	(J2) / (E6)	(E6) reports the stain to the evening cleaning crew to be cleaned(J2) reports stain has been taking care of	3:33 PM	Tenant issue
3/27/09	4:40 PM	I.Ramirez	6	lights out	B5101972-3	Lights	8:03 AM	(J3)	Replaced lights	8:17 AM	Normal Maintenance
3/27/09	6:55 PM	l.Ramirez	6	lights out	B5101972-3	Lights	6:55 PM	(J3)	after hour call was taking care of on 3/28	8:17 AM	Normal Maintenance
3/30/09	3:25 PM	A.Walling	6	stairwell door	B5102873-2	Doors & Locks	3:25 PM	(E7)	reports this issue with Bud to work out a plan.Per Bud	3:48 PM	Tenant issue
4/1/09	11:04 AM	S.Nguyen	4	lights out	B5012376-3	Lights	11:33 AM	(J4)	reports lights hav been replaced	12:44 PM	Normal Maintenance
4/1/09	6:01 AM	B.McElyea	25	cold	B5105551-2	HVAC	8:24 AM	(E5)	reports temp on fl.is 70, (E1) can't make adjust. Due to comp. having a problem.	8:32 AM	Normal Maintenance
4/6/09	8:48 AM	A.Orozco	8	toilet over flow	B5110772-4	Plumbing	8:51 AM	(E5)	reports to Ron w/Cbre to replace batteryin diaphragm	9:00 AM	CBRE
4/7/09	8:50 AM	T.Smith	29	water leak	B5111358-2	Leak	9:10 AM	(E4)	reports taking care of leak at cubicle29-167	8:40 AM	Normal Maintenance
4/8/09	11:04 AM	S.Collins	26	cold	B5113904-1	HVAC	11:04 AM	(E7)	reports making adjustments	11:24 AM	Normal Maintenance
4/8/09	11:57 AM	S.Heller	6	bugs	B5113956-1	Terminix	11:57 AM	(A5)	reports pest problem in Terminix work book	12:24 PM	Normal Maintenance
4/9/09	2:44 PM	S.Heller	6	lights out	B5113960-2	Lights	3:00 PM	Bud Sills	reports construction is going on that fl,	3:00 PM	Normal Maintenance
4/10/09	4:14 PM	S.Payne		time	B5116041-2	Elevators	4:14 PM	(A5)	elevators are allways running except to the const. fl.	4:15 PM	Elevator
4/11/09	10:25 AM	B.McElyea	25	lights out	B5116338-2	Lights	10:25 AM	3	reports replacing one light.	10:52 AM	Normal Maintenance
4/14/09	9:02 AM	R.Murray	19	elevators	B5119366-1	Elevators	9:02 AM	(S2) / 18	(S2) reports scratches on the elev. Doors on 19	9:46 AM	Elevator
4/20/09	7:26 AM	K.Smith	8	clean up	B5124755-2	Janitorial	7:26 AM	(J4)	reports cleaning LR and the small break room	8:20 AM	Tenant issue
4/22/09	10:04 AM	G.Whalen	6	lights out	B5120595-2	Lights	10:04 AM		reports replacing a few lights	10:34 AM	Normal Maintenance
4/22/09	12:40 PM	D. Thompson	6	stained carpet	B5126712-2	Janitoria!	12:40 PM	(J2)	reprots the night cleaning crew took care of that stain	8:04 AM	Tenant issue
4/23/09	2:48 PM	B.McElyea	26	request for air	B5130536-2	HVAC	2:48 PM	(E1)	(E1) contacts B.McEylea to talk about night HVAC	2:50 PM	BofA request
4/24/09	1:21 PM	C.Davis	6	cold	B5131630-2	HVAC	1:21 PM		reports making adjust, To thermo. (E1) adjust by comp.	1:43 PM	Normal Maintenance

	1	T	T	1	T .	<u> </u>		1	inroute to secure fire alarm cover that has		
4/24/09	1:49 PM	R.Murray	8	Fire Alarm pull open	B5132023-1	Security	1:49 PM	(S2)	come lose	3:15 PM	Security
4/24/09	2:51 PM	R.Murray	18	noise	B5132023-2	HVAC	2:55 PM	(E7)	reports vent was slitly closed making a wistling soundent was open and now no noise	3:25 PM	Normal Maintenance
4/27/09	1:32 PM	P.Benford	26	leak	B5134126-2	Leak	1:32 PM	(E5)	reports vent is leaking due to condensation	1:52 PM	Normal Maintenance
4/28/09	3:15 AM	B.McEylea	26	Vents are loud	B5131900-2	HVAC	3:15 AM	Security	This call came in at 3am/at 8am reports theres nothinge can do due to the kind of vents they have placed on the fl.	3:15 AM	Construction related
4/28/09	3:44 PM	B.McElyea	26	odor	B5135801-2	Odor	3:44 PM	(E6)	reports no water in sewage drain so when a breeze comes threw, the odor carries, (E6) put water in drain	4:00 PM	Normal Maintenance
4/29/09	9:55 AM	A.Orozco	8	lights out	B5137159-1	Lights	9:55 AM	(J3)	reports replcing several lights out threwout the lobby	11:00 AM	Normal Maintenance
4/29/09	9:56 AM	A.Orozco	8	hot	B5137159-2	HVAC	9:56 AM	(E5)	(E5) can't make adjust due to graphics on 33/informed (E1)	10.40 AM	Construction related
5/4/09	3:25 PM	Doreen Honza	32	Leak in ceiling was dripping in a bucket, bucket was knocked over needs clean up	B5142814-1	Janitorial	3:53 PM	E6 & E7	tracing out problem	4:00 PM	Normal Maintenance
5/4/09	3:26 PM	D.Honza	32	leak	B5142814-2	Leak	3:26 PM	(E6) / (E7)	reports working together on leak that are in two sepearate spots, Bud Sills is disussing this issue with (E1) and (A2)	4:27 PM	Normal Maintenance
5/6/09	12:59 PM	E. Ruthart	11	coid	B5143951-3	HVAC	12:59 PM	(E5)	reports close vent over tenat desk.	9:49 AM	Construction related
5/6/09	9:01 AM	M.Craig	11	over flow	B5145058-1	Plumbing	9:01 AM	(E5) / (J2)	reports toilet unstopped. (J2) is now working on clean up	9:45 AM	Normal Maintenance
5/6/09	1:50 PM	R.Gore	6	no power	B5145860-1	Electricity	1:50 PM	(E5) / (J3)	reports power is off/ flip breaker and (J3) replace several lights that were out	2:25 PM	Normal Maintenance
5/6/09	4:35 PM	A.Orozco	8	bugs	B5146202-2	Terminix	4:35 PM	(A5)	reports pest problem in the Terminix book for the 8th fl.	4:35 PM	Normal Maintenance
5 <i>/7/</i> 09	3:28 PM	C.Fatima	11	cold	B5147051-2	HVAC	3:28 PM	(E1)	made adjust. In the comp.	4:15 PM	Construction related
5/8/09	3:20 PM	B.McElyea	25	hot	B5149346-2	HVAC	3:20 PM		adjust. Thermostat and reported temp to (E1) to make adjust	3:47 PM	Normal Maintenance
5/10/09	9:00 AM	E.Ruthart	11	cold	B5146178-2	HVAC	9:00 AM	(E7)	reports weekend call, already taking care of.	9:00 AM	Normal Maintenance
5/11/09	9:23 AM	C.Fatima	11	cold	B5147051-2	HVAC	9:23 AM	(E1)	made adjust. In the comp.	9:23 AM	Construction related
5/12/09	9:00 AM	B.McElyea	25	hot	B5149325-2	HVAC	9:00 AM	(E7)	reports made adjust, on the comp.	9:18 AM	Normal Maintenance

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 95 of 122 PageID 681

		7	7	1			1	T			· · · · · · · · · · · · · · · · · · ·
5/12/09	6:01 AM	F.Liefer	26	wet spot	B5150966-2	Janitorial	8:09 AM	(J2)	reports engineers are done put vent back up/clean wet spot	8:35 AM	Normal Maintenance
5/12/09	9:05 AM	R.Useiton	10	hot	B5151977-1	HVAC	9:07 AM	(E4)	replaced P.E switch on unit	9:27 AM	Normal Maintenance
5/12/09	8:00 AM	J.Falger	21	restock	B5152204-2	Janitorial	8:00 AM	(J2)	restock the paper towles in kitchen area	8:38 AM	Normal Maintenance
5/13/09	2:00 PM	J.Begue	25	cold	B5154590-1	HVAC	2:29 PM	(E7)	reports adjust. Tmp in the comp. temp was at 68	2:49 PM	Normal Maintenance
5/14/09	9:00 AM	P.Grace	26	leak	B5155369-1	Leak	9:03 AM	(E4)	reports tracking water leak,coming from window unit/now off	9:23 AM	Normal Maintenance
5/14/09	11:12 AM	B.McElyea	26	oder	B5155605-2	HVAC	11:12 AM	(E7)	reports the heating elements I the unit was coming on	11:22 AM	Normal Maintenance
5/16/09	8;00 AM	E.Ruthart	11	cold	B5156485-2	HVAC	8:18 AM	(E7)	reports temp was adjusted by comp.	8:28 AM	Construction related
5/18/09	3:25 PM	B. Rogers	9	cold	B5159166-2	HVAC	3:25 PM	(E7)	reports the temp was at 72, adjust. To 74	3:45 PM	Normal Maintenance
5/19/09	9:35 AM	A.Orozco	8	ights out	B5161323-4	Lights	9:35 AM	(J3)	reports replacing several lights threwout the floor.	10:00 AM	Normal Maintenance
5/22/09	7:36 AM	K.Harsha	32	keys	B5163228-3	Keys	7:36 AM	(E7)	reports work order to (E7) per Bud Sills need this key for K128	8:00 AM	BofA request
5/22/09	8:10 AM	C.Morones	26	spill	B5164474-2	Janitoria!	8:10 AM	(J2)	reports spill was cleaned up	8:28 AM	Tenant issue
5/22/09	8:28 AM	R.Uselton	10	power	B5165091-2	Electricity	8:28 AM	(A5)	reports this to Rena, was not aware that Bud was not at work Rena will inform Bud when he come in.	8:28 AM	Construction related
5/26/09		E.Ruthart	11	cold	B5168060-1	HVAC	3:23 PM	(E7)	adjusted temp.in the comp.	3:49 PM	Construction related
5/27/09	4:00 PM	M.Craig	11	clogged toilet	B5168835-2	Plumbing	4:00 PM	(E6)	reports running a snake threw the drain, toilet unclogged	4:20 PM	Normal Maintenance
5/27/09	10:13 AM	B.Rogers	10	clogged toilet	B5169012-1	Plumbing	10:13 AM	(E4) / (A2)	reports running a snake threw the drain, toilet unclogged	11:44 AM	Normal Maintenance
5/29/09	8:17 AM	B.McElyea	25	hot .	B5171386-2	HVAC	8:17 AM	(E7)	adjusted temp.in the comp. temp on fl,74	8:43 AM	Normal Maintenance
6/1/09	7:34 PM	M.Hiser	9	toilet not flush	B5175014-2	Plumbing	7:34 PM	(E4)	reports replacing the washers in the MR on toilet on 6/2/09	8:00 AM	Normal Maintenance
6/2/09	4:50 PM	K.Denton	21	hot	B5176588-1	HVAC	4:50 PM	(E6)	reports unit is not working/ reports unit was turned off	5:00 PM	Normal Maintenance
6/3/09	8;53 AM	S.Richards	6	lights out	B5176994-1	Lights	9:00 AM		reports replacing several lights threwout the floor.	10:00 AM	Normal Maintenance
6/3/09	4:44 PM	R.Foreman	10	no cold water	B5178290-1	Plumbing	4:55 PM	(E6)	Buds knows the hot and cold water is working and water pressure is up.(E6) reproted it to Bud himself 6-4-09	8:34 AM	Normal Maintenance

2009 Case 3 BANK OF AMERICA WORK ORDERS

		1					T		(J3) replaced several lights threwout the fl.		Normal
6/5/09	1:47 AM	K.Harsha	32	lights out	B5179419-2	Lights	1:47 AM	(J3)	On 6/8/09, weekend	1:47 AM	Maintenance
		 	1			 -		 -	reset vent, everything is working ok. No		Normal
6/8/09	3:33 PM	C.Brantley	9	noise	B5181628-2	HVAC	3:33 PM	(E6)	noise	4:06 PM	Maintenance
6/8/09	3:01 PM	B.McElyea	26	spill	B5183709-1	Janitorial	3:01 PM	(J4)	reports the spill has been mopped up	3:23 PM	Tenant issue
	-								reports unit is making a humming noise, unit		Normal
6/8/09	3:53 PM	M.Craig	11_	noise	B5183877-1	HVAC	3:53 PM	(E7)	is fine just a little loud	4:10 PM	Maintenance
04000	4.00 514		١,,,		DE470500 4	1,,,,,	100 87	(=0.			Normal
6/10/09	4:29 PM	K.Denton	21	hot	B5176588-1	HVAC	4:29 PM	(E6)	reports to (E1) to adjust in comp.	4:43 PM	Maintenance
6/10/09	2:37 PM	K.Disque	21	lock jamed	B5187400-1	Doors & Locks	2:37 PM	(E7)	reports door lock was stuck, door now open	3:00 PM	Normal Maintenance
0/10/03	2.57 [10]	IX.Disque		lock james	150101400-1	LOCKS	2.37 FW	(=1)	reports door lock was stuck, door now open	3.00 PW	Normal
6/11/09	4:54 PM	S.Richards	6	hot	B5189496-1	HVAC	4:54 PM	(E1)	reports to (E1) to adjust in comp.	5:00 PM	Maintenance
			 					(= 1)	(=0) == == (=0)		Normal
6/11/09	4:41 PM	C.Morones	26	hot	B5189499-1	HVAC	4:41 PM	(E1)	reports to (E1) to adjust in comp.	4:45 PM	Maintenance
		Sandra	T								Afterhours
6/11/09	9:46 PM	Richards	6	Too hot	B5189509-2	HVAC			Afterhours call, AC is off	·	call
		L									Normal
6/11/09	9:44 PM	Toni Martin	18	Too hot	B5189572-2	HVAC	10:03 AM	(E7)	made adjust. To exterior unit	10:24 AM	Maintenance
6/11/09	5:42 DM	A.Orozco	8	hot	B5189591-1	HVAC	5:43 PM	(E1)	reports to (E1) to adjust in comp.	4:49 PM	Normal Maintenance
0/11/03	J.43 F W	7.010260	 -	TIOL	55168591-1	TIVAC	3.43 FW	(E1)	afterhours call when arrived on floor area	4.45 F W	Maintenance
6/11/09	10:12 PM	S.Tumbry	10	hat	B5189649-2	HVAC	10;12 PM	(E4)	was cool	10:12 PM	No Problem
					· · · · · · · · · · · · · · · · · · ·	Doors &					Normal
6/12/09	9:14 AM	R.Murray	4&7	door jamed	B5184821-1	Locks	9:29 AM	(E7)	reports doors has been taking care off	11:01 AM	Maintenance
6/12/09	11:35 AM	B.McElyea	25	stain	B5190379-2	Janitorial	11:39 AM	(J2)	already on fl. Cleaning carpet	11:42 AM	Tenant issue
							, ,	_	Security inform 18 of the elevator		
6/12/09	12:47 PM	R.Foreman	11	elev. #11	B5190589-1	Elevator	12:47 PM	18	entrapment	12:47 PM	Elevator
640/00	C.CD ALA	D Machine	7	d ()	B5190526-2	Doors &	8:08 AM	(C7)	language descriptions of	0.00 444	Normal
6/13/09	8:08 AM	B.McElyea		door locked	B3190320-2	Locks	0:00 AIVI	(E7)	reports door is now unlocked reports pest problem in the Terminix book'	8:20 AM	Maintenance Normal
6/16/09	12:59 PM	B Rogers	9	Bugs	B5192959-2	Terminix	12:59 PM	(A5)	for the 9th fl.	12:59 PM	Maintenance
0/10/03	12,00 191	D. Nogels		Duga .	D0102000 2	TOTTONIA	12001111	(1.0)	tor the out it.	12001111	Normal
6/17/09	12:38 PM	B.McElyea	26	hot	B5196359-1	HVAC	12:38 PM	(E7)	made adjust, in the comp.	1:00 PM	Maintenance
				· · · · · · · · · · · · · · · · · · ·				<u> </u>			Normal
6/17/09	2:00 PM	T.Houchins	21	LR mopped	B5196957-1	Janitorial	2:00 PM	(J2)	reports mopping up water on the floor.	2:00 PM	Maintenance
									reports fixed problem temp was 80, now at	_	Construction
6/22/09	1:22 PM	D.Thayer	10	hot	B5201806-1	HVAC	1:22 PM	(E6)	75/74	2:00 PM	related
000000	0.20	C \4.0-1	ا ہا	 -	DEDOCCOE C	ni	9.00 44	/E 4\		0.00 444	Normal
6/22/09	8:30 AM	G.Whalen	6	leak	B5201905-2	Plumbing	8:30 AM	(E4)	reports toilet unclogged	9:00 AM	Maintenance Normal
6/22/09	2:51 PM	K Denton	21	cold	B5202637-1	HVAC	2:51 PM	(E6)	reports temp was adjusted by comp.	2:51 PM	Maintenance
3,22,00	, 1141	,			2020201-1	.,,,,,	2.011111	(/	- Alexander		

App. 2/

6/23/09	9:26 AM	A.Orozco	8	bugs	B5204509-2	Terminix	9:26 AM	(A5)	reports pest problem in the Terminix book for the 8th fl.	9:26 AM	Normal Maintenance
6/23/09	12:38 PM	B.McElyea	26	hot	B5204836-1	HVAC	12:38 PM	(E1)	reports heat issue to Tom w /Divcon on property	1:06 PM	Construction related
6/23/09	4:02 PM	N.Wafer	6	hot	B5205494-2	HVAC	4:02 PM	(E7)	reports made adjust, on the comp.	4:02 PM	Normal Maintenance
6/23/09	4:04 PM	C.Edwards	18	cold	B5205514-1	HVAC	4:04 PM	(E1)	made adjust. In the comp.	4:04 PM	Normal Maintenance
6/24/09	8:30 AM	D.Honza	32	hot	B5206033-1	HVAC	8:36 AM	(E1)	made adjust. In the comp.	8:36 AM	Normal Maintenance
6/24/09	9:26 AM	T.Martin	18	hot	B5206235-1	HVAC	9:26 AM	(E6)	made adjust. To exterior unit	9:26 AM	Normal Maintenance
6/24/09	11:21 AM	R.Foreman	11	hot	B5206481-1	HVAC	11:21 AM	(E7)	reports turning on the pneumatic valves to turn on the other 3 valves	11:55 AM	Construction related
6/24/09	8:08 AM	S, Heller	6	hot	B5207371-2	HVAC	8:08 AM	(E4)	reports adjust. The thermostat and reporting temp to (E1)	8:08 AM	Normal Maintenance
6/25/09	9:35 AM	N.Wafer	6	hot	B5205494-2	HVAC	9:35 AM	· (E4)	made adjustments to 3 thermostats	9:35 AM	Normal Maintenance
6/25/09	12:22 PM	B.Rogers	9	hot	B5208132-1	HVAC	12:22 PM	(E6)	reports temp was adjusted by comp by (E1)	12:22 PM	Normal Maintenance
6/26/09	1:33 PM	S. Taylor	10	cleaning	B5210109-1	Janitorial	1:33 PM	(J2)	reports mopping and cleaning rest room	1:33 PM	normal Maintenance
6/27/09	4:52 AM	C.Brantley	9	ac not on	B5209298-2	HVAC	4:52 AM	After hours	ac unit was not on/ unit came on around noon	4:52 AM	Construction related
6/30/09	2:23 PM	B.McElyea	26		B5213981-1	HVAC	2:23 PM	(E6)	closed the vent directly over tenants head	3:26 PM	Normal Maintenance
7/1/09	1:03 AM	Jacqueline Nicholson	6	Replace burned out ceiling lights in several places	B5214709-2	Lights	1:07 PM	J3	Replaced lights	1:46 PM	Normal Maintenance
7/1//09	11:31 PM	Lueila Telker	29	New deodorizers installed in restrooms are too strong. Causing allergic reactions.	B5231619-2	CBRE	9:14 AM	E 7	CBRE installed deodorizers. Turned back over to Bud Sills with CBRE	9:20 AM	CBRE
7/8/09		Elayn Ruthart	11	Whistling sound coming from air vent and knocking sound from above	B5223494-2	Noise	8:17 AM	E7	Couldn't hear anything. Might have been from contractors working last night.	8:25 AM	Construction related
7/13/09		Leticia Flores	3	Adjust temps in training	B5227315-1	HVAC	8:05 AM	E1	Have issues with EMS and BofA software	8:15 AM	Construction related
7/13/09	7:34 AM	Ron Murry	9	Repair window AC units NW side of floor	B5227393-1	HVAC	8:05 AM	E1	Made adjustments on computer	8:20 AM	Normal Maintenance

7/4 4/00	7:00 D14	Leticia	2	Adjust temps in training	BE207245 4	LD (AC	0:07 414	F4	AQ is about down of the table.		Afterhours
7/14/09	7:32 PM	Flores Cindy	3	rooms all are too hot 2nd Stall won't flush in	B5227315-4	HVAC	8:07 AM	E1	AC is shut down at that time.	<u> </u>	call
7/14/09	12:39 PM		21	ladies rest room	B5230176-1	CBRE	8:40 AM	E4	Turned back over to CBRE engineering	8:40 AM	CBRE
7/14/09	9:20 PM	Kisha Brown	Lobby	Overtime air request for air for Banking Center	B5230545-2	HVAC			Wrong building		Wrong building
7/14/09	3:57 PM	David Estes	8	Unpleasant smell on floor	B5230649-1	Odor	4:16 PM	E6	Plate burned in microwave on 23rd floor	4:40 PM	Cause by other tenant
7/14/09	5:14 PM	Jaames Robbins	10	Unpleasant smell throughout floor	B5230775-2	Odor	8:05 AM	Janitorial	Found no smell	8:15 AM	Unkown
7/15/09	1:39 PM	Doreen Honza	32	Repair pipe that is leaking in ceiling	B5232016-1	Leak	1:45 PM	E7	Traced out pipe to 34th floor shut off water and repaired leak	3:44 PM	Normal Maintenance
7/15/09	2:00 PM	Doreen Honza	32	Clean up water on floor in the lab	B5232016-3	Janitorial	2:18 PM	J2	Cleaned up water	2:35 PM	Normal Maintenance
7/15/09	11:19 PM	Barbara Rogers	10	Spot clean floor - It appears that there is blood on the floor	B5232185-2	Janitorial	3:00 PM	J2	Passed on to night crew	3:05 PM	BofA request
7/16/09	1:02 PM	Jacqueline Nicholson	6	Replace burned out ceiling lights in several places	B5214709-2	Lights	3:12 PM	J3	Lights will be replaced first thing in the morning	9:00 AM	Normal Maintenance
7/16/09	11:20 PM	Barbara Rogers	9	Spot clean spill in front of glass doors	B5232190-2	Janitorial	3:01 PM	J2	Passed on to night crew	3:05 PM	BofA request
7/16/09	2:16 PM	Sharyn Nguyen	32	Puddles of water on floor, please mop up. Maybe from ceiling?	B5233886-2	Janitorial	2:18 PM	J2	Mpped up spills	2:35 PM	BofA request
7/18/09	1:48 PM	Martella Craig	10 & 11	After hours air on Monday 7/20/09 and Thursday 7/23/09 from 7pm till midnight	B5234263-2	HVAC	2:00 PM	E 1	Put run times in computer	2:15 PM	BofA request
7/20/09	11:23 AM		3	Florida and Texas conference rooms are too cold	B5236918-1	HVAC	11:30 AM	E6	E6 checked floor. E7 couldn't change set points due to no graphics. E1 reports problem to Divcon at 12:13 PM	12:13 PM	Construction related
7/20/09	1:43 PM	Elayn Ruthart	11		B5237473-1	HVAC	3:00 PM	E6	Made adjustments on computer. Having issues with BofA software	3:25 PM	Construction related
7/21/09	1:38 PM	Brenda McElyea	26	AC making loud noise in southwest corner by Christine Chicosky	B5239041-1	HVAC	4:17 PM		Tightened FCU cover	4:28 PM	Normal Maintenance
7/28/09	3:09 PM	Leticia Flores	3	Cold in conference and training center	B5248461-1	HVAC	3:31 PM		Reported problem to E1 Divcon is working on it	3:40 PM	Construction related
7/28/09	11:56 PM	Barbara Rogers	9	Location 09-177 is cold	B5248555-1	HVAC			HVAC off at that time.		Afterhours call

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 99 of 122 PageID 685

7/29/09	10:38 AM	Leticia Flores	3	Georgia and Maryland	B5249437-1	HVAC		E 7	Reported problem to E1 Divcon is working on it. Called divcon		Construction related
7/29/09	8:08 AM	Cindy Neinast	21	Very cold in SE corner in the cubes away from the windows		HVAC	8:35 AM	E7	HVAC off at that time. Temp was 74 degrees at 8:40 AM	8:45 AM	Afterhours call
7/30/09	6:52 PM	Christopher Brantly	?_	Water is leaking from ceiling it appears to be coming from TH AC unit in that room	B5252200-1	Leak			No floor or location given		Unkown
8/1/09	6:40 AM	Anna Orozco	8	Loud noise (gurgling) coming from vent on west side near Kathy Smith,	B5248597-2	Noise	·		Call came on Saturday. No noise on Monday		Afterhours call
8/4/09	11:44 AM	Martella Craig	10 &	Bring 3 large blue trash bins. One for 10 and one for 11. Confirm with Martella that there will be janitorial this weekend. Food will need to be diposed of this weekend.	B5256986-2	Janitoria)			Bins delivered		BofA request
8/5/09		Christi Eaker	6	Ceiling light out Letter of Credit Dept. over her desk	B5256739-3	Lights	8:46 AM	J3	Replaced light bulb	9:00 AM	Normal Maintenance
8/5/09	<u> </u>	Christopher Brantly	10	Coke spill in cubicle 10- 189	B5259558-2	Janitorial	8:52 AM	J2	Cleaned up spill	9:05 AM	Tenant issue
8/7/09	12:35 PM	Teresa Houchins	10	Very cold in work area AC control #FCU10-9	B5262035-2	HVAC	12:41 PM	E7	Temp at stat 73.4 space temp 74 set point is at 72	12:53 PM	No Problem
8/8/09	7:29 AM	Sarah Taylor	10	Please sweep floor in Instuction Unit area . This is a secured area see Sarah in the Mail Room for access	B5260155-2	Janitorial			Weekend call. Left message for Sunday cleaning crew		BofA request
8/10/09	3:05 PM	Teresa Houchins	10	Area very cold. AC unit #FCU10-9	B5264188-1	HVAC	3:21 PM	E6	Temp is 71 raised to 73	3:30 PM	Normal Maintenance
8/11/09		Barbara Rogers	9		B5264730-2	Plumbing	8:35 AM	E7	Nothing wrong	8:50 AM	No Problem
8/11/09	10:51 AM	Leticia Flores	3	Team 1 and Team 2 are too warm	B5265701-1	HVAC	11:04 AM	E6	Checked rooms reported to E1. E1 made adjustments	11:25 AM	Construction related

		T	т—	T	Т	$\overline{}$	1		_		
8/12/09	10:25 AM	Leticia Flores	3_	North Carolina Training Center is too cold Class is in the room	B5267312-1	HVAC	10:28 AM	E7	72 temp No thermostat and no graphics. E1 reports not having any zones to read	10:50 AM	Construction related
8/12/09	10:04 AM	Leticia Flores	3	Conference/Training Center is too warm	No Number	HVAC	10:11 <u>A</u> M	E7	Temp 76 in rooms No thermostat no graphics can't make adjustments called E1 he reports not having any zones to read.	10:51 AM	Construction related
8/13/09	8:10 AM	Leticia Flores	3	Small break out room area Hvac needs to be set at 68 degrees max today for blood drive	B5268596-1	HVAC	8:28 AM	E1	Room temp 75, Set at lowest setpoint 72	8;36 AM	BofA request
8/13/09	10:15 AM	Anna Orozco	8	Water pressure issue. The building is working on it. Water is coming up in all the toilets on 8. The toilets have not overflowed yet but people are still using them and are uncomfortable with the water rising while they are using them.		Plumbing	10:24 AM	E 7	Reports running a cable threw the drai to unclog. Found tissue and waste, J3 mopped up	11:42 AM	Normal Maintenance
				mens restroom urinals have anextremely strong smell and water pressure					Smell is because someone urinated on the floor. Whaer pressure is ok, all urinals and		
8/13/09 8/13/09	1:26 PM 1:30 AM	Sarah Taylor Leticia Flores	10 3	low Texas and Florida room are hot	B5269484-1 B5269491-1	Janitorial HVAC	1:31 PM 1:33 PM	E6 & J2 E6	toilets are flushing ok Room temp 77, no graphics or readings on computer	1:40 PM 1:52 PM	Tenant issue Construction related
8/15/09	12:15 AM	Brenda McElyea	25	AC is blowing hot air	B5270357-2	HVAC	8:30 AM	E1	AC was off on weekend, and kicked on there this morning ok	8:44 AM	Afterhours call
8/15/09	12:48 AM	Elayn Ruthart	11	Please service ladies and mens restrooms, very unpleasant odor is present in both and can be detected in our work area	B5271225-2	Odor	8:30 AM	E 7	deodorizers in restrooms low and AC was off	8:44 AM	Afterhours
8/17/09		Brenda McElyea	25	Light out over a des see Brenda McElyeak	B5264828-2	Lights	8:20 AM	JЗ	Replaced 3 light bulbs	8:35 AM	Normal Maintenance
8/17/09	9:13 AM	Leticia Flores	3	Warmin the Florida and Texas rooms in the conference training center	B5272124-2	HVAC	8:39 AM	E7	Reports Brian with Whiting Turner was there checking problem	9:47 AM	Construction related

	· · · · · ·	<u> </u>	Γ	Ladies restroom 1st 2	 _	<u> </u>		1	T	<u> </u>	1
1	ł	i	l	stalls have back up, clean		ŀ	i	E7, E4 &	1	l	1
8/17/09	10.32 AM	Anna Orozco	8	up needed	B5272342-3	Plumbing	10:37 AM	J4	Unstopped toilets and J4 cleaned up	10;55 AM	Duplicate call
- 0,777.00	70.02.7 (17)	741114 010200	<u> </u>	Ladies restroom 1st 2	DOL! 20 12 0	Trumbing	10.01 7 (17)	-	onotopped toheto and on occurred up	10.007411	Duplicate can
İ	ľ		Ī	stalls have back up, clean	i						Normal
8/17/09	10:44 AM	Anna Orozco	8	up needed	B5272342-4	Plumbing	11:02 AM	E6	Someone had already taken care of	11:05 AM	Maintenance
5711700	10,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					,		 		11.001.111	THOUSE TO STATE OF
		ļ						i			
ŀ			İ	Requesting additional							
1	j	}		janitorial services to	,			J	1	J	1
				deliver 3 large blue waste			•				
				bins to each hub due to catering services							
				happening from Friday				,			
		1		thru Tuesday. Need					·		
				delivered 8/21/09 and	<u> </u>			ļ	i		
		İ		picked up on 8/25/09.							
ļ				Pleas contact Martella to	İ			i			1
	Ì			discuss the cleaning							
		Martella	10 &	services for the events	DEOZEODE 4		0.40 414	<u> </u>	han han a top our of an design and a de-	0.45 484	lo-10
8/19/09	9:03 AM	Craig	11	over the weekend.	B5275925-1	Janitorial	9:10 AM	J2	has been informed and will talk to J1	9:15 AM	BofA request
					!			•	·		
				Need to have janitorial				1			
				services for the following	i l] .			
1				days this Friday 8/21 from		· ·					
	•			8:30pm until 10:30pm, Sat 8/22 from 9:00am			,	i			
		:		untill 9:00pm, Sun 8/23	Í				·		
ļ	l		l	also until 11:00am and		- }					}
1		Martella	10 &	Mon 8/24 8:30pm until	'	1					
8/21/09	12:49 AM	Craig	11		B5277638-2	Janitorial	8:18 AM	J2	Already taken care of	8:30 AM	BofA request
		Deona		Light out in hallway above							Normal
8/21/09	12:50 AM		28	entry to the office	B5277846-2	Lights	8:18 AM	J3	Replaced light	8:25 AM	Maintenance
0/04/05		Elayn		T115 44 847	DE004400 4	1040	2.40 DM		Constant COS and a division of	2.EE DM	Construction
8/24/09	3:06 PM	Ruthart	11	Too cold in 11-017	B5281486-1	HVAC	3:42 PM	E6	Room temp 69.5, made adjustment	3:55 PM	related
]		F1		Too cold in northwest]	J	j]		Comotomication
8/27/09		Elayn Ruthart	11	corner cubes 11-120 thru	B5286923-1	HVAC	12:15 PM	E6	Adjusted temp	12:30 PM	Construction related
0/2//08	12.03 F W	i valiaj i	- 11	11-12/	00200320-1	110/10	12.10114		, agained temp	12.001 191	- CIACOA
		ļ		Please AC on tomorrow					. 		
		Brenda	25 &	night 8/28/09 on 25 and	` !						
8/27/09	12:12 PM		26		B5286934-1	HVAC	12:15 PM	E1	Put run times in computer	12:30 PM	BofA request
											

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 102 of 122 PageID 688

	,	I 		1					T70 E		10
9/2/09	2:22 PM	Teresa Houchins	10	Freezing in area near 10- 195 southeast side	B5294689-1	HVAC	2:28 PM	E6	Temp was 73.5, set point 73.5, changed set point to 74.5	2:40 DM	Construction
912109	2:22 FM		10		DOZS400S-1	TVAC	2.20 PW	 	Politic 14.5	2:40 PM	related
9/3/09	12:26 AM	Irma Ramirez	6	Need ceiling lights replaced Cube 625B	B5290341-2	Lights	8:34 AM	J3	Replaced lights	8:50 AM	Normal Maintenance
3/3/03	12.20744	1 Carring 2		Elevator lobby lights out	D02303-71-2	Ligitus	0.047(0)		Treplaced lights	0.50 AIVI	Maititetiarice
	1	Barbara		please replace burned out]	•		1		Normal
9/4/09	12:51 PM		9	bulbs	B5297932-1	Lights	12:52 PM	E5	Fixed lights	1:26 PM	Maintenance
		Elayn						 			Construction
9/8/09	3:48 PM	Ruthart	11	Too cold in 11-028	B5280374-3	HVAC	3:50 AM	E7	Adjusted temp	4:06 PM	related
		Teresa		Too cold in cube 10-195			 	†			Construction
9/8/09	1:51 PM	Houchins	10	southeast side	B5299638-1	HVAC	2:05 PM	E7	7-Z1 SPCO is reading 71.2 east side of 10	2:15 PM	related
				Ladies restroom please		·					
9/8/09	12:39 PM	Anna Orozco	8	clean up human waste	B5299888-1	Janitorial	1:03 PM	J2	Cleaned up	1:28 PM	Tenant issue
	i '			AC blowing warm air see			ļ				
0140/00	5-20 DIA	Brenda	0.5	Brenda McElyea on which		18/40	D-22 A14		NA/td a-II A a successful	D-05 A44	Afterhours
9/12/09	5:32 PM	McElyea	25	unit	B5300886-2	HVAC	8:32 AM	E1	Weekend call Ac was off	8:35 AM	call
9/12/09	8:58 AM	Teresa Houchins	10	Too cold in team room 10- 035	B5305585-2	HVAC			Still having computer problems		Construction related
31 12103	0.00 AN	Leticia		Texas and Florida room	D0000000-Z	TIVAO		-	Other having compater problems		Construction
9/15/09	3:08 PM	Flores	3		B5306881-4	HVAC			Still having computer problems		related
				Water dripping from		,		<u> </u>	Having a meeting on 22 and someone		
			,	ceiling near kitchen it is]			ļ	turned on the ice machine that's broke.		}
		ReneE		coming from floor above	1				Water from drain line is dripping, turned off		Cause by
9/16/09	8:11 AM	Jones _	21	them	B5309892-2	Leak	8:30 AM	E7	ice machine	9:09 AM	other tenant
				Repair leak in nortwest							
		Elayn		corner in the walkwat					Repair FCU that is leaking already talked to		Normal
9/16/09	12:42 PM	Ruthart	11		B5310640-2	Leak	2:22 PM	E7 & E6	Bud	2:30 PM	Maintenance
		1		Client Immigr. Dept.				i	1		1
		, ,		please attach 2 light				ļ	<u> </u>		
9/17/09	3:47 PM	Sandra Richards	6	covers they have come completely off	B5304818-2	Lights	3:51 PM	J3	Replaced lense covers	4:08 PM	Normal Maintenance
9/1/109	3,47 PIVI	Richards	° 		D0304616-2	Lights	3.31 FW	- 33	Replaced letise covers	4.06 FIVI	IVIAII ILEI IAI ICE
			1	Conference/Training					Ì		
		J	- 1	Center GA & MD the window AC is making		J		1]		1
		Leticia	i	loud noise and meeting is			•		New system unit is not rattling but humming		Normal
9/17/09	11:44 AM		з		B5312228-2	HVAC	11:36 AM	E7 & E1	loud from fan	11:36 AM	Maintenance
		Rachelle	 	Clean up spill in break							Normal
9/17/09		Raasch	26		B5312954-1	Janitorial	11:26 AM	J2	Cleaned up spill	11:55 AM	Maintenance
				Warm in corporate real							†
· · · · · · · · · ·		- 1	}	estate dept northwest)]	}]		Normal
- 1	i			corare achi nominicar		1					111011111

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 103 of 122 PageID 689

9/20/09	11:48 AM		21	One panel of ceiling is flickering west side	B5309844-2	Lights	8:40 AM	J3	Weekend call, sent J3 to look for it	9:24 AM	Normal Maintenance
9/20/09	5:46 PM	Margaret Hiser	11	2nd Stall won't flush in ladies rest room	B5310885-2	Plumbing			Weekend call was fixed by Sunday janitorial		Normal Maintenance
9/23/09	12:31 PM	Anna Orozco	8	Too cold at southest side see Robin Haddock	B5319045-2	HVAC	1:35 PM	E 5	Made adjustments on computer	1:55 PM	Normal Maintenance
9/23/09	1:46 PM	Doreen Honza	32	Mens room urinal has been running all a.m. afraid it will run over	B5319599-1	CBRE	1:40 PM	E6_	Turned back over to Ron with CBRE engineering		CBRE
9/24/09	12:17 AM		26	Clean up spill in break room	B5312954-2	Leak	8:24 AM	J2	Night crew cleaned up but found that water is coming from ice machine. Turned over to CBRE engineering	8:35 AM	Tenant issue
9/24/09	8:15 PM	Raymond Glenn	21	Too cold in northwest corner	B5319235-2	HVAC			Afterhours call		Afterhours call
9/24/09	8:21 PM	Christopher Brantly	9	Air needs to be turned off or redirected air is causing this person to get cold	B5319729-2	HVAC			Afterhours call		Afterhours call
9/28/09	2:31 PM	Leticia Flores	3	Texas-Florida Conference Rooms too cold	B5325227-1	HVAC	2:34 PM	E 7	Temps are in range at 72	2:55 PM	Construction related
9/29/09	6:14 PM	Joseph Begue	25 & 26	We will be working extended hours9/28 and 9/29 and will need HVAC system on until 9:00 PM both days	B5325553-2	HVAC			Afterhours call was too late to provide by the time call came in		BofA request
9/29/09	6:18 PM	Anna Orozco	8		B5325919-2	HVAC		-	Afterhours call	,	Afterhours call
9/30/09		Barbara Rogers	10	East side check temp too cold	B5327149-2	HVAC	9:35 AM	E7	Made adjustments on computer	9:52 AM	Construction related
10/1/09	9:26 AM	Martella Craig	11	Very cold on floor in area of cube 11-074	B5319219-1	HVAC	9:50 AM	E6	Whole floor 74-75 tenant not even in state informed by enant behind cubicle	10:01 AM	Construction related
10/5/09		Leticia Flores	3	Texas and Florida rooms too hot	B5332922-1	HVAC	9:26 AM	E7	Temps were 71	9:33 AM	Construction related
10/5/09	12:10 PM	Teresa Houchins	10	Too cold in team room 10- 035	B5333103-2	HVAC	12:27 PM	E4	Made adjustments on computer	12:39 PM	Construction related

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 104 of 122 PageID 690

				Southwest section work		_					
	,			area is too cold temp at				ŀ	1		
	1			64 degrees usually 70							•
10/5/09	12:44 DM	Luella Telker	29	degres is normal don't make it too hot	B5333393-1	HVAC	12:27 PM	E6	Made adjustments on computer	12:45 PM	Normal Maintenance
10/3/03	12.11 [19]	Luciia Teikei	23	it is 64 degrees on the	D0000090-1	110/10	12.21 - 14		Iwade adjustments on computer	12,45 PW	Waintenance
]		1		weat end. When I arrived							
]		Stephen		this morning it was 63				i			Normal
10/6/09	11:30 AM	Marshall	29	degrees	B5333227-1	HVAC	12:27 PM	E6	Made adjustments on computer	12:51 PM	Maintenance
		[One of the ceiling tiles fell and broke all over the			·				
				floor and on some chairs					•		
]		Leticia		and table. Please clean	ĺ			ſ	E7 working on that; J1 reports clean-up is	ĺ	Normal
10/7/09	7:52 AM	Flores	3	up broken tiles	B53358778-3	Janitorial	8:18am	E& & J1	done	9:00 AM	Maintenance
j .		J J		One of the ceiling tiles fell and broke all over the	j			})]]]
				floor and on some chairs					•	1	1
	1	Leticia		and table. Please clean		,			E7 working on that; J1 reports clean-up is	ł	Normai
10/7/09	7:52 AM	Flores	3	up broken tiles	B53358778-3	Janitorial	8:18am	E& & J1	done	9:00am	Maintenance
			_	Need all HVAC vents							Normal
10/7/09	10:14 AM	Alma Walling	6		B5336318-2	Janitorial	<u></u>	J1			Maintenance
10/7/09	10:14 AM	Alma Walling	6	Need all HVAC vents cleaned	B5336318-2	Janitorial		J1	Seduled fo weekend		Normal Maintenance
10///03	10.1-77481	7 dilizi Vizini g		Need training room	100000010 2	Carnena			Training room vacuumed on 10/09/09		Normal
10/7/09	10:14 AM	Alma Walling	6		B5336318-3	Janitorial	10:15 AM	J2	reported by J2		Maintenance
				Need training room					Training room vacuumed on 10/09/09		Normal
10/7/09	10:14 AM	Alma Walling	6		B5336318-3	Janit <u>orial</u>	10:15 AM	J2	reported by J2		Maintenance
10/8/09	10:35 AM	Leticia	3	N. Carolina Conf. room is too warm	B5336379-1	HVAC	10:35 AM				Construction related
10/0/08	10.35 AIVI	Lintes	-	Stall #3 in ladies RR has	D0000019-1	HVMO	10.33 ANI				Normal
10/8/09	10:25 AM	Anna Orozco	8	*	B5337885-2	Plumbing		E6	unclogged toilet	11:09am	Maintenance
				Stall #3 in ladies RR has							
	45			over flown request for]	·	-1415			Normal
10/8/09	10:25 AM	Anna Orozco	8	clean-up	B5337885-3	Plumbing		E4 &J2	unclogged toilet and cleaned up		Maintenance

		 									
10/9/09	2:56 AM	Luella Telker	29	AC vent along entire west wall are producing hot air on a continual basis instead of cold. Temp is 4 degrees warmer on this side is very uncomfortable	B5313710-2	HVAC	8:18 AM	E4	Afterhours call, air compressor went down during night	8:18 AM	Afterhours call - Equipment failure
10/9/09	10:14 AM	Suzanne Payne	8	to warm on the northeast side of floor	B5337797-1	HVAC	10:33 AM	E6		}	Normal Maintenance
10/9/09	10:14 AM	Suzanne Payne	8	to warm on the northeast side of floor	B5337797-1	HVAC	10:33 AM	£6	Made adjustments on computer		Normal Maintenance
10/10/09	11:01 AM	Anna Orozco	8	Ladies RR 2 toilets overflowing	B5339431-1	Plumbing	11:14 AM	CBRE~Ro n Murray	Turned over to CBRE		CBRE
10/10/09	11:01 AM	Anna Orozco	8	Ladies RR 2 toilets overflowing	B5339431-1	CBRE	11:14 AM	CBRE~Ro n Murray	Turned over to CBRE		CBRE
10/10/09	11:01 AM	Anna Orozco	8	Ladies RR clean up is needed due to 2 toilets overflowing	B5339431-2	Plumbing		E4 & J2	unclogged toilets and cleaned up		Normal Maintenance
10/12/09	10:12 AM	Alma Walling	6	floor need to be treated for roaches	B5336318-1	Terminix			Terminix was sent to floor to treat area		Normal Maintenance
10/12/09	10:12 AM	Alma Walling	6	floor need to be treated for roaches	B5336318-1	Terminix			Terminix was sent to floor to treat area		Normal Maintenance
10/12/09	9:18 AM	Kris Emmert	29	cold call	B5340660-2	HVAC	9:24 AM		Construction is going on that floor there is no way to control the air nothing we or CBRE can do		Construction related
10/12/09	9:18 AM	Kris Emmert	29	coid call .	B5340660-2	HVAC	9:24 AM		Construction is going on that floor there is no way to control the air nothing we or CBRE can do		Construction related
10/13/09		Anna Orozco	8	Too warm on northwest side of building (elm street)	B5341097-1	HVAC	10:15 AM	E7	Made adjustments on computer		Normal Maintenance
10/13/09	10:11 AM	Suzanne Payne	8	N.E. corner too hot	B5341276-2	HVAC	10:17 AM	E6	changed unit from heating to cool	1:30 PM	Normal Maintenance
10/13/09		Martella Craig	11	hot	B5341283-1	HVAC	4:18 AM	E5			Construction related
10/13/09	4:33 PM	Teresa Houchins	10	cold call	B5341350-1	HVAC	4:36 AM	E5			Construction related
10/13/09	7:09 PM	Teresa Houchins	10	cold call	B5341865-1	HVAC	9:01 AM	E4			Construction related

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 106 of 122 PageID 692

404050	3:24 PM	Leticia	3	Georgia and Maryland	DS040047.0	HVAC	3:26 AM	E6		4.40 114	Construction
10/13/09	3:24 PM	Flores	3	conference rooms too hot		HVAC	3;26 AIVI	- 50	<u> </u>	4:18 AM	related
	ľ	Rodney	ł	hallway door outside mail room is not closing	į	Doors &		ł	ľ		Construction
10/13/09	8:26 PM	Foreman	10	completely.	B5342394-1	Locks	8:20 AM	E7	Door leaning on side (E7)	9:14 AM	related
10/13/09	8:26 PM	Rodney Foreman	10	hallway door outside mail room is not closing completely.	B5342394-1	Maintence	8:20 AM	E7	Door leaning on side (E7) 10/19/09 E7 contacted Ron Murray at 1:54pm to take care of the problem	9:14 AM	Construction related
10/13/09	5:29 PM	Barbara Rodgers	9	Men's RR Urnial #3 is running and stall #1 toilet needs to be repaired	B5342578-1	Plumbing	9:04 AM	E4	work to be done by CBRE engineers A5 tried to contact Ron Murray (CBRE). Ron called back at 11:23 to report problem taken care of	11:23 AM	CBRE
				Too warm on northwest		<u>_</u>					
10/14/09	10:11 AM	Anna Orozco	8	side of building (elm street)	B5341097-1	HVAC	4:25 AM	E5	changed set point from 74 to 72 degrees		No Problem
10/14/09	8:16 AM	Doreen Honza	32	Hot call	B5342937-1	HVAC	9:45 AM	E7	window unit is putting out 90 degrees set point is 73 and cooling E7 compressor went off and caused window unit to go into heat. Got compressor back on	4:32 AM	Normal Maintenance
40/44/00	9:37 AM	Christopher	29	Cold cubicle 29.079	B5343063-1	HVAC	9:37 AM	E7	this floor is under construction	10:10 AM	Construction related
10/14/09	9:37 AM	Larson Leticia	29	clean up spill in	150343003-1	HVAC	9.37 AIVI		this floor is under construction	TO: TO AIVI	related
10/14/09	9:33 AM	Flores	3	breakroom coffee room	B5343095-1	Janitorial	9:43 AM	j 4	Cleaned up spill	10:15 AM	Tenant issue
10/16/09	11:55 AM	Teresa Houchins	10	cold call Randle team room Zone VAV10	B5341609-2	HVAC	12:40 PM	E5	72 adjusted to 74 degrees on computer		Normal Maintenance
10/16/09	7:49 AM	Teresa LaMere	21	too cold	B5346369-1	HVAC	8:04 AM	<u>E</u> 7			Normal Maintenance
10/17/09	1:06 PM	Leticia Flores	3	Faucet in breakroom is loose	B5334427-2	Plumbing	1:22 PM	E6	Tightened sink fixture on the 3rd floor		Normal Maintenance
10/17/09	1:06 PM	Leticia Flores	3	Faucet in breakroom is loose	B5334427-2	Plumbing	1:22 PM	E6	Tightened sink fixture on the 3rd floor		Construction related
10/19/09	1:42 PM	Matt Olson	26	too cold construction lending dept.	B5349209-1	HVAC	1:48 AM	E5	67 degrees adjustments made after 30 mins. temp was 71 talked to Matt Olson he said temp. is now okay.		Normal Maintenance
10/19/09	2:10 PM	Leticia Flores	3	Too cold in TX. FL. Room	B5349223-3	HVAC	2:15 AM	E5			Construction related
10/20/09	10:14 AM	Cara Edwards	18		B5350041-1	HVAC	10:23 AM	E6	E6 reports compressor was out temp is now 71 degrees	10:36 AM	Normal Maintenance
10/20/09	10:15 AM	Deona Vargas	28	cold	B5350090-1	HVAC	10:27 AM	E7	Just got compressor started	10:45 AM	Normal Maintenance

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 107 of 122 PageID 693

		1			<u> </u>		<u> </u>	-			Normal
10/20/09	9:44 AM	Anna Orozco	8	entire floor to cold	B5350179-1	HVAC	9:53 AM	E7.	Temp is 69 Compressor shut down	10:26 AM	Maintenance
				cube 21.062 and . neighbors have a lot of cold air coming thru the			, .				
10/20/09	9:48 AM	Susan Sparks	21	wall vents and it is too cold	B5350190-1	HVAC	9:52 AM	E6	Temp is 73 Compressor shut down	10:20 AM	Normal Maintenance
10/21/09	12:02 PM	Teresa Houchins	10	cold	B5348279-1	HVAC	12:30 PM	E7	72 degrees Brian informed E7 that temp was okay	2:47 PM	Construction related
10/21/09	1:59 PM	Cara Edwards	18	cold	B5352236-1	HVAC	1:59 PM	E7		2:30 PM	Normal Maintenance
10/21/09	2:02 PM	Ruby Taylor	3	cold in the copy center	B5352607-2	HVAC	2:30 PM	E5	69.5 degrees reset to 70.1	2:43 PM	Construction related
10/22/09	8:29 AM	Suzanne Payne	8	Too hot on entire floor	B5341276-4	HVAC	8:30 AM	E7		10:17 AM	Normal Maintenance
		Barbara		A REPEAT issue manager is requesting air flow be turned off since it appears that nothing else			;		:		Construction
10/22/09	7:55 AM	Rodgers	10	has worked.	B5353337-1	HVAC		E7		8:21 AM	related
10/23/09	10:05 AM	Leticia Flores	3	N. Carolina Conf. room is too cold	B5354882-4	HVAC	10:05 AM	E6	64.05 no graphics on floor report to E1	10:23 AM	Construction related
10/26/09	1:15 PM	Leticia Flores	3	Too cold in TX, FL. Room	B5356903-1	HVAC	8:17 AM	E7			Construction related
10/26/09	1:16 PM	Leticia Flores	3	Georgia room's interior door isn't staying open as it should a door stop is needed and repair	B5356903-2	Doors &	8:27 AM	E7	re-directed at 9:07 am; 9:30 contact Flores to inform that E1 is taking care of the problem	9:30 AM	BofA request
10/26/09	12:48 PM	Anna Orozco	8	too cold in Ed Hamby's office	B5357682-1	HVAC	12:49 PM	E7			Normal Maintenance
10/26/09	2:35 PM	Brenda McElyea	26	cold on floor side that faces Griffith street	B5357697-1	HVAC	2:22 PM	E7			Normal Maintenance
10/27/09	7:36 AM	Leticia Flores	3	Very cold on entire floor	B5358497-1	HVAC	8:03 AM	E7			Construction related
10/27/09	7:51 AM	Leticia Flores	3	Very cold on entire floor	B5358497-1	HVAC					Duplicate call
10/28/09	10:49 AM	ReneE Jones	21	Water leaking down in the corner of the Corporate Security Dept	B5360532-2	Leak	10:50 AM	J2, E1, E6 & E4	All working on leak		Duplicate call

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 108 of 122 PageID 694

		Freda	T	Water leaking froma light	Γ		<u> </u>	J2, E1, E6			Caused by
10/28/09	10:51 AM		26	fixture	B5360576-4	Leak	10:54 AM	& E4	All working on leak		other tenant
		Buzzy Don		Toilets in mens restroom	<u> </u>					*	Normal
10/29/09	5:29 PM	Brown	32	overflowing	B5363049-1	Plumbing	5:30 PM	E5		6:00 PM	Maintenance
		Elayn									Construction
10/30/09	2:17 PM	Ruthart	11		B5360662-2	HVAC	2:30 PM	E5			related
		Leticia	١ ـ	Too cold in Training and							Construction
10/30/09	1:19 PM	Flores	3		B5363755-2	HVAC_	1:20 PM	E1			related
11/2/09	9:37 AM		١.	Texas/ Florida room still no	B5365528-1	limbto	9:37 AM	(12)		0.27	Normal Maintenance
11/2/09	9:37 AW	L.Flores	3	lights	JB5363326-1	Lights Doors &	9:37 AM	(J3)	reports lights have been taking care off	9:37 AM	Normal
11/3/09	12:10 PM	L.Flores	3	key stuck in door Latecia	B5366717-2	Locks	11:08 AM	(E6/(E7)	reports key has been taken out of door	12:29 PM	Maintenance
11/0/03	IZ.IO FIVI	Licioles	-3-	key Stuck in Goor Lateria	50000717-2	LOOKS	11.00 AW	(10)(17)	reports key has been taken out of door	12.25 101	Normal
11/3/09	10:18 AM	L.Flores] з	cold	B5367519-3	HVAC	10:18 AM	(E6)	reports temps to (E1) to make adjust ments	10:18 AM	Maintenance
									reports temp at 74 NW ,Wset at 75, already at		
11/3/09	3:00 PM	B.McEylea	26	cold	B5368170-1	HVAC	3:02 PM	(E5)	room set point	3:02 PM	No Problem
									reports already working on fl/made adjust 69 to		Normal
11/3/09	3:20 PM	B.McEylea	26	Cold	B5368419-2	HVAC	3:40 PM	(E5)	72	4:02 PM	Maintenance
				ladies restroom over					reports some did #2 on floor in bath room/ now		
11/3/09	4:30 PM	B.McEylea	26	flow/clean up	B5368509-1	Plumbing	4:06 PM	(E6)/ (J4)	cleaned up	4:30 PM	Tenant issue
					5 5554000 0	District to			reports taking care water coming from ac		Normal
11/5/09	12:00 PM	B.McEylea	26	leak	B5371008-2	Plumbing	12:38 PM	(E6)	unit, unit no longer leaks	12:58 PM	Maintenance
11/6/09	10:00 AM	R.Taylor	3	lights out	B5372439-2	Lights	10:00 AM	(12)	reports replacing lights on the 3rd floor	10:44 AM	Normal Maintenance
11/0/08	10:00 AM	R.Taylor	3	ngnts out	D331 2435-2	Ligitis	10:00 AM	(J3)	reports leak to Wayne cbre, drinking fountain&	10:44 AW	IVIAII ILEI IAI ICE
11/9/09	2:00 PM	A.Orozco	8	water leak	B5375179	Plumbing	2:00 PM	(ES)	coffee machine	2:27 PM	CBRE
	2.00 1 111	7 11010200		Tracer real.			2.00	\	reports temp is between 72 and 75 ,at room		
11/12/09	3:12 PM	N.Taylor	18	hot	B5378717-2	HVAC	3:12 PM	(E5)	temp	3:32 PM	No Problem
11/12/09	1:00 PM	L.Flores	3	stains on window	B5379088-5	Janitorial	1:00 PM	(J2)	reports crew was cleaning windows	3:00 PM	No Problem
				- -			,		68 at the window/70 at desk.reports to (E1) to		Normal
11/13/09	7:54 AM	L.Flores	3	cold	B5379711-2	HVAC	8:43 AM	(E4)	make adjust.	8:43 AM	Maintenance
									tenant are moving boxes around/temp 72/73		
11/13/09	3:22 PM	N.Taylor	18	hot	B5380099-2	HVAC	3:22 PM		temp is at room temp	3:32 PM	No Problem
				ļ					adjusted set point on comp.for FCU11-15,11-14,		Normal
11/16/09	12:32 PM	M.Craig	11	cold	B5381629-1	HVAC	12:32 PM	(E5)	to 74	1:00 PM	Maintenance
444000			_ [75004600	1540		(=a)			Construction
11/16/09	9:28 AM	L.Flores	3	cold	B5381686-2	HVAC	9:28 AM		made adjust. On comp.	9:28 AM	related
11/16/09	11.40 444	N C-lababar-		cold	B5382064-2	HVAC	11:49 AM		replaced prematic valve, changed set pointfrom 72-74	12:04 PM	Normal Maintenance
11110109	11:49 AIVI	N.Salahshour	29	colu	00002004-2	UAMO	11:49 AIVI	(12)	12-14	12:04 PIVI	Iviali iteliarice

BANK OF AMERICA WORK ORDERS

					· • · · · · · · · · · · · · · · · · · ·	,		.			
444700			_		D5074474.0				talk to larry to see if he would like for PBM to stock restrooms with sanitizer or not. Larry		
11/17/09	11:14 AM	<u> </u>	8	restock	B5374474-2	Janitorial	11:14 AM	(J1)	respondedd he will get back next week.	11:21 AM	BofA request
11/17/09	11:24 AM	G.Shields	18	cold	B5380106-1	HVAC	11:24 AM	(E5)	reports no change allready in range	11:40 AM	No Problem
11/17/09	8:46 AM	L.Flores	3	cold	B5383275-2	HVAC	8:46 AM	(E7)	reports this problem to (E1) to make adjust. (E6) reports temp 68	8:46 AM	Construction related
	İ	i						1	adjust the set point for FCU-16 from FCU-1from		Normal
11/17/09	12:00 PM	A.Orozco	8	cold	B5383688-1	HVAC	12:00 PM	(E5)	72 - 74F	12:00 PM	Maintenance
11/17/09	2:48 PM	L.Telker	29	hot	B5384376-2	HVAC	2:48 PM	(E5)	reports temp is 81, reports temp to (E1) to make adjust.	2:48 PM	Normal Maintenance
11/19/09	1:30 PM	R.Taylor	3	cold	B5385727-1	HVAC	1:33 PM	(E4)	reports to temp to (E1) , make changes in comp. 68.5	1:35 PM	Construction related
11/19/09	8:33 AM	L.Flores	3	cold	B5386855-1	HVAC	8:33 AM	(E7)	reports temp was 68, no access to comp.informedc (E1)	8:33 AM	Construction related
11/19/09	11:48 AM	C.Edwards	18	cold	B5387238-1	HVAC	11:48 AM	(E6)	report temp was at 69 degrees/report to (E1) to adjust in comp.	12:08 PM	Normal Maintenance
11/20/09	9:35 AM	Angela	21	no hot water	B5387167-3	Plumbing	9:00 AM	(E6) / (E4)	(E6) reports to (A2)working on the water issue for the bank floors waiting til (E4) returns from vacation	9:35 AM	Construction related
- 1,120,130	3105 F H.F.							1=0,7, 1= 1,7	reports air compressor was off, now on, temp		Normal
11/23/09	8:05 AM	L.Flores	l 3	cold	B5389913-1	HVAC	8:05 AM	(E7)	was 65.3	8:55 AM	Maintenance
11/23/09	10:21 AM			cold	B5390332-1	HVAC	10:21 AM	(E7)	made a vent adjust.over desk	10:21 AM	Normal Maintenance
11/24/09	8:35 AM	T.LaMere	21	cold	B5391801-1	HVAC	8:35 AM	(E7)	reports temp on fl.72,changed to 74	8:48 AM	Normal Maintenance
11/24/09	8;44 AM	B.McEylea	25	cold threw out the fl.	B5391817-2	HVAC	8:44 AM	(E7)	made adjust in comp.	9:00 AM	Normal Maintenance
11/24/09	9:30 AM	A.Orozco	8	cold	B5392035-1	HVAC	9:30 AM	(E6)	reports compressor was off, temp at 72 set point 74	10:29 AM	Normal Maintenance
11/24/09	10:00 AM	C.Williams	8	clogged toilet	B5392130-1	Plumbing	10:03 AM	(E4)	reports paper towel stuck in toilet, unclogged now	10:40 AM	Tenant issue
11/24/09	11:40 AM	L.Espinoza	18	cold	B5392281-3	HVAC	11:40 AM	(E6)	waiting on parts for compressor/unit is down	12:00 PM	Normal Maintenance
11/25/09	8:12 AM	T.Houchins	10	cold	B5393382-1	HVAC	8:12 AM	(E7)	reports making changes in comp.	8:12 AM	Normal Maintenance
11/25/09	9:57 AM	T.Houchins	10	cold	B5393382-1	HVAC	9:57 AM	(E1)	reports making changes in comp.	10:57 AM	Normal Maintenance
11/25/09	11:27 AM	A.Orozco	8	cold	B5393430-1	HVAC	11:27 AM	(E7) / (E1)	made adjust ments. (E7) reports temp is at 72middle/70 window	12:55 PM	Normal Maintenance
11/25/09	10:57 AM	L.Espinoza	18	cold	B5393760-1	HVAC	11:54 AM	(E1) / (E5)	reports temp on fl.68 to 70. reports to (E1) to make adjust.	12:55 PM	Normal Maintenance

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 110 of 122 PageID 696

BANK OF AMERICA WORK ORDERS

	T	T		 		T	<u> </u>	1	reports temp between 67/68 threwout fl.made		Normal
11/27/09	9:51 AM	S.Payne	8	cold	B5394746-1	HVAC	9:51 AM	(E6)	adjust.on pump	10:08 AM	Maintenance
1021700	3/31 VIA	3.7 ayıle	╁	rcora			3.31744	(4.0)	and an interest to the state of	10.00 AW	Construction
11/30/09	1:13 PM	E.Ruthart	1 11	cold	B5395251-2	HVAC	1:40 PM	(E4)	reports unit to (E1) to make adjust.	1:40 PM	related
11700700	11.70.7 11.7	- Text leave	 					(',	talk to tenant, inform tenant will make changes	11.15 1 1.11	Normal
11/30/09	8:08 AM	T.LaMere	21	cold	B5395610-1	HVAC	8:08 AM	(E7)	in comp.	8:08 AM	Maintenance
-1100,00	0,007,111	Taballica C	+	0014			0.001	(27)	made adjust.in comp.temp is at 73middle and 60		Construction
11/30/09	8:08 AM	L.Flores	3	cold	B5395617-2	HVAC	8:08 AM	(E7)	at window	8:08 AM	related
	0.007.87	1	 					\			Normal
11/30/09	8:26 AM	A.Orozco	8	cold	B5395679-1	HVAC	8:26 AM	(E1)	reports making changes in comp.	8:26 AM	Maintenance
	J.257.117	1.1.0.1.0.2.00	1			-		\/	, apara manng anangas maanar	01201111	Normal
11/30/09	9:10 AM	J.Hoyt	21	cold	B5395680-1	HVAC	9:10 AM	(E1)	reprots made changes in the comp.	9:18 AM	Maintenance
	57251							1-1-7	made adjust. In comp.temp70 middle and 67 at		Normal
11/30/09	8:26 AM	J.Morrison	21	cold	B5395686-1	HVAC	8:26 AM	(E1)	window	8:26 AM	Maintenance
			 					, ,			Normal
11/30/09	8:49 AM	R.Glenn	21	cold	B5395690-1	HVAC	8:49 AM	(E7)	temp is at 62.8. made changes in comp.	8:49 AM	Maintenance
								 ` ` 			Normal
11/30/09	2:58 PM	R.Glenn	21	cold	B5395690-1	HVAC	1:48 PM	(E1)	reports making changes in comp.	1:48 PM	Maintenance
			 					 ` ` ` `]	-	Construction
11/30/09	9:46 AM	M.Craig	11	cold	B5395739-2	HVAC	9:46 AM	(E4)	reports temp to (E1) to make adjust temp is 68.5	9:46 AM	related
11/30/09	8:58 AM	S.Tatlor	10	spil!	B5395752-1	Janitorial	8:58 AM	(J2)	reoprts spill has been mopped up .	8:58 AM	Tenant issue
100.00	0,50 (1,1)	Structor	 			0 (,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	0.001,417	(92)	reports temp on fl. Was 70/ (E1) made adjust. In	010011111	Normal
11/30/09	10:24 AM	L.Williams	18	cold	B5396010-2	HVAC	10:24 AM	(E1)/(E7)		10:24 AM	Maintenance
- 1100	201211111	Living to	 					(4-//(4-/			Normal
11/30/09	10:18 AM	K.Denton	21	cold	B5396028-1	HVAC	10:18 AM	(E4)	reports unit was off /now plugged back in	10:18 AM	Maintenance
	201112							 ```	reports to the 21st floor talk to tenant, made		Normal
11/30/09	11:22 AM	K.Denton	21	cold	B5396028-1	HVAC	11:22 AM	(E1)	adjust. By comp.	11:45 AM	Maintenance
			 					 			Normal
11/30/09	10:30 AM	T.Stone	29	cold	B5396038-1	HVAC	8:42 AM	(E1)	made adjust.in comp.	8:42 AM	Maintenance
					-				reports temp was 68, no access to		Construction
11/30/09	11:27 AM	M.laman	10	cold	B5396255-1	HVAC	11:27 AM	(E7)	comp.informedc (E1)	11:27 AM	related
											Construction
11/30/09	11:44 AM	B.Rogers	11	cold	B5396313-1	HVAC	11:44 AM	(E5)	reports unit to (E1) to make adjust.	11:44 AM	related
		<u>~</u> _			<u> </u>				no control over compressor/unplugged 3		Normal
11/30/09	1:28 PM	R.Taylor	3	cold	B5396525-1	HVAC	1:28 PM	(E5)	exterior units	1:28 PM	Maintenance
		-				······	7.,				Construction
12/1/09	12:48 PM	T.Houchins	10	cold	B5393382-1	HVAC	11:45 AM	(E4)	reports tried to making adjusteports to (E1)	11:45 AM	related
									reportschecked when at8:18 on 12/2/2009 area		Normal
12/1/09	6:32 PM	J.Hoyt	21	cold	B5395680-1	HVAC	6:32 PM	(E7)	was ok	6:32 PM	Maintenance
									reports we do not hav graphics for there heat	-	Construction
12/1/09	9:16 AM	L.Flores	3	cold	B5397336-1	HVAC	9:16 AM	(E7)	/ac, reports to (E1)	9:16 AM	related
									<u> </u>	***	

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 111 of 122 PageID 697

BANK OF AMERICA WORK ORDERS

12/1/09	1:30 PM	Adt Security	3	outlets are not working	B5397928-1	Electricity	1:30 PM	ADT	ADT is on property and taking care of floors.	1:30 PM	Construction related
12/4/09	11:00 AM	L.Flores	3	cold	B5402554-2	HVAC	11:51 AM	(E1) /(E4)	Divcon is working on there system at this very moment	11:51 AM	Construction related
12/7/09		S.Payne	8	cold	B5404894-1	HVAC	12:42 PM	(E5)	reports temp was at 70 change to 72	1:10 PM	Normal Maintenance
12/7/09		S.Visher	18	hot	B5405206-2	HVAC	4:54 PM	(E6)	reports temp to (E1) comp. make adjust,	4:54 PM	Normal Maintenance
12/8/09	8:11 AM	R.Useiton	10	hot	B5404548-1	HVAC	8:11 AM	(E7)	reports making adjust, to comp area 76	9:10 AM	Normal Maintenance
12/8/09	10:50 AM	R.Uselton	10	cold	85404548-2	HVAC	10:50 AM	(E5)	adjusted exterior units from 72 to 74/replaced 1 heat element	2:10 PM	Normal Maintenance
12/8/09	8:10 AM	T.Smith	29	HVAC alarm	B5404711-1	CBRE	10:00 AM	CBRE/(E1)	(E1) works with cbre to resolve issue.	10:00 AM	CBRE
12/8/09	8:22 AM	D.Peters	4	hot	B5404994-1	HVAC	10:50 AM	(E5)	reports unit was turned off/ now on/informed.L.William	10:50 AM	Normal Maintenance
12/8/09		B.Rogers	9	cold	B5405164-1	HVAC	8:09 AM	(E7)	reports temp 69 to (E1) to make adjust	8:30 AM	Construction related
12/8/09	8:04 AM	J.Carter	6	lights out	B5406064-1	Lights	8:04 AM	(J3)	reports some lights wer changed/other have to be order	8:32 AM	Normal Maintenance
12/8/09	3:38 PM	D.Yarborough	18	hot	B5406441-1	HVAC	3:38 PM	(E7)	reports the temp is 72, made adjust. To 70	3;58 PM	No Problem
12/8/09	3:05 PM	L.Flores	3	hot	B5406787-1	HVAC	3:05 PM	(E5)	adjusted temp from 72 to 70, temp was 69.5	3:05 PM	No Problem
12/8/09	1:41 PM	J.Blair	6	dust	B5406819-1	Janitorial	1:41 PM	(12)	reports all areas in LR has been cleaned	1:41 PM	Normal Maintenance
12/8/09	8:20 AM	J.Begue	25	hot	B5407738-1	HVAC	8:20 AM	(E7)	reports made adjust. To unit	8:20 AM	Normal Maintenance
12/9/09	8:15 AM	L.Flores	3	cold	B5407902-1	HVAC	8:15 AM	(E4)	reports temp to (E1), check temp on comp. spoke w/ L.Flores	8:15 AM	Construction related
12/9/09	2:22 PM	T.Houchins	10	hot	85408271-1	HVAC	2:22 PM	(E5)	mixedtemp/T.H is hot/ J.Pain cold/ reports to (E1) make adjust.	2:22 PM	Construction related
12/9/09	10:30 AM	R.Taylor	3	cold	B5408382-1	HVAC	10:30 AM	(E4)	reports working w/Divcon on HVAC problems	10:30 AM	Construction related
12/10/09	9:00 AM	J.Begue	25	hot	B5407738-1	HVAC	9:00 AM	(E7)	reports made adjust. To unit	9:00 AM	Normal Maintenance
12/10/09	10:10 AM	N.Wafer	6	cold	B5408894-1	HVAC	10:10 AM	(E7)	68 degrees,adjusted thermo. To 72	10:27 AM	Normal Maintenance
12/10/09	8:20 AM	N.Wafer	6	cold	B5411257-1	HVAC	8:20 AM		reports checking temp, reports to (E1 to make adjust.	8:20 AM	Normal Maintenance
12/14/09	8:23 AM	L.Flores	3	cold	B5413770-1	HVAC	8:23 AM	(E7)	reports temp was at 70, report to (E1)	8:23 AM	Construction related

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 112 of 122 PageID 698

BANK OF AMERICA WORK ORDERS

	<u> </u>	T -									Construction
12/14/09	3:16 PM	E.Ruthart	11	cold	B5414259-1	HVAC	3:16 PM	(E7)	can not make adjust at building standard	3:23 PM	related
12/15/09	11:36 AM	J.Nicholson	6	cold	B5416130-1	HVAC	11:36 AM	(E6)	window unit was off turned on	11:36 AM	Normal Maintenance
		1						,,		2210071111	Construction
12/16/09	8:04 AM	L.Flores	3	cold	B5417833-1	HVAC	8:04 AM	(A4)	reports engineer made adjust.	8:04 AM	related
404600	0.40.414	T			B5417853-1	HVAC	0.40 414	(4.4)		0.40.414	Normal
12/16/09	8:18 AM	T.LeMere	21	cold	B0417603-1	HVAC	8:18 AM	(A4)	reports engineer made adjust.	8:18 AM	Maintenance Construction
12/16/09	8:32 AM	J.issacs	9	cold	B5417886-1	HVAC	8:32 AM	(A4)	reports engineer made adjust.	8:32 AM	related
			1								Construction
12/16/09	8:42 AM	T.Houchins	10	cold	B5417908-1	HVAC	8:42 AM	(A4)	reports engineer made adjust.	8:42 AM	related
12/16/09	11:37 AM	J.lssacs	10	replace glass/metal	B5418386-1	Misc.	11:37 AM	(A4)	report engineer takes care of work order	11:37 AM	BofA request
404000			l	1	DE 4000EE 4	1046	4.05.514	75. 0			Construction
12/18/09	1:05 PM	E.Ruthart	11	cold	B5422355-1	HVAC	1:05 PM	(E4)	reports temp was at 70, report setting unit to 72 reports replacing the board on the wall.now	1:42 PM	related
12/18/09	1:25 PM	A.Orozco	8	board hanging	B5422490-1	Misc.	1:48 PM	(E5)	secure	1:48 PM	BofA request
		1	 	88							Construction
12/22/09	11:08 AM	E.Ruthart	11	cold	B5426415-1	HVAC	11:08 AM	(E6)	reports made adjust. To unit	11:08 AM	related
12/22/09	11:10 AM	S.Payne	8	hot	B5426453-1	HVAC	11:10 AM	(E4)	eports made adjust, to unit	11:10 AM	Normal Maintenance
									reports each engineer mad adjust. Twice		Construction
12/23/09	12:49 PM	E.Ruthart	11	cold	B5426415-1	HVAC	11:52 AM	(E6) / (E4)	checking on tenant	11:52 AM	related
12/23/09	10:52 AM	S.Parlin	6	hat	B5428247-1	HVAC	9:39 AM	(E6)	80 was the temp/made adjust. Tp perimeter unit.	9:39 AM	Normal Maintenance
1220,00	10.027 (11	0.1 4,18,1	 					()	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0.007.111	Normal
12/23/09	11:35 AM	A.Orozco	8	hot	B5428363-1	HVAC	10:53 AM	(E4)	chiller was off/ needed time to come on	10:53 AM	Maintenance
12/23/09	2:00 PM	L.Latimer	6	hot	B5428397-1	HVAC	2:00 PM	(E4)	reports unit was turned off/ now on	2:00 PM	Normal Maintenance
									reports work order to Ron Murray/informed will		
12/23/09	11:51 AM	V.Surmiller	29	refrigerator off	B5428450-1	CBRE	11:51 AM	(A5)	take of	11:51 AM	CBRE
12/23/09	3:11 PM	S.Davis	29	refrigerator off	B5428547-1	CBRE	3:11 PM	(A5)	reports to cbre/refrigerator nol onger works	3:11 PM	CBRE
12/23/09		N.Taylor		door	B5428862-1	CBRE	3:15 PM	<u> </u>	reports the door to cbre/ to contact ADT	3:18 PM	CBRE
12/23/09		E.Ruthart	11	audio equip not working	B5428884-1	CBRE	3:30 PM	(E5)	reports equipment belongs to B.O.A/there is power	4:00 PM	CBRE
				- 1				\ <u>-</u> -/	reports temp to (E1) comp. is down so cant		Normal
12/28/09	8:09 AM	L.Flores	3	coid	B5430473-1	HVAC	8:09 AM		make changes	8:09 AM	Maintenance
12/28/09	11:27 AM	S.Payne	8	cold	B5430752-1	HVAC	10:49 AM		reports the temp of 70 to (E1) to make adjust.	11:01 AM	Normal Maintenance

2603

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 113 of 122 PageID 699

BANK OF AMERICA WORK ORDERS

12/29/09	8:00 AM	L.Espinoza	18	cold	B5431940-1	HVAC	8:00 AM		reports temp on fl.63.8, (E7) reports to (E1) make adjust.	8:18 AM	Normal Maintenance
									reports temp68.8, adjust to 70 report unnit to		Construction
12/29/09	4:00 PM	J.Robbins	10	cold	B5432622-1	HVAC	4:00 PM	(E5)	(E1)	4:20 PM	related
12/29/09	12:00 PM	C.Morones	26	microwave on fl.	B5433286-1	CBRE	12:00 PM	(A5)	redirected to obre	12:00 PM	CBRE

App. 288

Case 3:11-cv-00306-O Document 45-8 Filed 11/07/11 Page 114

From:

Randy Kohana [rkohana@rakgroup.com]

Sent:

Tuesday, April 06, 2010 5:36 PM

To:


Sudderth, David L

Subject:

OMP

Attachments:

OMP- B of A ltr to David Sudderth-4-6-10.pdf; Cambridge Real Estate Consulting.pdf



Randy Kohana
President
RAK Main Place Associates L.P.
270 Lafayette Street
New York, NY 10012
(212) 245-1601 (Tel)
(212) 245-7001 (Fax)
RKohana@rakgroup.com
www.rakgroup.com

CONFIDENTIAL

BANA_Cambridge002460

App. 289

VIA E-MAIL AND FEDEX

April 6, 2010

Mr. David L. Sudderth
Transaction Director
Bank of America
Bank of America Corporate Workplace
35 North Greenvine Circle
The Woodlands, Texas 77382

Re: Lease Between RAK Main Place Associates L.P., as successor to RREEF USA Fund-II, as "Landlord" and Bank of America, N.A., as successor to NationsBank of Texas, as "Tenant", dated May 1, 1995, as amended (the "Lease"), for premises located at One Main Place, 1201 Main Street, Dallas, TX (the "Building")

Dear Dave:

We have worked exhaustively with Corporate Risk Consultants ("CRC") to address the alleged issues that they raised in connection with six (6) of the floors that are part of the Bank's premises. Subsequent to my email to you of March 30th saying that I would deal with all Worrell requests after the religious holiday we found the Worrells website (see attachment). CRC led us to believe that CRC was helping the Bank in connection with subleasing six (6) floors in the Building. However, as it turns out, CRC's sole business is to assist tenants in negotiating lease buyouts.

David Worrell called me a few weeks ago with a proposal to buyout your unused office space. As we were discussing the situation, among other comments he said "All my brother wants to do is make a lot of money on this". At the time I didn't know what to make of that comment but we have now pieced everything together.

As mentioned, we have come upon the websites and marketing pieces (see attached) of the Worrells and CRC or more accurately Cambridge Real Estate Consulting (also CRC). It is now obvious that this exercise is all about the Bank's intention of negotiating a buyout of the lease for the unused floors instead of the Worrells confirming that those floors are "safe to sublease" as they previously stated was their intention. As CRC's website clearly states, the Worrells do not engage in subleasing. Their only business is negotiating office lease buyouts.

270 Lafayette Street New York New York 10012

tel 212 245 1601

fax 212 245 7001



Mr. David L. Sudderth April 6, 2010 Page 2

In the words of the Worrells, from their website, among other things:

- 1) Work on commission only (percentage of savings).
- 2) Specialists in Negotiating Office Lease Buyouts
- 3) Find the "buttons" that will produce a positive result for the client.
- 4) Can get their clients out of their lease in 60 to 90 days.
- 5) Breaking a commercial lease is a "negative context business".
- 6) Their "boots on the ground" approach.

Additionally, John Worrell in conversations with my employees has spoken about me in a most disparaging fashion, as well as to my general manager. I cannot believe that Bank of America condones this type of behavior.

Dave, we have had a good and professional landlord/tenant relationship for 12 years without any of the issues that have arisen recently. At this point as Landlord, we will not have any more contact with the Worrells. They are not to contact us or any of our employees including without limitation, via e-mail, regular mail and/or telephone. We will be happy to communicate directly with Bank of America employees.

In summary, we are going to look to the lease between us and follow it completely, no more, no less. As previously mentioned, I am happy to meet with you "one on one" next week if you so desire.

Sincerely,

RAK MAIN PLACE ASSOCIATES, LP.

a Delaware limited partnership

By: RAK Main Ventures L.P., a Texas

limited partnership, its general partner

By: RAK Ventures Corp., a Texas

corporation, its general partner

Randy Kohana

President

CAMBRIDGE REAL ESTATE CONSULTING

SPECIALISTS IN NEGOTIATING OFFICE LEASE BUY OUTS

A surplus lease is not a real estate issue – IT IS A CASH FLOW ISSUE. Office leases are one of a corporation's largest expenses. Just one surplus lease can cripple your company and its ability to grow in a highly competitive marketplace. Negotiating a lease buy out is a unique process not understood or practiced by the real estate industry. Cambridge Real Estate Consulting not only pioneered this process – but can successfully negotiate a buy out of your surplus lease quicker and less expensively than subleasing.

A NEW SOLUTION: A PROFESSIONALLY NEGOTIATED LEASE TERMINATION

Lease termination negotiation is a specialized exercise that requires a unique and expert knowledge of real estate leases; finance and investor expectations. But most importantly, it requires years of experience in this type of negotiation.

THE SOLUTION DOES NOT FIND YOU... YOU MUST CREATE IT.

Surplus space can have great value to the landlord, which is often overlooked – even by the landlord. The landlord can earn far more for your space than you can under a sublease. They have the ability and expertise to more profitably market the property.

The challenge is to convince the landlord that it is in their interest to take back your space with a small cushion of cash now rather than leave the space vacant or have a less than desirable subtenant there.

A SUCCESSFULLY NEGOTIATED LEASE BUY OUT:

- COSTS FAR LESS THAN A SUBLEASE
- CAN BE ACCOMPLISHED IN 60 TO 90 DAYS
- ELIMINATES ALL RISK AND FUTURE LIABILITIES
- REQUIRES NO "AT-RISK" CAPITAL.

"...I just wanted to formally thank you and your firm for helping us to negotiate a truly remarkable settlement with the landlord for our Atlanta office space. In an area like Atlanta, with millions of square feet of office space vacant, this was even better than I had hoped we could achieve."

■ Hunter Lewis, CFO, Netuitive

THE TRUTH ABOUT SUBLEASING: IT'S NOT A SOLUTION

A sublease not only creates a high-risk liability - it puts you in the real estate management business. Subleasing requires that you delegate the responsibility of your company's cash drain to a real estate broker - someone who does not have any vested interest in your company.

Real estate brokers rely on local landlords for future income. Asking them to negotiate a highly discounted lease buy out with that landlord can damage a critical relationship affecting their future income.

According to a ... article, "...WHETHER BROKERS ADMIT IT OR NOT, THEY MAKE SURE THE GUY GIVING THEM THE ON-GOING BUSINESS - PROBABLY THE LANDLORD - GETS THE BENEFIT OF THE DEAL AS OPPOSED TO THE TENANT, WHO THEY'LL PROBABLY NEVER SEE AGAIN*"

*CFO Magazine, Divided Loyalties, December, 2005

3620 Preston Pointe Way, Suite 100, Atlanta, GA 30041

888.472.5656 VPSales@CCGIMAIL.COM

A Typical Lease Buy Out Negotiation Process:

:. A SITUATION ANALYSIS

We dissect your lease and all additional bills and correspondences to determine your exact future obligation including any unanticipated fees or charges. We then develop a presentation outlining our findings.

2. PRE-PROCESS PLANNING

The most important and time consuming part of the buy out process is pre-process planning. The reason for this planning is to gain knowledge of the landlord's unique financial and market position. Once given the "go ahead", we meet with the landlord to explain the situation and determine their financial, marketing, and investor issues.

3. STRATEGY DEVELOPMENT

Once understanding your lease and business situation and meeting with the landlord and determining market conditions – we work directly with you to develop a strategy that fits your budget and timing.

4. TACTICAL NEGOTIATIONS

A negotiated lease termination is not just a simple meeting to convince the landlord to let you out of a large financial obligation. It requires several tactical negotiations to find the "buttons" that will help the landlord recognize the potential gain — or at least no potential loss.

5. EXECUTE THE BUY OUT

This is the most critical and delicate part of the process. More buyouts are lost during the final legal negotiations and documentation than any other part of the process. We actively participate in this process through execution.



"...Mr. Worrell was extremely knowledgeable and effective in this (Buy Out) process. He successfully engaged our landlord in discussions that they otherwise were refusing to participate in and ultimately negotiated a termination agreement which was more favorable than the market offered at that time."

■ Sharon Kincl, CFO, Persona

FOR 23 YEARS CAMBRIDGE REAL ESTATE CONSULTING has been negotiating lease buy outs for Fortune 500 and venture capital backed companies in every major U.S. market. We have successfully negotiated over 1,200 lease buy outs for more than 100 clients saving them almost \$1.2 Billion.

We would be happy to give you a free, confidential analysis of your situation. This can give you a realistic picture of the present situation and offer several options to meet your needs whether we are engaged by you or not.

-Cambridge Real Estate Consulting earns it's compensation on contingency for the measurable value we save your company. Please call us at 888-472-5656 or email us at the address below.

DON'T WASTE ANOTHER USELESS RENT PAYMENT.

3620 Preston Pointe Way, Suite 100, Atlanta, GA 30041

888.472.5656

VPSales@CCGIMAIL.COM

NEGOTIATING CORPORATE LEASE TERMINATIONS FOR 23 YEARS CAMBRIDGE REAL ESTATE CONSULT

Cambridge Real Estate Consulting

Dear Commercial Real Estate Broker:

As Managing Director of Cambridge Real Estate Consulting, let me extend to you a "special invitation" to work with us to assist your clients in ending their surplus lease obligations. We work with brokers all over the nation giving them increased credibility with their clients while preserving their income and client relationship. We can work as an "extension" of your staff managing the disposition project under your banner. By contracting Cambridge you can:

- · Make use of the best team in the nation on your client's behalf.
- · Preserve your income on the project.
- · Stay in complete control of the process.
- · Maintain that 'all important' relationship with the landlord.
- Free your valuable time to work on more profitable assignments.
- · Most importantly enhance your relationship with your client.

I know how much time, energy and money it takes to gain a good client. Yet only one bad experience can ruin years of hard work and excellent service. A lease disposition assignment is the most likely way to have that happen. We can prevent that from happening.

- We are not Real Estate Brokers we are Financial Consultants.
- We have no future intent with your client our loyalty is to you.
- You can continue your current subleasing efforts.

Breaking a commercial lease through a negotiated settlement is a "negative-context" business. If it were fun or easy - you would do it. It also requires years of experience to do it right. Let us take on that burden. Please call us with your situation. Perhaps we can help you really make a difference.

Sincerely,

David R. Worrell, Managing Director

Call Us For A No-Cost Consultation. 5656 Click Here To Email Us 888-472-

Download Cur (*)
This is a PDF file that
we do; how we do it;
in the past.

Download Our Re This page provides a sharing their thought provided.

Download Out of This is our most read Truth About Soties with your colleagues

C

Haverty's Inc.
"You have a rare abil financially sophistical landlords. I rely on you an extension of myse forward to doing so for

Beverly Rollins Asset Manager Haverty's Furniture Ir

Netuitive Inc.

"Our situation was co remaining lease term

than this was a seculting a some title

rate Map

original to high

CAMBRIDGE REALESTATE CONSULTING

The Solution Will Not Come To You - It Must Be Created!

Sublease marketing is a passive effort to mitigate your growin financial losses. You and your broker sit and wait for someone to come to you. A Negotiated Lease Termination, on the other hand, is an active effort to get you out of the lease now for the least expense. Unfortunately, reaf estate brokers are required by law to work toward the best interests of both the tenant and the landlord making aggressive negotiations on your behalf difficult. Most tenants lack the skills and experience required to build the necessary leverage for a successful negotiation. That's why contracting an expert third party financial consultant like Cambridge will generate the best results in the shortest time frame.

Creating A New Solution: Ending Your Lease Obligations.

Negotiating a lease buy out is a specialized discipline that requires a unique and expert knowledge of real estate leases, corporate finance and accounting, investment analysis, and FASB regulations. It also requires an expert knowledge of commonly over-looked lease expenses like taxes, insurance and common area maintenance costs.

But our greatest value comes from the many years of experience in this very unique type of negotiation. In our 23 years, Cambridge has:

- Successfully negotiated the termination of over 1,250 corporate leases.
- Recovered over \$500 million in savings for our clients.
- Saved on average 68% of our clients' remaining lease obligations.
- Released our clients from all remaining lease obligations and liabilities.

How Cambridge Is Compensated.

Engaging Cambridge requires no risk and no change in current subleasing efforts. Cambridge is paid for results: Measurable, Quantifiable Results. Once engaged, Cambridge is paid a small percentage of what is actually saved on a project, between 10% and 15% depending on project complexity (optional travel expenses, which are at the client's discretion and often not necessary, are billed separately). Our earnings are contingent upon meeting the goals our clients agree to before we are contracted.

If We Don't Succeed We Don't Get Paid - Period!

Cownload Our Brechure

This is a PDF file that explains in better diwe do; how we do it; and who we have ν in the past.

Download Our References

This page provides references from past sharing their thoughts about the service provided

Download Our White Paus

This is our most read White Paper titled " About Subleaving". Please read trand sho your colleagues.

Client Quotes

a savings of over \$5 Million to our compan specialization in this field enabled them to success where other firms had already trie failed..."

James Dixon Chairman CompuCom Systems

Persona Inc.

"He successfully engaged our landlord in that they otherwise were refusing to partic ultimately negotiated a termination agree was more favorable than we ever expects

Sharon Kincl



Mr. David Worrell Cambridge Consulting Group 6000 Fraser Street, Suite 10-302 Centennial, CO 80016

Dear David:

I just wanted to formally thank you and your firm for helping us to negotiate a truly remarkable settlement with the landlord for our Atlanta office space. Based on our remaining lease obligation prior to the settlement, we recovered approximately 55 cents on the dollar, *including* your commission. In an area like Atlanta, with 28 million square feet of office space vacant, this was even better than I had hoped we could achieve. Complicating our situation was the relatively short remaining lease term of seventeen months, yet you found a way to work that to our advantage in the negotiations. Of particular significance were the "boots-on-the-ground" tactics that your Atlanta associate, Tim Sundy, employed to convince the landlord to come to the table and negotiate in good faith. Your approach to the engagement was creative and professional—and successful!

I would be happy to be a reference for prospective Cambridge clients in the future. I believe you provide an immense value at a very reasonable price in what is certainly a challenging and unforgiving commercial real estate marketplace.

Please let me know if there is anything I can do for you in the future, and be sure to contact me if you're ever in the DC area.

Regards,

Hunter Louis Chief Englancial Officer

> 12700 Sunrise Valley Drive · Reston, VA 20191-5804 Tel 703-464-1390 Fax 703-464-1388

NEGOTIATING CORPORATE LEASE TERMINATIONS FOR 23 YEARS CAMBRIDGE REAL ESTATE CONSULTING

MANAGING DIRECTOR

David R. Worrell, MCR.h, CAS

David has been the Managing Director of Cambridge since its inception, over 23 years ago.

He has been personally involved in over 700 negotiated lease buy outs ranging from \$25,000 to \$50 Million in value.



David is an officer of CoreNet, an international commercial real estate education association for 20+ years. He was a senior instructor for them for over 8 years. He won the "Top Faculty". Designation for 4 straight years.

David is a graduate of Georgia Tech and later earned his Master of Corporate Real Estate with Honors. He has been a frequent speaker on disposition strategies and has authored 2 books - "surplus Property Strategies" and Financial Analysis of Real Estate Transactions".

OUR PROFESSIONALS

- Timothy Sundy
- · Phil Skinner
- Salley Mertens, Ph.D.
- · Marshall Cochran
- John Worrell

Call Us For A No-Cost Consultation.
5656 Click Here To Email Us

888-472-


Download Our Brochure

This is a PDF file that explains in better we do; how we do it; and who we have with in the past.

Download Our References

This page provides references from passing their thoughts about the service provided.

Download Our White Paper fitted About Sublession



where $p \to 2 - 4$, and the section

14. H

Provincy Francy